

## **10.0 BUILDING 5681: STEWART CROSSING GRADER STATION**

### **10.1 Description of Existing Water Supply System**

Building 5681, the Stewart Crossing Grader Station and Building 5682, the Stewart Crossing Living Complex, are serviced by a water supply system that sources water from a 177.4 m deep well. Water is delivered to each building from the pumphouse storage building by way of underground recirculating piping. The well is located adjacent to the pumphouse storage building (Building 5690) approximately 50 m east of the maintenance garage. A public fill station is also located at the pumphouse where residents of Stewart Crossing can obtain water. A site plan is provided as Figure 5681-A in Appendix A10. The coordinates of the wellhead, as measured by a handheld GPS device, were recorded as:

- UTM ZONE 8
- Northing: 7028437
- Easting: 416194

The pumphouse storage building houses water treatment and distribution equipment consisting of an inline filter, pressure tank, water softener and a proportional feed LMI chlorine injection system. The piping for the public water fill station leaves the main system after filtration and disinfection but before the water softener. Neither the chlorination nor the softening system was operating at the time of the water system assessment. A schematic detailing the water supply system is provided as Figure 5681-B in Appendix A10. Photos of the well and water system are also included at the back of this appendix.

Additionally, there is an abandoned dug well on site located in a pumphouse just outside from the southeast corner of the property and approximately 110 m south of the deep well. This well has not been properly decommissioned, and could pose a safety risk in its current condition. The dug well enclosure, although it has a ladder, is not locked, and could be easily accessed by children.

### **10.2 Description of Existing Wastewater Systems**

Wastewater from the maintenance garage is discharged to a leach pit located east of the building approximately 33 m to the west of the deep well. The Living Complex

is served by a septic system with tank and in-ground disposal system on the east side of the building and is greater than 60 m from the well. Septic systems are shown on Figure 5681-A in Appendix A10.

### 10.3 Water Quality Results

#### 10.3.1 Water Quality Results from Previous Sampling

##### *Bacteriological*

A total of 17 samples were collected from the Stewart Crossing Grader Station water system between October 2004 and June 2005 and were tested for total coliform and *E. Coli* by Yukon Environmental Health Services using the presence/absence test method. Samples were collected from the Grader Station as well as the Living Complex. Results are tabulated in Table 5681-1 in Appendix A10. Coliform bacteria and *E. coli* were reported as absent in each of the 17 samples for which results are provided.

##### *Potability*

YTG representatives collected water samples from this system on September 29, 2004 and June 8, 2005. A sample was also collected from the Living Complex on September 29, 2004. The samples were submitted to Northwest Labs in Surrey BC and ALS Environmental in Vancouver BC for potability analyses. The results of these analyses are summarized in Table 5681-2 in Appendix A10. EBA reviewed the analytical results for comparison with the Canadian Drinking Water Quality Guidelines (CDWQG) to observe general water quality, identify and recommend additional sampling and analytical and to identify potential indicators of contamination.

- At 10.3 NTU during the first sampling event and 17.7 NTU during the second sampling event, the turbidity in samples collected from the Grader Station were above the Canadian Drinking Water Quality Guideline – Maximum Acceptable Concentration (CDWQG MAC) of 1.0 NTU and aesthetic objective (AO) of 5.0 NTU. The sample collected from the Living Complex also marginally exceeded this MAC;
- Each of the samples collected have had arsenic concentrations below the existing CDWQG MAC of 0.025 mg/L but above the proposed MAC of 0.005 mg/L;

- At 0.6 mg/L during the first sampling event and 1.48 mg/L during the second sampling event, the total iron concentration was in exceedence of the CDWQG AO of 0.3 mg/L;
- At 0.136 mg/L during the first sampling event and 0.134 mg/L during the second sampling event, the total manganese concentration was in exceedence of the CDWQG AO of 0.05 mg/L;
- Colour was reported to be 27 CU, which was in exceedence of the CDWQG AO of 15 CU;
- The water quality results indicated that all other health based and aesthetic objectives were met for the parameters analyzed;
- The water quality results indicated that the groundwater is calcium bi-carbonate type water with a pH of approximately 8.1; and,
- The hardness (as  $\text{CaCO}_3$ ) was approximately 170 mg/L and is considered hard. The high hardness indicates that the water softening system was not functioning when the water samples were taken.

#### 10.3.2 Identification of Additional Analytical Testing Required

Additional analytical for the Stewart Crossing Grader Station water system that was identified to be included during the water system assessments is detailed below:

- Total and dissolved iron, manganese, and arsenic;
- Turbidity;
- Phosphate, silicate, and total vanadium to determine the potential for an arsenic removal treatment system;
- Total organic carbon (TOC);
- Measurements in the field for total dissolved solids, conductivity, pH, and temperature.

Analytical results for these additional parameters can be used in treatment system design.

A water sample was obtained by EBA during the water system assessment on August 16 2005, and was submitted to ALS Environmental in Vancouver BC for analysis of additional parameters. These results are summarized in Table 3440-2 in Appendix A10 and the laboratory reports are included in Appendix B. Significant observations are detailed below:

- Turbidity at 8.02 NTU though lower than previous sampling events, was still above the CDWQG health based upper limit;

- Total and dissolved arsenic at 0.0108 and 0.00697 mg/L were above the proposed CDWQG MAC of 0.005 mg/L;
- Total iron at 0.923 mg/L was in exceedence of the CDWQ AO of 0.3 mg/L, however dissolved iron was below the laboratory detection limit (0.03 mg/L) indicating that the elevated total iron concentration was likely attributed to elevated turbidity;
- Total and dissolved manganese concentrations were in exceedence of CDWQG AO's at 0.14 and 0.135 mg/L respectively, indicating that elevated manganese concentrations were not related to elevated turbidity;
- Water quality results indicated no other exceedences of CDWQG MACs or AOs.

### 10.3.3 Indicators of Potential Contamination

Chloride, nitrate and nitrite concentrations can indicate impacts from surface water sources or septic waste. The chloride concentration was low and is within the normal background range for groundwater in the area. Nitrate and nitrite concentrations for this sample were also low and within the normal background range for this area. These water quality results indicate that the Stewart Crossing Grader Station water system was not under the influence of septic wastes or other anthropogenic sources of nutrients or anions at the time of sampling.

## 10.4 Conceptual Hydrogeology

The log for this well indicates that the well is completed at a depth of 177.4 m within a confined gravel aquifer. Drilling encountered mostly silt from ground surface to 100.6 m with interbedded fine and coarse-grained material to a depth of 177.4 m. The presence of a thick sequence of fine-grained material overlying the aquifer provides significant protection from surficial sources of contamination.

## 10.5 Potential Contaminant Sources

Details and photographs of potential contaminant sources observed during the site investigation are compiled in Appendix A10.

Potential contaminant sources within 30 m of the wellhead include:

- Various drums containing paint, toluene, and other unknown chemicals within 15 m of the well;
- Creosote treated timbers at 15 m; and
- Various industrial activities occurring around the well.

In addition, a tar storage tank is located 45 m away from the wellhead. There is an underground fuel storage tank (UST) located approximately 40 m from the well. The closest portion of a septic system to the wellhead is a septic leach pit located 33 m away.

#### 10.5.1 Spills Records and Contaminated Sites Search Results

The Government of Yukon Environmental Programs Branch and Environment Canada Environmental Protection Branch did not identify any recorded spill events or contaminated sites issues for this site or neighbouring sites.

### 10.6 Identified Water System Deficiencies and Associated Risk

#### 10.6.1 High and Medium Risk Deficiencies

High and medium risk deficiencies observed during this study include:

- Poor surface completion of the well. Due to insulation surrounding the wellhead it was not possible to determine the exact stick up of the well casing, however it is unlikely that the casing extends the required 500 mm above grade, and as such, could potentially be subjected to flooding and is in contravention of the regulation;
- The well is located within 30 m of potential contaminant sources including various chemical storage drums, creosote timbers, and industrial activities;
- Turbidity has been in exceedence of the both the CDWQG MAC and AO;
- The chlorine disinfection system was not in operation at the time of water system assessment;
- There is no backflow prevention between the system and on the public fill station; and,
- The pumphouse door is normally left unlocked which could pose a security issue.

#### 10.6.2 Low Risk Deficiencies

- There is no surface sanitary seal (grout or bentonite seal as required by the Canadian Groundwater Association's Guidelines for Water Well

Construction), however as mentioned previously, there is likely a tight bond between the casing and the soil formation based on the well record and drilling method;

- The arsenic concentration, although not in exceedence of the current CDWQG MAC, is above the proposed MAC of 0.005 mg/L;
- The total iron concentration has been in exceedence of the CDWQG AO;
- The manganese concentration has been in exceedence of the CDWQG AO;
- The colour has previously been reported above the CDWQG AO; and,
- The public water fill comes off of the water system prior to the softening system, and the softening system was not operating at the time of water system assessment.

The Niels Jacobsen report titled “Community Water Systems in the Yukon – Stewart Crossing” (February, 2003) also noted that there are features that are normally found in a pumphouse for a community water supply system that are lacking in this one which relate to construction materials, floor type, plumbing and security. When the water system requires treatment upgrades to remove arsenic to below the proposed MAC, more space will be required than currently available and it would be worthwhile to consider constructing a new building that is complete with a concrete floor and more suitable plumbing to house the water system equipment.

## **10.7 Mitigative Options for Deficiencies**

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

### **10.7.1 Priority 1**

The following recommendations are provided in order to mitigate deficiencies that are of immediate concern for the Stewart Crossing Grader Station. Priority 1 remedial recommendations include:

- Standard wellhead including installation of a pitless unit and near surface sanitary seal should be completed. With a near surface sanitary seal, this well would considered to be non-GUDI.
- A chlorine tap should be installed on the wellhead and the well and water system should be super-chlorinated.

- Primary disinfection treatment consisting of a duplex commercial filtration system to filter to 1 micron (absolute) should be considered and the proportional feed chlorination system should be upgraded to ensure disinfection of the water supplied to this building. It is recommended that a digital dosing proportional feed chlorination system (or equivalent) be installed to replace the existing LMI system, as it would be more reliable and require less maintenance. The LMI system could be maintained as a back-up chlorination system (a back-up chlorination system was recommended by Niels Jacobsen in February 2003). The digital dosing type of chlorine injection system has recently been installed in most other community wells in the Yukon and would lend itself to better preparedness for equipment maintenance and replacement as well as operator training. These are conceptual design recommendations based on the information available for planning and budgeting purposes. Engineering input will be required for final system specifications.
- All chemical storage and creosoted timber piles should be relocated to at least 30 m from the wellhead. Activities within 30 m of the wellhead should be regulated to ensure that hazardous chemicals are not handled or stored in proximity to the wellhead.
- Backflow prevention should be installed to ensure that water can not flow from the public access point back to the water system.

#### 10.7.2 Priority 2

The softener system should be reconditioned and brought back into operation. Once the softener system is brought back into operation, arsenic concentrations should be monitored to determine whether future arsenic removal treatment will be required (see Priority 3).

All other high and medium risk deficiencies would be mitigated through completion of Priority 1 upgrades.

#### 10.7.3 Priority 3

Although standard softener systems are not designed for arsenic removal, they do often effect some arsenic removal. The arsenic concentrations should be monitored following reconditioning of the softener system. In the event that arsenic concentrations are still above the proposed MAC, an arsenic removal treatment system would be required. A new building to house all treatment equipment should be considered at this time.

## 10.8 Cost Estimates for Mitigative Options

Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

### 10.8.1 Priority 1

The estimated costs for the recommended Priority 1 upgrades are detailed below:

- It would cost approximately **\$5,000** for materials and labour to complete the recommended pitless unit wellhead upgrade and well and water system superchlorination.
- Commercial stainless steel duplex filtration canisters and filters (to 1 micron (absolute) would cost approximately **\$2,500** installed.
- Upgrades to a new digital dosing chlorine feed system with suction lines and reservoir would be approximately **\$2,100** installed.
- A suitable backflow prevention device could be supplied and installed for approximately **\$400**.

Therefore, it would cost approximately **\$10,000** to complete the recommended Priority 1 upgrades for this system.


### 10.8.2 Priority 2

Reconditioning and the softener system would cost approximately **\$500**.

### 10.8.3 Priority 3


An arsenic removal treatment system would cost in the order of **\$4,000**, while a new building to house the treatment systems with a concrete floor and appropriate construction would cost in the order of **\$20,000**.






NOTES:


1. UTM COORDINATES OBTAINED WITH A HAND HELD GPS USING NAD83 SYSTEM AND ARE CONSIDERED TO BE ACCURATE TO 10.0 m, APPROXIMATELY.

 30 m RADIUS FROM WATER WELL FOR CONSIDERATION OF PROXIMITY TO POTENTIAL CONTAMINANT SOURCES.

No.	DESCRIPTION	DATE	APPROVED
0	ISSUED FOR CLIENT REVIEW	DD/MM/YY	XXX
REVISION			

**EBA Engineering Consultants Ltd.**

DESIGNED BY: R. MARTIN  
DRAWN BY: J. BUYCK  
DATE: SEPT. 2005  
SCALE: AS SHOWN  
PROJECT No.: 1260002.004  
ACAD FILENAME: 004-NORTHERN REGION

CLIENT:  
  
Highways and Public Works  
Property Management Branch


SMALL PUBLIC WATER SYSTEMS ASSESSMENT  
NORTHERN REGION

GOVERNMENT OF YUKON  
HIGHWAYS & PUBLIC WORKS

STEWART X-ING GRADER STATION  
BUILDING # 5681  
SITE LOCATION DIAGRAM  
WELL ID: 5681

REVISION	ISSUE
0	
FIGURE No.	
FIGURE 5681-A	

## LEGEND



**EBA Engineering Consultants Ltd.**

CLIENT

**Yukon**  
Highways and Public Works  
Property Management Branch

PROJECT

SMALL PUBLIC WATER SYSTEMS ASSESSMENT  
WESTERN REGION

TITLE

SCHEMATIC SYSTEM  
LEGEND


DATE    APRIL 2006

DWN.    JSB



CHKD.    RMM

FILE NO.    1260002

DRWG.    LEGEND



SCHEMATIC PRODUCED BY BERT ALBISSER OF AQUA TECH SUPPLIES AND SERVICES LTD.

 <b>EBA Engineering Consultants Ltd.</b>		PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT NORTHERN REGION	
CLIENT 		TITLE WATER SYSTEM DISTRIBUTION/TREATMENT SCHEMATIC SYSTEM ID.: 5681 GRADER STATION - STEWART CROSSING, YT.	
DATE	SEPT. 2005	DWN.	JSB
CHKD.	RMM	FILE NO.	1260002.004
		DWG.:	FIGURE 5681-B

**Northern Region – Stewart Crossing Grader Station  
Building # 5681**

**DISTRIBUTION & TREATMENT SYSTEM DATA**

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	SUB PUMP	?				5HP - 4"
2	INLINE FILTER	AMEYER	10" BB			1 1/2" x 10"
3	CHLORINE PUMP	LMI	A751-39251		20020712896	
4	CHLORINE TANK	LMI	20 I. GALLON			
5	FLOW METER	LMI	REF-010			
6	PRESSURE TANK	Wau x TRO L	Wx-360			
7	SOFTENER	AQUA-TECH	50265606	DUPLEX	184243	9000-1450 DUPLEX
8	PRESSURE SWITCH	SQUARE D	FSG-2			
9	PRESSURE GAUGE	MARSH	0-100			2 1/2" - 1/4" FPT
10	CIRC PUMP	ARMSTRONG	?			

**TABLE 5681/5682- 1: SUMMARY OF BACTERIOLOGICAL RESULTS**

<b>Building #</b>	<b>Building Name</b>	<b>Number of Sampling Events</b>	<b>Time Period over which Sampling was Done</b>	<b>Any Positive Total Coliform Results? (yes or no)</b>	<b>Fraction of Positive Total Coliform Results vs. Total Sampling Events</b>	<b>Any positive E.Coli results? (yes or no)</b>	<b>Most Recent Sampling Event Available for EBA Review</b>	<b>Is Most Recent Result Positive?</b>
5681	Stewart Crossing Grader Station	9	Oct-04 to Jun-05	no	0/9	no	9-Jun-05	no
5682	Stewart Crossing Living Complex	8	Oct-04 to Jun-05	no	0/8	no	9-Jun-05	no



Table 5681/5682 - 2: Water Quality Results

SOURCE:	Building 5681 - Stewart Crossing Grader Station			Building 5682 - Stewart Crossing Living Complex	GCDWQ Criteria		
Location/ Resident	Stewart Crossing			Stewart Crossing			
Address							
Treatment	Softener (not in use), filtration			Softener (not in use), filtration			
Disinfection	Chlorination (not in use)			Chlorination (not in use)			
Source of Water	On-site well			On-site well			
Purpose of Sampling	Base Line	Base Line	Additional Sampling	Base Line			
Sample Location			Complex Residence				
Date Sampled	29-Sep-04	8-Jun-05	16-Aug-05	29-Sep-04	Lower	Upper Limit	
Physical Tests (ALS)					AO	MAC	AO
Colour (CU)	27	<5.0		7			15
Conductivity (uS/cm)		344					
Total Dissolved Solids	180	180		181			500
Hardness CaCO <sub>3</sub>	169	171		168	AO >200 = poor, > 500 unacceptable <sup>A</sup>		
pH	8.07	8.22		8.07	6.5		8.5
Turbidity (NTU)	<b>10.3</b>	<b>17.7</b>	<b>8.02</b>	<b>1.4</b>		1	5
UV Absorbance							
% UV Transmittance							
Dissolved Anions (ALS)							
Alkalinity-Total CaCO <sub>3</sub>	161	160		163			
Chloride Cl	0.8	<0.50		0.6			250
Fluoride F	0.15	0.173		0.15		1.5	
Silicate SiO <sub>4</sub>			10.2				
Sulphate SO <sub>4</sub>	17.7	18.5		17.8			500
Nitrate Nitrogen N	<0.1	<0.10		<0.1		10	
Nitrite Nitrogen N	<0.05	<0.10		<0.05		1	
Ammonia Nitrogen N							
Total Phosphate PO <sub>4</sub>			0.0285				
Total Metals (ALS)							
Aluminum T-Al	<0.005	<0.010		<0.005		0.1	
Antimony T-Sb	<0.0002	<0.00050		<0.0002		0.006	
Arsenic T-As	<b>0.0094</b>	<b>0.0117</b>	<b>0.0108</b>	<b>0.0074</b>		0.025	
Barium T-Ba	0.08	0.077		0.072		1	
Boron T-B	0.005	<0.10		0.004		5	
Cadmium T-Cd	<0.00001	<0.00020		<0.00001		0.005	
Calcium T-Ca		53.5					
Chromium T-Cr	0.001	<0.0020		0.001		0.05	
Copper T-Cu	<0.001	0.0057		0.002		1	
Iron T-Fe	<b>0.6</b>	<b>1.48</b>	<b>0.923</b>	0.28			0.3
Lead T-Pb	<0.0001	<0.0010		0.0002		0.01	
Magnesium T-Mg		9.11					
Manganese T-Mn	<b>0.136</b>	<b>0.134</b>	<b>0.14</b>	<b>0.136</b>			0.05
Mercury T-Hg		<0.00020				0.001	
Potassium T-K		1.38					
Selenium T-Se		<0.0010				0.01	
Sodium T-Na	3	3.4		3			200
Uranium T-U	<0.0005	<0.00010		<0.0005		0.02	
Vanadium T-V			<0.030				
Zinc T-Zn	0.221	0.43		0.226			5
Dissolved Metals							
Arsenic D-As			0.00697			0.025	
Iron D-Fe			<0.030				0.3
Manganese D-Mn			<b>0.135</b>				0.05
Organic Parameters							
Tannin and Lignin							
Total Organic Carbon C			1.44				
Field Chemistry (EBA)							
pH			8.38		6.5		8.5
TDS (ppm)			165				500
EC (uS/cm)			326				
Temperature (°C)			15.5				
Free Available Chlorine			0.01				

## Notes:

A. Guidelines indicated for hardness are not CDWQG, rather they are general aesthetic guidelines

- exceedences are indicated in yellow highlighting.

Italics and underline indicates exceedence of proposed MAC (ie. arsenic)**Bold with Yellow** highlighting indicates exceedence of CDWQG Aesthetic Objective (AO)**Bold Underline with Yellow** highlighting indicates exceedence of CDWQG MAC

Results are expressed as milligrams per litre except for pH and Colour (CU)

Conductivity (umhos/cm), Temperature (°C) and Turbidity (NTU)

&lt; = Less than the detection limit indicated.

AO = Aesthetic Objective

MAC = Maximum Acceptable Concentration (Health Based)



# EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

## SMALL PUBLIC WATER SYSTEM ASSESSMENT

### PART A: EBA Site Inspection

Inspector: Ryan Martin, Luke Lebel

Date Aug 16, 2005

WELL ID #	Owner	Location Description
5681	YTG	Stewart Crossing Grader Station

#### 1. Well Location and Potential Contaminant Sources

a. General location of well: (Community, Subdivision, etc.)

Stewart Crossing

b. Specific location: (Road or street, Building number, name of owner and/, legal description,

In wellhouse on grader station compound

c. GPS location: N 7028437 E 416194 elev 468m ±6m

d. Is there electric power? ☒ Yes ☐ No

e. Is there outside water access? ☒ Yes ☐ No  
Publicly Accessible

f. Does the well system have:

☐ 15 or more service connections to a piped distribution system? If so how many \_\_\_\_\_

Maintenance garage and Living Complex

☐ 5 or more delivery sites on a trucked distribution system? If so how many \_\_\_\_\_

g. Nearest building, specify Pumphouse

h. Distance from well to building 1.65m

i. If there is an effluent disposal field, is its location known? ☒ Yes ☐ No

j. Distance from well to nearest point of known field: leach pit @ 33m

k. Well location relative to field: ☐ upslope ☐ downslope ☒ lateral

# EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- l. Is there any part of a sewage disposal system(s) or other potential sources of pollution that may pose a health and safety risk within 30 m? ☐ Yes ☒ No

No. Tank @ ~45m; outhouse @ ~40m

- m. Is the well located within 300 m from a sewage lagoon or pit? ☐ Yes ☒ No unlikely

- n. Is the well located within 120 m from a solid waste site or dump, cemetery? ☐ Yes ☒ No unlikely

- o. Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment plant designed and secured to prevent:

Unauthorized access by humans? ☐ Yes ☒ No  
Unlocked enclosure

Entrance by animals? ☐ Yes ☒ No  
Access possible

- p. Is well site subject to flooding? ☐ Yes ☒ No

- q. Is the well site well drained? ☒ Yes ☐ No

- r. Is there a buried fuel tank on the property? ☒ Yes ☐ No

If yes, is it ☒ in use ☐ abandoned

Is the location known? ☒ Yes ☐ No

Distance from the well to known buried tank ~40m

- s. Are there any other known contaminant sources on the property?

☒ Yes ☐ No Describe Industrial activities around the well

If yes, specify the source: ☐ dump ☐ sewage lagoon ☐ cemetery ☐ other

Potential Source 1: <sup>Drums</sup> (Unknown contents); Distance from well to Potential Source 1: ~10m

Potential Source 2: <sup>Paint + Toluene</sup> Drums; Distance from well to Potential Source 2: ~15m

Potential Source 3: <sup>Tar tank</sup>; Distance from well to Potential Source 3: ~45m

Potential Source 4: <sup>Salt storage</sup>; Distance from well to Potential Source 4: ~35m  
<sup>Creosote timbers @ ~15m</sup>

- t. Are there other wells on this property? ☒ Yes ☐ No

How many? 1 ☐ in use ☒ abandoned ☐ require proper sealing  
dug well @ ~100m



# **EBA Engineering Consultants Ltd.**

Creating and Delivering Better Solutions

## **2. Well and Wellhead information:**

- a. When was well installed? Year 1994 Month April
- b. Type: ☒ drilled ☐ dug ☐ sand point ☐ other \_\_\_\_\_
- c. Is there a drillers log for the well: ☒ Yes ☐ No
- d. Is there a surface seal to 6 m ☐ Yes ☒ No ☐ unknown ☐ unlikely
- e. Surface casing: ☒ Yes Diameter 30 cm ☐ No
- f. Well casing: Diameter 30 cm to 12.8 m  
20 cm to 150 m  
15 cm to 176 m Material: ☒ steel ☐ plastic ☐ concrete
- g. Depth of well: 177.4 m ☐ measured (if possible) ☒ reported ☒ from log
- h. Static water level below ground: Unknown  
☐ measured (if possible) ☐ reported ☐ from log ☐ flowing
- i. (If granular) Is the well completed: ☐ open end casing ☒ with a well screen  
☐ with slotted pipe ☐ unknown other \_\_\_\_\_
- j. (If bedrock) Does the well have a liner? ☐ yes ☐ No ☐ steel ☐ plastic
- k. If there is a well screen: length 1.8 m slot size(s) 80 slot and 50 slot  
Location of screen: from 176.0 m to 177.4 m from log ☐ reported ☐
- l. Is there a sump below the screen? ☐ Yes ☒ No
- m. Is the well head: ☐ in pumphouse ☐ in pit ☐ pitless adaptor ☐ in a building  
☒ in a wooden enclosure other, describe adjacent to pumphouse
- n. If the well head is located in a wooden enclosure,

# **EBA Engineering Consultants Ltd.**

Creating and Delivering Better Solutions

- i. Is the well head below grade? describe in detail No
- ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? ☐ Yes ☒ No
- iii. Is the wellhead enclosed by fiberglass insulations? ☒ Yes ☐ No
- iv. Any evidence of rodents? Specify No
- v. Does the well casing have a proper seal cap? ☒ Yes ☐ No

If no, describe condition likely, but not able to observe due to insulation

## **3. Water Supplying This Well:**

- a. By definition is the water from a surface water source or under the direct influence of surface water?  
☒ Yes ☐ No ☐ farther investigation required.

If yes is there treatment or disinfection ☒ Yes ☐ No

Explain (filtration, disinfection etc...) Filtration, softening, chlorination

## **4. Aquifer Supplying This Well:**

- a. The aquifer is: ☐ bedrock ☒ granular sediment ☐ unknown

- b. Does water level and/or well capacity show seasonal fluctuation? ☐ Yes ☒ No  
unlikely

## **5. Pump Installation:**

- a. Is the well equipped with a pump? ☒ yes ☐ No

- b. Type of pump: ☐ hand ☒ electric submersible ☐ jet

☐ shallow well centrifugal ☐ other, \_\_\_\_\_

- c. Description: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_  
horsepower \_\_\_\_\_ capacity \_\_\_\_\_ voltage \_\_\_\_\_

# **EBA Engineering Consultants Ltd.**

Creating and Delivering Better Solutions

d. Date installed: \_\_\_\_\_ By: \_\_\_\_\_

e. For submersible pump, depth of setting below surface \_\_\_\_\_

f. Drop pipe for submersible pump: ☐ steel ☐ plastic *unknown*

g. Pump delivers water to: ☒ pressure tank ☐ elevated tank ☐ other

h. Are there automatic pump controls: ☒ Yes ☐ No

i. Is there provision for taking water samples before water reaches storage? ☐ Yes ☒ No

j. Is there a water meter on the system? ☐ Yes ☒ No

k. Is the pump and piping protected from freezing? ☒ Yes ☐ No

If yes, describe: Insulation and heat trace

l. Comments on pump installation: \_\_\_\_\_

## **6. Conclusions**

a. Comments on overall installation:

---

---

---

---

---

---

---

---

b. Recommendations: \_\_\_\_\_

---

---

---

---

---

---

---

---

# EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

## PART B: EBA Site Inspection

Inspector: BERT ALKSEK

Date AUG. 16/05

WELL ID #	Owner	Location Description
<u>5681</u>	<u>VTG</u>	<u>STEWART CROSSING, YT</u>

### 6. Water Treatment

a. Is well water treated? ☒ Yes ☐ No; Type of treatment:

☒ chlorination ☒ iron and or manganese removal ☐ other \_\_\_\_\_

b. Is water entering plumbing or piped distribution system treated with chlorine or another treatment that is as effective as chlorine used to achieve disinfection throughout the system?

☒ Yes ☐ No If so how CHLORINATOR (LIQUID)

c. If treated with chlorine, is the free residual chlorine concentration less than 0.2 mg/L

☐ Yes ☒ No \_\_\_\_\_ reading.

Tested at \_\_\_\_\_ (location)

d. Is testing for chlorine residual concentration done at the tap (eg. Kitchen faucet) or from representative points in a piped distribution system, including a point from tap at the end line

☐ Yes ☒ No If yes how often? \_\_\_\_\_

e. If the drinking water is being transported by water delivery truck does it have a minimum chlorine free residual of 0.4 mg/L at the time of fill. ☐ Yes ☒ No

### 7. Water Quality (observations):

a. Does the water stain plumbing? ☐ yes ☒ No ☐ slight ☐ severe

Type of stain: ☐ brown ☐ red ☐ black

b. Does the water contain sediment? ☐ Yes ☒ No ☐ occasional ☐ constant

c. Is there an unpleasant odour? ☐ Yes ☒ No ☐ H<sub>2</sub>S ☐ Other \_\_\_\_\_

# **EBA Engineering Consultants Ltd.**

Creating and Delivering Better Solutions

- d. Is there an unpleasant taste? ☐ Yes ☒ No ☐ brackish ☐ Other \_\_\_\_\_
- e. Is there a history of bad bacterial analyses? ☐ Yes ☒ No
- f. Is there a chemical analysis? ☐ Yes ☐ No ☐ adequate ☐ incomplete
- g. Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? ☐ Yes ☒ No
- h. Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the range 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? ☐ Yes ☒ No ☐ unknown
- i. If yes is the test performed in accordance with manufactures directions? ☐ Yes ☒ No ☐ unknown
- j. Is a record of the date, time, name of person performing the test and results of the drinking water sample kept? ☐ Yes ☒ No

## **TANK AND PIPING DETAILS**

### ***Tank Room***

Is there a water tank? Yes No Details: PRESSURE TANK

Where is it located?

Comments: \_\_\_\_\_

Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water?

YES NO

Comments: Wall House

Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES

NO

Comments: \_\_\_\_\_

Are there other heat sources near the tank? YES NO

Comments: \_\_\_\_\_

Is there waterproof flooring with a sealed base to contain spills? YES NO

Comments: \_\_\_\_\_

# **EBA Engineering Consultants Ltd.**

Creating and Delivering Better Solutions

## **Overall Tank**

What are the tank size and dimensions?

Wx - 366

What material is the tank constructed of? STEEL & Butyl Bladder

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments: \_\_\_\_\_

## **Tank Inlet, Outlet and Lid**

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

## **WATER TANK AND WATER QUALITY CONDITION**

Are there signs of staining or biofouling? YES NO

Comments: \_\_\_\_\_

Is there any sediment or scum in bottom of tank? YES NO

Comments: \_\_\_\_\_

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

# **EBA Engineering Consultants Ltd.**

Creating and Delivering Better Solutions

## **8. Conclusions**

### **a. Comments on overall installation:**

INSTALLATION IS ACCEPTABLE WITH THE  
EXCEPTION OF THE SOFTNER DRAIN. THERE  
IS NO PROPER DRAIN PIT IT DRAINS ON THE  
GROUND OUTSIDE THE WELL HOUSE  
THE CHLORINATOR IS UNPLUGGED. IT IS  
NOT IN SERVICE AT THIS TIME

### **b. Recommendations:**

INSTALL PROPER DRAIN FACILITY FOR  
TREATMENT SYSTEM.  
RETURN SOFTNER TO SERVICE AND  
TRAIN PERSONNEL TO OPERATE THE  
SYSTEM AND INSTITUTE CHLORINE  
RESIDUAL TESTING AT SCHEDULED  
INTERVALS. DAILY RESIDUAL TESTING  
IS RECOMMENDED.

### Willow Prickers





# Field Report

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

PHONE (403) 633-3070  
TELEX 036-8496

Started. *May 8*.....19*92*

Completed. *Apr 1*.....19*92*

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<i>Com. Transportation</i>	<i>U1/W1</i>	<i>Stewart</i>
	<i>94-1A-3</i>	<i>King</i>

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE 8" casing				
			set 40' of 8" casing	<i>May 10</i>	<i>12:30</i>	<i>8:00</i>	<i>7.5</i>
<i>40</i>	<i>47</i>	<i>Gr. sand cobs</i>					
<i>47</i>	<i>100</i>	<i>silt</i>					
<i>100</i>	<i>175</i>	<i>silt</i>	Broke casing unable to close bit	<i>May 11</i>	<i>8:00</i>	<i>8:00</i>	<i>1.2</i>
			set up wait till 11:00	<i>May 12</i>	<i>8:00</i>	<i>4:00</i>	<i>8</i>
			for Pullars Pulling casing to slow				
			travel to where for	<i>"</i>	<i>4:00</i>	<i>9:00</i>	<i>5</i>
			Exer a 6" casing				
			Leading	<i>"</i>	<i>9:00</i>	<i>11:00</i>	<i>2</i>
			Travel to start	<i>May 13</i>	<i>1:00</i>	<i>7:00</i>	<i>6</i>
			Pulling 175' casing	<i>"</i>	<i>8:00</i>	<i>6:00</i>	<i>10</i>

## Rcd. of Casing & Pipe

Size	Type	Size	Type
------	------	------	------

Feet	Inch	Feet	Inch
------	------	------	------

## Remarks:

## SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....



# Field Report

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

PHONE (403) 633-3070  
TELEX 036-8496

Started. *Mar...8.....1992*

Completed. *Apr...1.....1992*

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<i>Corn &amp; Transport</i>	<i>W / W</i>	<i>Stewart King</i>
	<i>94-1A-3</i>	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOUR
			MOVE 8" casing				
			waiting for drive shoe	<i>Mar. 14</i>	<i>8:00</i>	<i>4:30</i>	<i>8.5</i>
			mount casing hammer				
			set 40' casing	<i>11</i>	<i>4:30</i>	<i>8:00</i>	<i>3.5</i>
			Redrill to 175'	<i>Mar. 15</i>	<i>8:00</i>	<i>8:00</i>	<i>12</i>
<i>175</i>	<i>290</i>	<i>silt</i>	Plugged bit	<i>Mar. 16</i>	<i>8:00</i>	<i>8:00</i>	<i>12</i>
			unable to keep bit	<i>Mar. 17</i>	<i>8:00</i>	<i>6:00</i>	<i>10</i>
			from plugging				
			Fix discharge hose				
			off casing hammer				
			Fix casing hammer				
			cable				

## Rcd. of Casing & Pipe

Size	Type	Size	Type
------	------	------	------

Feet	Inch	Feet	Inch
------	------	------	------

Remarks:

	Static Level	Total Rig Time	hrs.
	Ground Level	Total Standby	hrs.
	Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....



# Field Report

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

PHONE (403) 633-3070  
TELEX 036-8496

Started *Mar. 8*.....19*9*

Completed *Apr. 1*.....19*9*

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<i>Comm. Transport</i>	<i>W / W?</i>	<i>Stewart</i>
	<i>94-1A-3</i>	<i>King</i>

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOUR
			MOVE 8" casing				
			Pull back to 100' 3 times	<i>Mar. 18</i>	<i>8:00</i>	<i>11:00</i>	<i>1.5</i>
			blow on in on Rapid				
			Feed back when using				
			casing hammer				
			wanted.				
			change over to clutch	<i>Mar. 19</i>	<i>8:00</i>	<i>8:00</i>	<i>12</i>
			bank, Not working				
			change spools				
			Plugged bit trip out				
			Bit plugged trip hole	<i>Mar. 20</i>	<i>8:00</i>	<i>12:00</i>	<i>16</i>
			Red will from 180' Built seal				
			for top of casing hammer				
<i>290</i>	<i>305</i>	<i>silt</i>	Put tent on				
			Blew hose off Fitting to				
			Injection pump trouble				
			with supply pump getting				
			water picking up rocks Blow seal				

Rcd. of Casing & Pipe  
Size Type Size Type

Remarks:

Feet Inch Feet Inch

Static Level

Total Rig Time

hrs.

Ground Level

Total Standby

hrs.

Top Of Casing

Drilling Mud

sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....



# Field Report

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

PHONE (403) 633-3070  
TELEX 036-8496

Started...Mar...8.....1996

Completed...Mar...1.....1996

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Com. & Transport	W/U	Stewart King
	94-1A.3	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE 8" casing				
			Tripped hole Badrill & removed	Mar 21	8:00	11:00	
			220' Arclon compressor				
			dumped oil from				
			receiver tank cleaned				
			Fuel filters				
305	315	silt					
			Taking broken Piece	"	11:00	12:00	1
			odd casing hammer				
			Taking broken Piece	Mar 22	12:00	4:00	4
			odd casing hammer				
315	365	silt					
			2hrs Fixing short 6"	Mar 23	8:00	11:00	15
			discharge hose on				
			casing hammer				
365	385	silt					
			blowing oring in Ropit	Mar 24	8:00	10:30	14.5
			Feed control Bank				
			Plugged bit tripped hole				
			Hole heaving				

## Rcd. of Casing & Pipe

Size	Type	Size	Type
------	------	------	------

--	--	--	--

--	--	--	--

Feet	Inch	Feet	Inch
------	------	------	------

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

Remarks:

Static Level

Ground Level

Top Of Casing

Total Rig Time

Total Standby

Drilling Mud

hrs.

hrs.

sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....





# Field Report

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

PHONE (403) 633-3070  
TELEX 036-8496

Started May 8 1994

Completed Apr 1 1994

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<u>Comincons</u>	<u>W/W</u>	<u>Stewart</u>
		<u>Xing</u>
	<u>94-1A-3</u>	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE 6" casing				
			Trip out	May 27	8:00	5:00	9
			set 120' of 6" casing	"	5:00	8:00	3
			set 270' of 6" casing	May 28	8:00	12:30	16.5
490	520	silt		May 29	8:00	9:00	13
520	569	silt	Gr.	May 30	8:00	9:30	13.5
567	574	silt	Gr.	May 31			
574	579	silt	Sand Pss Gr.				
579	582	silt	Gr.				
			Trip out	May 31	8:00	11:00	3
			check hole set screens	"	11:00	5:00	6
			Druc/ax	"	5:00	12:00	7
			rite shift 12:00, 8:00 P.m.				
			Trip out clean up	Jun 1	8:00	2:00	6
			Load				
			travel to whse with drill	"	2:00	7:30	5.5

## Rcd. of Casing & Pipe

Size Type Size Type

6

Feet Inch Feet Inch

57.6

## Remarks:

100 G.P.M.

screen bottom 582' G.L.

1-80 slot

1-50 slot

1-2' riser + ~~1-2'~~ P-Packer

58 bit pin

Total Length 10' 6"

Static Level

Ground Level

Top Of Casing

Total Rig Time

hrs.

Total Standby

hrs.

Drilling Mud

sacks

## SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....





**Photo 001:** Abandoned well enclosure.



**Photo 002:** Wellhead of abandoned well.



**Photo 003:** Looking down abandoned dug well.



**Photo 005:** 5681 Stewart Crossing grader station facing west.



**Photo 009:** 5690 Existing deep well enclosure and well house storage building.



**Photo 174:** 5690 water system that serves 5681 & 5682. (pressure tank, filter, pump controls, LMI proportion feed chlorination system).



**Photo 008:** 5682 Living Complex.



**Photo 012:** Paint and toluene drum storage.