

7.0 BUILDING M0133: BEAVER CREEK RCMP RESIDENCE

7.1 Description of Existing Water Supply System

Building M0133, the Beaver Creek RCMP Residence, is currently served by a water supply system that delivers water from a 37.4 m deep well. The well is located in an enclosure off from basement of the residence. The well location and other details about the surrounding area are provided in Figure M0133-A in Appendix A7. The coordinates of the wellhead, as measured by a handheld GPS device, were recorded as:

- UTM ZONE 7
- Northing: 6917199
- Easting: 506150

The water system is equipped with an in-line filter and a water softener, however, at the time of the assessment, the softener was being bypassed and was not functioning. The system is not equipped with a disinfection system. A schematic detailing the well supply system is provided as Figure M0133-B in Appendix A7.

There is an abandoned well located in the same enclosure as the well that is currently in use. The abandoned well was not equipped with a proper cap and was open.

7.2 Description of Existing Wastewater Systems

The septic tank that serves the residence is located approximately 20 m west of the well, and the septic effluent discharge field is located approximately 40 m down slope from the well. Although the effluent field is downslope from the well, conceptual hydrogeology (outlined in a following section) indicates that it may be hydraulically upgradient. A site plan showing the septic system is given by Figure M0133-A in Appendix A7.

7.3 Water Quality Results

7.3.1 Water Quality Results from Previous Sampling

Bacteriological

Four samples were collected from the M0133 Beaver Creek RCMP Residence water system between September 2004 and June 2005 and were tested for total coliform and *E. coli* by Yukon Environmental Health Services using the presence/absence test method. Results are tabulated in Table M0133-1 in Appendix A7. Coliform bacteria and *E. coli* were reported as absent in each of the four samples for which results are provided.

Potability

Water samples were previously collected from the M0133 Beaver Creek RCMP Residence water system on September 23, 2004 and June 15, 2005. The samples were submitted to Northwest Labs in Surrey, BC and ALS Environmental in Vancouver, BC for potability analyses. The results of these analyses are summarized in Table M0133-2 in Appendix A7. EBA reviewed the analytical results to compare them with the Canadian Drinking Water Quality Guidelines (CDWQG) to observe general water quality, identify and recommend additional sampling and analytical, and to identify indicators of potential contamination as follows:

- The turbidity of the water during the June 15th, 2005 sampling event was reported at 2.28 NTU, which is in exceedence of the CDWQG MAC of 1.0 NTU;
- The water quality results indicated that all other health based and aesthetic objectives were met for the parameters analyzed;
- The water quality results indicated that the groundwater from which this system receives its water supply is a calcium bicarbonate type water; and,
- The hardness (as CaCO₃) was 151 mg/L during the first sampling event, and is considered hard. During the second sampling event the hardness (as CaCO₃) was 141 mg/L, and is also considered hard.

7.3.2 Identification of Additional Analytical Testing Required

Additional analytical for the M0133 Beaver Creek RCMP Residence that was identified to be included during the water system assessments is detailed below:

- As there had previously been an exceedence of the CDWQG MAC for turbidity, a sample was taken to re-test for turbidity;
- UV absorbance and UV transmissivity, as well as tannins and lignin, to determine potential for UV treatment as a disinfection option for this water system;
- Total organic carbon (TOC); and,
- Measurements in the field for total dissolved solids, conductivity, pH, and temperature.

Additional Analytical Results

A water sample was obtained during the water system assessment on July 27, 2005, and was submitted to ALS Environmental in Vancouver, BC for analysis. These results are summarized in Table M0133-2 in Appendix A7 and the laboratory reports are included in Appendix B. The water quality results from additional analytical sampling indicated that all health based and aesthetic objectives were met for the parameters analyzed.

7.3.3 Indicators of Potential Contamination

Chloride, nitrate and nitrite concentrations can indicate impacts from surfacewater sources or septic waste. Although below the MAC, the chloride concentrations were elevated compared to normal background ranges for groundwater in the area. Nitrate and nitrite concentrations for this sample were low and within the normal background range for this area. These water quality results do not suggest that the aquifer from which the groundwater is obtained for the M0133 Beaver Creek RCMP Residence is under the influence of surfacewater sources or septic wastes. Road salting on the highway adjacent to the well could result in elevated chloride concentrations.

7.4 Conceptual Hydrogeology

The log for this well indicates that the well is completed at a depth of 37.4 m within a gravel aquifer. The lithology indicates mostly gravel with variable till and silty sediments. This is consistent with most well logs in the area, which indicate that discontinuous lenses of finer-grained sediments persist throughout the area, but in general the sediments are dominated by coarse alluvium. Some discontinuous permafrost is also interpreted to persist throughout the Beaver Creek area. The static water level the abandoned well was measured to be 12.1 m below the top of the casing and approximately 13.7 m below grade. The presence of variable interbedded fine grained material overlying the aquifer indicates limited protection from surficial sources of contamination. A study previously completed in the Beaver Creek area by EBA determined that the direction of groundwater flow in the vicinity of the site is north to northeasterly.

7.5 Potential Contaminant Sources

Potential contaminant sources identified during the water system assessment are compiled in field notes in Appendix A7. Photos of potential contaminant sources are also provided in Appendix A7.

Potential contaminant sources within 30 m of the wellhead are:

- An indoor fuel storage tank (AST) at 3 m;
- An abandoned well approximately 1 m from the well that is currently not in use; and
- A septic Tank at 20 m (note that sewage regulation allows tank to be within 15 m).

In addition, the septic field is located 40 m away from the well.

7.5.1 Spills Records and Contaminated Sites Search Results

The Government of Yukon Environmental Programs Branch and Environment Canada Environmental Protection Branch did not identify any recorded spill events or contaminated sites issues for this site or neighbouring sites.

7.6 Identified Water System Deficiencies and Associated Risk

7.6.1 High and Medium Risk Deficiencies

- Poor surface completion of the wellhead (located in an enclosure below grade);
- There is no surface sanitary seal (grout or bentonite seal as required by the Canadian Groundwater Association's Guidelines for Water Well Construction);
- By definition of the Draft Yukon GUDI Assessment Guideline, the well is potentially under the direct influence of surface water because does not meet the requirements of the Guidelines for Water Well Construction.
- The well is located within 30 m of potential sources of contamination including: an abandoned well that is not equipped with a proper cap and is located within 1 m of the current well, and an AST located in the basement of the building; and,
- There is no disinfection system.

7.6.2 Low Risk Deficiencies

- There had been a previous CDWQG MAC exceedence for turbidity, but the most recent sampling event reported turbidity below the CDWQG MAC;

- The plumbing installation was observed to be unprofessional, and the softener discharge is not to code;
- The water softener was not functioning at the time of the water system assessment;
- The in-line filter was observed to need replacing; and,
- There is an indoor fuel storage tank located in the basement of the residence, however, because the floor is concrete the potential risk of impact to the well from a spill or leak event is considered minimal.

7.7 Mitigative Options for Deficiencies

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

7.7.1 Priority 1

- An NSF/ANSI 55 approved UV disinfection system (or equivalent) should be installed. This is a conceptual design recommendations based on the information available for planning and budgeting purposes. Engineering input will be required for final system specifications; and
- The abandoned well should be properly decommissioned by backfilling it with grout or bentonite, and welding a cover over the casing.

7.7.2 Priority 2

- The wellhead at M0131 should be extended to a minimum of 500 mm above the surrounding grade, and the well pit should be backfilled with a low-permeability material to provide a surface seal around the well casing. A surface sanitary seal (grout or bentonite) should be installed as deep as possible during wellhead improvements.

7.7.3 Priority 3

- Upgrade plumbing to meet code;
- Repair water softener, and replace filter; and,
- Install secondary containment tray around AST.

7.8 Cost Estimates for Mitigative Options

Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

7.8.1 Priority 1


- It would cost approximately **\$2,200** for supply and installation of a UV disinfection system; and
- Proper decommissioning of the abandoned well would cost in the order of **\$1,000** for materials and labour.

7.8.2 Priority 2

- Standard wellhead upgrades (casing extension, sanitary seal, plumbing and electrical extensions, and insulation and heat trace as necessary) would cost approximately **\$4,000**; and,
- Installation of NSF 61 NSF 61 filtration system (to 1 micron absolute) would cost in the order of **\$500**.


7.8.3 Priority 3

- It is estimated that the recommended plumbing upgrades would cost approximately **\$100**;
- To repair the water softener (replace media), and replace filter would cost approximately **\$600** for materials and labour; and
- To supply and install a secondary containment tray around the AST would cost approximately **\$500**.



SEPTIC FIELD

SEPTIC TANK



UNDEVELOPED

UNDEVELOPED BETWEEN LOTS

ROAD

RESIDENTIAL PROPERTY

WELL M0133
N 6 917 199
E 506 150
DRILLERS REPORT
NO. 111070018

RCMP
RESIDENCE
BLDG. # M0133

AST

FILL & VENTS
PIPES

TO OTHER RCMP
RESIDENCE (M0134)



SCALE 1:300

NOTES:
1. UTM COORDINATES OBTAINED WITH A HAND HELD GPS USING NAD83 SYSTEM AND ARE CONSIDERED TO BE ACCURATE TO 10.0 m, APPROXIMATELY.

 30 m RADIUS FROM WATER WELL FOR CONSIDERATION OF PROXIMITY TO POTENTIAL CONTAMINANT SOURCES.

No.	DESCRIPTION	DATE	APPROVED
0	ISSUED FOR CLIENT REVIEW	DD/MM/YY	XXX
REVISION			

EBA Engineering Consultants Ltd.

DESIGNED BY: R. MARTIN
DRAWN BY: J. BUYCK
DATE: AUG. 2005
SCALE: AS SHOWN
PROJECT No.: 1260002.003
ACAD FILENAME: 003-WESTERN REGION

CLIENT:

Yukon
Highways and Public Works
Property Management Branch

SMALL PUBLIC WATER SYSTEMS ASSESSMENT
WESTERN REGION


GOVERNMENT OF YUKON
HIGHWAYS & PUBLIC WORKS

BEAVER CREEK RCMP
RESIDENCE BUILDING # M0133
SITE LOCATION DIAGRAM
WELL ID: M0133

REVISION ISSUE
0

FIGURE No.
FIGURE M0133-A

LEGEND



EBA Engineering Consultants Ltd.

PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT
WESTERN REGION

CLIENT

Yukon
Highways and Public Works
Property Management Branch

TITLE

SCHEMATIC SYSTEM
LEGEND


DATE APRIL 2006

DWN. JSB



CHKD. RMM

FILE NO. 1260002

DRWG. LEGEND



SCHEMATIC PRODUCED BY BERT ALBISSER OF AQUA TECH SUPPLIES AND SERVICES LTD.

 EBA Engineering Consultants Ltd.		PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT WESTERN REGION	
CLIENT 		TITLE WATER SYSTEM DISTRIBUTION/TREATMENT SCHEMATIC SYSTEM ID.: M0133 BEAVER CREEK RCMP RESIDENCE	
DATE	SEPT. 2005	DWN.	JSB
CHKD.	FMM	FILE NO.	1260002.003
		DWG.:	FIGURE M0133-B

Western Region – R.C.M.P. Housing
 Building # MO133 ? North

DISTRIBUTION & TREATMENT SYSTEM DATA

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	SUB. Pump	UNKNOWN	3/4 HP.			4" - 3/4 HP
2	PRESSURE TANK #1	JET RITE	JR 15.			
3	PRESSURE TANK #2	WELL RITE	WR-260			
4	PRESSURE SWITCH	SQUARE D	FSG-2			2HP - 1/4" NPT.
5	INLINE FILTER	CUNO	10" CLEAR			10" 3/4" NPT
6	FILTER CART.	CUNO	AP-110			10" x 2 1/2"
7	WATER SOFTENER	NOVATEK.	HCZOMI		202531	20K.
8						
9						
10						

TABLE MO133- 1: SUMMARY OF BACTERIOLOGICAL RESULTS

		Number of Sampling Events	Time Period over which Sampling was Done	Any Positive Total Coliform Results? (yes or no)	Fraction of Positive Total Coliform Results vs. Total Sampling Events	Any positive E.Coli results? (yes or no)	Most Recent Sampling Event Available for EBA Review	Is Most Recent Result Positive?
Building #	Building Name							
M0133	Beaver Creek R.C.M.P. Residence	4	Sept-04 to Jun-05	no	0/4	no	16-Jun-05	no



Table MO133-2: Water Quality Results

SOURCE:		Building M0133 - Beaver Creek RCMP Residence			GCDWQ Criteria		
Location/ Resident		Beaver Creek					
Address							
Treatment		Filtration					
Disinfection		None					
Source of Water		On-site well					
Purpose of Sampling		Base Line	Base Line	Additional Analytical			
Sample Location				Kitchen tap			
Date Sampled		23-Sep-04	15-Jun-05	27-Jul-05	Lower	Upper Limit	
Physical Tests (ALS)					AO	MAC	AO
Colour (CU)		<5	<5.0	-			15
Conductivity (uS/cm)			309	-			
Total Dissolved Solids		171	189	-			500
Hardness CaCO3		151	141	-	AO >200 = poor, > 500 unacceptable ^A		
pH		8.21	8.25	-	6.5		8.5
Turbidity (NTU)		0.4	2.28	0.360		1	5
UV Absorbance				0.0050			
% UV Transmittance				98.9			
Dissolved Anions (ALS)							
Alkalinity-Total CaCO3		128	138	-			
Chloride Cl		1.1	0.83	-			250
Fluoride F		<0.05	0.057	-		1.5	
Silicate SiO4				-			
Sulphate SO4		32.6	35.2	-			500
Nitrate Nitrogen N		0.2	0.22	-		10	
Nitrite Nitrogen N		<0.05	<0.10	-		3.2	
Ammonia Nitrogen N				-			
Total Phosphate PO4				-			
Total Metals (ALS)							
Aluminum T-Al		<0.005	<0.010	-			
Antimony T-Sb		<0.0002	<0.00050	-		0.006	
Arsenic T-As		0.0012	0.00093	-		0.025	
Barium T-Ba		0.017	<0.020	-		1	
Boron T-B		0.027	<0.10	-		5	
Cadmium T-Cd		<0.00001	<0.00020	-		0.005	
Calcium T-Ca			45.2	-			
Chromium T-Cr		0.0006	<0.0020	-		0.05	
Copper T-Cu		0.053	0.0494	-		1	
Iron T-Fe		0.03	<0.030	-			0.3
Lead T-Pb		<0.0001	<0.0010	-		0.01	
Magnesium T-Mg			6.86	-			
Manganese T-Mn		<0.005	<0.0020	-			0.05
Mercury T-Hg			<0.00020	-		0.001	
Potassium T-K			1.24	-			
Selenium T-Se			<0.0010	-		0.01	
Sodium T-Na			2.8	-			200
Uranium T-U		<0.0005	0.00035	-		0.02	
Vanadium T-V				-			
Zinc T-Zn		0.021	<0.050	-			5
Organic Parameters							
Tannin and Lignin				<0.10			
Total Organic Carbon C				1.03			
Field Chemistry (EBA)							
pH				8.34	6.5		8.5
TDS (ppm)				51			500
EC (uS/cm)				104			
Temperature (°C)				7.8			
Free Available Chlorine							

Notes:

A. Guidelines indicated for hardness are not CDWQG, rather they are general aesthetic guidelines - exceedences are indicated in yellow highlighting.

Italics and underline indicates exceedence of proposed MAC (ie. arsenic)

bold with yellow highlighting indicates exceedence of CDWQG Aesthetic Objective (AO)

bold underline with yellow highlighting indicates exceedence of CDWQG MAC

Results are expressed as milligrams per litre except for pH and Colour (CU)

Conductivity (umhos/cm), Temperature (°C) and Turbidity (NTU)

< = Less than the detection limit indicated.

AO = Aesthetic Objective

MAC = Maximum Acceptable Concentration (Health Based)



EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

SMALL PUBLIC WATER SYSTEM ASSESSMENT

PART A. EBA Site Inspection

Inspector: Ryan Martin, Luke Lebel

Date July 27, 2009

WELL ID #	Owner	Location Description
M0133	RCMP	Beaver Creek RCMP Residences

1. Well Location and Potential Contaminant Sources

a. General location of well: (Community, Subdivision, etc.)

Beaver Creek

b. Specific location: (Road or street, Building number, name of owner and/, legal description,

c. GPS location: N 6917199 E 506150 elev 667m ± 6m

d. Is there electric power? Yes No

e. Is there outside water access? Yes No

f. Does the well system have:

15 or more service connections to a piped distribution system? If so how many _____
RCMP Residence.

5 or more delivery sites on a trucked distribution system? If so how many _____

g. Nearest building, specify located off of basement of M0133 Residence

h. Distance from well to building _____

i. If there is an effluent disposal field, is its location known? Yes No

j. Distance from well to nearest point of known field: ~20m to tank, ~40m to field

k. Well location relative to field: upslope downslope lateral

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

l. Is there any part of a sewage disposal system(s) or other potential sources of pollution that may pose a health and safety risk within 30 m? Yes No

m. Is the well located within 300 m from a sewage lagoon or pit? Yes No *unlikely*

n. Is the well located within 120 m from a solid waste site or dump, cemetery? Yes No *unlikely*

o. Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment plant designed and secured to prevent:

Unauthorized access by humans? Yes No *located in residence* Entrance by animals? Yes No

p. Is well site subject to flooding? Yes No

q. Is the well site well drained? Yes No *Ground around well is flat*

r. Is there a buried fuel tank on the property? Yes No *unlikely*

If yes, is it in use abandoned

Is the location known? Yes No

Distance from the well to known buried tank _____

s. Are there any other known contaminant sources on the property?

Yes No Describe _____

If yes, specify the source: dump sewage lagoon cemetery other

Potential Source 1: *Indoor AST*; Distance from well to Potential Source 1: *~2m*

Potential Source 2: _____; Distance from well to Potential Source 2: _____

Potential Source 3: _____; Distance from well to Potential Source 3: _____

Potential Source 4: _____; Distance from well to Potential Source 4: _____

t. Are there other wells on this property? Yes No

How many? 1 in use abandoned require proper sealing

is not equipped with a cap on the casing

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

2. Well and Wellhead information:

a. When was well installed? Year 1992 Month June

b. Type: drilled dug sand point other _____

c. Is there a drillers log for the well: Yes No

d. Is there a surface seal to 6 m Yes No unknown unlikely

e. Surface casing: Yes Diameter _____ No

f. Well casing: Diameter 15 cm Material: steel plastic concrete

g. Depth of well: 35.90 m ^{could be pump} measured (if possible) reported from log 123 ft from log

h. Static water level below ground: 12.090 m bc 47 ft from log

measured (if possible) reported from log flowing

i. (If granular) Is the well completed: open end casing with a well screen

with slotted pipe unknown other _____

j. (If bedrock) Does the well have a liner? yes No steel plastic

k. If there is a well screen: length _____ slot size(s) 25 slot
Location of screen: from 121.5 ft to 123 ft from log reported

l. Is there a sump below the screen? Yes No

m. Is the well head: in pumphouse in pit pitless adaptor in a building

in a wooden enclosure other, describe of from basement of residence

n. If the well head is located in a wooden enclosure,

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- i. Is the well head below grade? describe in detail ~ 1.85m below grade
- ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? Yes No
Some dampness on floor
- iii. Is the wellhead enclosed by fiberglass insulations? Yes No in walls of enclosure
- iv. Any evidence of rodents? Specify Access possible
- v. Does the well casing have a proper seal cap? Yes No
If no, describe condition Split gasket cap

3. Water Supplying This Well:

- a. By definition is the water from a surface water source or under the direct influence of surface water?
 Yes No farther investigation required.

If yes is there treatment or disinfection Yes No

Explain (filtration, disinfection etc...) filtration

4. Aquifer Supplying This Well:

- a. The aquifer is: bedrock granular sediment unknown
- b. Does water level and/or well capacity show seasonal fluctuation? Yes No unlikely

5. Pump Installation:

- a. Is the well equipped with a pump? yes No
- b. Type of pump: hand electric submersible jet
 shallow well centrifugal other, _____
- c. Description: Manufacturer _____ Model _____
horsepower _____ capacity _____ voltage _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

d. Date installed: _____ By: _____

e. For submersible pump, depth of setting below surface _____

f. Drop pipe for submersible pump: steel plastic

g. Pump delivers water to: pressure tank elevated tank other

h. Are there automatic pump controls: Yes No

i. Is there provision for taking water samples before water reaches storage? Yes No

j. Is there a water meter on the system? Yes No

k. Is the pump and piping protected from freezing? Yes No

If yes, describe: OFF from heated building

l. Comments on pump installation: _____

6. Conclusions

a. Comments on overall installation:

b.Recommendations: _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

PART B: EBA Site Inspection

Inspector: BEET ALBISER

Date July 27/05

WELL ID #	Owner	Location Description
M0133	YTG	RAMP RESIDENCE (NORTH) BEVER CREEK

6. Water Treatment

- a. Is well water treated? Yes No; Type of treatment: WATER SOFTENER.
- chlorination iron and or manganese removal other _____
- b. Is water entering plumbing or piped distribution system treated with chlorine or another treatment that is as effective as chlorine used to achieve disinfection throughout the system?
- Yes No If so how _____
- c. If treated with chlorine, is the free residual chlorine concentration less than 0.2 mg/L
- Yes No _____ reading.
- Tested at _____ (location)
- d. Is testing for chlorine residual concentration done at the tap (eg. Kitchen faucet) or from representative points in a piped distribution system, including a point from tap at the end line
- Yes No If yes how often? _____
- e. If the drinking water is being transported by water delivery truck does it have a minimum chlorine free residual of 0.4 mg/L at the time of fill. Yes No

7. Water Quality (observations):

- a. Does the water stain plumbing? yes No slight severe
- Type of stain: brown red black
- b. Does the water contain sediment? Yes No occasional constant
- c. Is there an unpleasant odour? Yes No H₂S Other _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- d. Is there an unpleasant taste? Yes No brackish Other _____
- e. Is there a history of bad bacterial analyses? Yes No ?
- f. Is there a chemical analysis? ? Yes No adequate incomplete
- g. Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? Yes No
- h. Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the range 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? Yes No unknown
- i. If yes is the test performed in accordance with manufactures directions? Yes No unknown
- j. Is a record of the date, time, name of person performing the test and results of the drinking water sample kept? Yes No

TANK AND PIPING DETAILS

Tank Room

Is there a water tank? Yes No Details: PRESSURE TANK.

Where is it located?

Comments: # 1 IN WELL ENCLOSE / # 2 IN BASEMENT

Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water?

YES NO

Comments: _____

Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES

NO

Comments: _____

Are there other heat sources near the tank? YES NO

Comments: _____

Is there waterproof flooring with a sealed base to contain spills? YES NO

Comments: _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

Overall Tank

What are the tank size and dimensions?

What material is the tank constructed of? _____

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments: _____

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO

Comments: _____

Is there any sediment or scum in bottom of tank? YES NO

Comments: _____

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

8. Conclusions

a. Comments on overall installation:

THE PIPING AT WELL HEAD IS UNPROFESSIONAL.
THE WATER SOFTENER IS NOT OPERATIONAL
AND THE INLINE FILTER IS IN NEED OF
CHANGING.
THE SOFTNER DRAIN IS NOT TO CODE.

b. Recommendations:

REPAIR WATER SOFTENER AS NECESSARY IN
PUT BACK INTO SERVICE. CHANGE INLINE
FILTER. REPIPE SOFTNER DRAIN TO CODE.
BRING WELL HEAD PIPING TO CODE.



Photo 0545: M0133 Beaver Creek RCMP Residence from rear, wellhead enclosure (front centre)



Photo 0544: M0133 Septic field



Photo 0089: M0133 Pressure tank



Photo 0090: M0133 In-line filter and water softener