14.0 BUILDING 3125: BEAVER CREEK AIR TERMINAL BUILDING

14.1 Description of Existing Water Supply System

Building 3125, the Beaver Creek Airport Terminal Building, is currently served by a water system that sources water from a well of unknown depth. The well is located in a pit approximately 2 m east of the terminal building. The well location and other details about the surrounding area are provided in Figure 3125-A in Appendix A14. The coordinates of the wellhead, as measured by a handheld GPS device, were recorded as:

- UTM ZONE 7
- Northing: 6919562
- Easting: 507085

There is no treatment or disinfection system for the water supplying this building. A schematic detailing the well water supply system is provided as Figure 3440-B in Appendix A14.

14.2 Description of Existing Wastewater Systems

A septic tank that serves the terminal building is located on the east side of the building approximately 5 m north of the tank. Effluent is discharged to an in ground sewage disposal system approximately 54 m northwest of the well. Conceptual hydrogeology for the area indicates that the effluent disposal field is likely downgradient from the well. A site plan showing the septic system is given by Figure 3125-A in Appendix A14.

14.3 Water Quality Results

14.3.1 Water Quality Results from Previous Sampling

Bacteriological

Nine samples were collected from the Beaver Creek Airport Terminal Building water system between September 2004 and June 2005 and were tested for total coliform and *E. coli* by Yukon Environmental Health Services using the presence/absence test method. Results are tabulated in Table 3125-1 in Appendix A14. *E. coli* bacteria were reported as absent in each of the nine samples for which results are provided, but one sample, taken November 17, 2004, tested positive for total coliform bacteria. More recent samples have not had Total coliform bacteria present.



Potability

Water samples were previously collected from the Beaver Creek Airport Terminal Building water system on September 21, 2004 and June 15, 2005. The samples were submitted to Northwest Labs in Surrey, BC and ALS Environmental in Vancouver, BC for analyses included in their drinking water packages. The results of these analyses are summarized in Table 3125-2 in Appendix A14. EBA reviewed the analytical results to compare them with the Canadian Drinking Water Quality Guidelines (CDWQG) to observe general water quality, identify and recommend additional sampling and analytical, and to identify potential indicators of contamination.

- The turbidity was 4.1 NTU during the first sampling event and 3.29 NTU during the second sampling event. In both cases the turbidity was in exceedence of the CDWQG MAC of 1.0 NTU;
- Review of the water quality results indicated that all other health based and aesthetic objectives were met for the parameters analyzed;
- Review of the water quality results indicated that the groundwater is a calcium magnesium bi-carbonate sulphate type water; and,
- The hardness (as CaCO₃) was 137 mg/L during the first sampling event and 126 mg/L during the second sampling event, and is considered to be moderately hard.

14.3.2 Identification of Additional Analytical Testing Required

Additional analytical for the Beaver Creek Airport Terminal Building that was identified to be included during the water system assessments is detailed below:

- As turbidity was previously in exceedence of the CDWQG MAC, a sample was taken to re-test for turbidity;
- UV absorbance and UV transmissivity, as well as tannins and lignin, to determine potential for UV treatment as a disinfection option for this water system;
- Total organic carbon (TOC);
- EPH to determine if there are any signs of hydrocarbon contamination; and,
- Measurements in the field for total dissolved solids, conductivity, pH, and temperature.



Additional Analytical Results

A water sample obtained during the water system assessment on July 27, 2005 was submitted to ALS Environmental in Vancouver, BC for analysis. These results are summarized in Table 3125-2 in Appendix A14 and the laboratory reports are included in Appendix B.

- At 11.7 NTU, turbidity was in exceedence of the CDWQG MAC of 1.0 NTU;
- Concentrations of extractable petroleum hydrocarbons (EPH) were below analytical detection; and,
- All other health based and aesthetic objectives were met for the parameters analyzed.

14.3.3 Indicators of Potential Contamination

Chloride, nitrate and nitrite concentrations can indicate impacts from surfacewater sources or septic waste. Chloride concentrations were reported to be low and can be considered to be within the normal background ranges for groundwater in the area. Nitrate and nitrite concentrations for this sample were also low and within the normal background range for this area. These water quality results do not suggest that the aquifer from which the groundwater is obtained for the airport building is under the influence of surfacewater sources or septic wastes.

14.4 Conceptual Hydrogeology

There was no driller's well log available for review for this well. Most of the wells in the Beaver Creek area indicate coarse sand and gravel with cobbles and small boulders to depths of at least 30 m. The well logs also indicate that discontinuous lenses of finer-grained sediments persist throughout the area, but in general the sediments are dominated by coarse alluvium. Some discontinuous permafrost is also interpreted to persist throughout the Beaver Creek area. The variability of sediments in the Beaver Creek area indicates limited aquifer protection from surficial sources of contamination. A study had been previously completed in the Beaver Creek area by EBA, and it was determined that the direction of groundwater flow is north to northeasterly.



14.5 Potential Contaminant Sources

Potential contaminant sources from observations during the assessment are compiled in field notes in Appendix A14. Photos of potential contaminant sources are also provided in Appendix A14.

Potential contaminant sources within 30 m of the wellhead are:

- An above ground fuel storage tank (AST) at 5 m;
- Oil drums;
- Aircraft parking area;
- Vehicle parking area;
- Jet fuel storage area; and,
- Septic tanks located approximately 5 m from the well.

Additionally, septic discharge lines that run between the tank and the field are located within 10 m of the well and the septic field is approximately 54 m from the well.

14.5.1 Spills Records and Contaminated Sites Search Results

The Government of Yukon Environmental Programs Branch identified that on April 30, 2004, 3 L to 5 L of diesel fuel spilled on the south side of the terminal building when a tank overfilled. It is considered unlikely that this impacted on the groundwater quality at the site. No other spill records or contaminated sites issues were identified for this site.

14.6 Identified Water System Deficiencies and Associated Risk

14.6.1 High and Medium Risk Deficiencies

- Poor surface completion of the wellhead (located in a pit below grade);
- There is no surface sanitary seal (grout or bentonite seal as required by the Canadian Groundwater Association's Guidelines for Water Well Construction;
- By definition of the Draft Yukon GUDI Assessment Guideline, the well is potentially under the direct influence of surface water because it does not meet the requirements of the Guidelines for Water Well Construction;
- The well is located within 30 m of potential contaminant sources, including an above ground fuel storage at 5 m, aircraft and vehicle parking within 10 m, and oil and aviation fuel drum storage within 30 m;
- Although the septic field is located greater than 30 m likely downgradient from the well, the septic tank is located 5 m from the well which contravenes the proposed





- 85 -

Part III Small Public Drinking Water Guideline, and the existing Yukon Public Sewage Regulation which requires a 15 m setback;

- Total coliform bacteria were reported as present in one previous sampling event;
- Three independent sampling events reported turbidity to be above the CDWQG MAC. The most recent sampling event reported turbidity to be 11.7 NTU; and,
- There is no treatment or disinfection system present.

14.6.2 Low Risk Deficiencies

• There are no low-risk deficiencies associated with this site. All deficiencies are either high or medium risk.

14.7 Mitigative Options for Deficiencies

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

14.7.1 Priority 1

Recommended Priority 1 upgrades to mitigate immediate risk to the Beaver Creek Airport water system are summarized below:

- Confirm depth of well;
- Superchlorinate well and water system;
- Install chlorine tap at wellhead for future disinfection;
- Install an appropriately sized filtration (to 1 micron absolute) and NSF/ANSI 55 certified UV disinfection system. Based on water quality data it appears that pretreatment to ensure proper UV operation will not be required. These are conceptual design recommendations based on the information available for planning and budgeting purposes. Engineering input will be required for final system specifications.

14.7.2 Priority 2

Two potential options to mitigate potential long-term risk to the Beaver Creek Airport water system are presented below:



Option 1: Upgrade and Rehabilitate Well, Relocate Potential Contaminant Sources

The option of upgrading, rehabilitating and relocating potential contaminant sources is presented below:

- Camera well to determine well construction and condition;
- Chemically clean (pending camera investigation results);
- Standard wellhead upgrades consisting of a pitless unit installation, extending the casing to at least 500 mm above grade, and retrofitting of a surface sanitary seal (grout or bentonite to at least 3 m in depth);
- Relocate AST; and,
- Relocate septic tank.

Option 2: Construct New Well to Serve Airport Facility

This second option proposes that a new well be drilled to serve the airport, and that the existing well be properly decommissioned. It is recommended that the new well be installed to meet the following conditions:

- The well should be equipped with a surface seal to at least 6 m and the casing should be extended above grade (500 mm) within a lockable enclosure that is not inaccessible to animals and unauthorized personnel;
- The well must be located at a distance greater than 30 m from any potential source of contamination, including the above ground storage tanks and all parts of the septic system;
- The water from the new well must meet all CDWQG health based guidelines. If there are any exceedences in the CDWQG health-based guidelines then a treatment system must be designed and installed as necessary.

14.8 Cost Estimates for Mitigative Options

Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

14.8.1 Priority 1

Priority 1 costs are summarized below:

- The estimated cost for labour to superchlorinate the well and water system is approximately **\$200**;
- Installation of a chlorine tap at wellhead for future disinfection would cost approximately **\$200**;



• It is estimated that the installation of an appropriately sized NSF 61 filtration system (to 1 micron absolute) and an NSF/ANSI 55 certified UV disinfection system would cost \$3,000.

14.8.2 Priority 2

Priority 2 costs for each option presented above are as follows:

Option 1: Upgrade and Rehabilitate Well, Relocate Potential Contaminant Sources

Option 1 estimated costs are provided below:

- The estimated cost for standard wellhead upgrades is approximately **\$5,000**;
- The estimated cost to camera, redevelop and clean the well is **\$3000**; and,
- A Class D estimate of the cost to relocate all potential contaminant sources within 30 m of well would be in the order of **\$15,000**.

Option 2: Construct New Well to Serve Airport Facility

The estimated cost for the Option 1 which includes the construction of a new well to serve the Airport Terminal Building is approximately **\$30,000** for drilling, testing and hook-up, assuming that the well would be approximately 30 m deep and constructed as described above.

The existing treatment system (Priority 1) would be utilized for water system disinfection for each of the options presented above.









Z:\0201Drawings\1260002 Water Assessment YTG\003 -Western Region\beaver\1260002 B Crk Air Terminal_3125B Schematic.dwg, 4/4/2006 12:49:52 PM, Adobe PDF, jbuyck

July 2005

Western Region – Beaver Creek Air Terminal Building Building # 3125

DISTRIBUTION & TREATMENT SYSTEM DATA

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	SUB PUMP.	MONARCH	WKIZA5EX		834	4" - 1/2 /f.
2	PRESSURE TANK	CHALLENGER	PC 122			
3	PRESSURE SWITCH	Souther D	FSG-2			ZHP- 1/4" NPT
4	PRESSURE GAUGE	MARSH	0-100 PST			Z" - 1/4 "NPT
5						
6			· ·			
7						
8					- -	
9						
10				:		



Building #	Building Name	Number of Sampling Events	Time Period over which Sampling was Done	Any Positive Total Coliform Results? (yes or no)	Fraction of Positive Total Coliform Results vs. Total Sampling Events	Any positive E.Coli results? (yes or no)	Most Recent Sampling Event Available for EBA Review	Is Most Recent Result Positive?
3125	Beaver Creek Air Terminal Building	9	Sept-04 to Jun-05	yes	1/9	no	16-Jun-05	no

TABLE 3125- 1: SUMMARY OF BACTERIOLOGICAL RESULTS



Table 3125-2: Water Quality Results

SOURCE:	Building Air Te	3125 - Beav erminal Bui	ver Creek Iding			
Location/ Resident	В	eaver Cree	k			
Address						
l'reatment		None				
Distriection		None			.DwQ Crite	ria
Source of Water		On-site well				
Purpose of Sampling	Base Line	Base Line	Additional Analytical			
Sample Location			Washroom			
Date Sampled	21-Sep-04	15-Jun-05	27-Jul-05	Lower	Unper	Limit
Physical Tests (ALS)	LI Dep 01	15 5411 05	27-541-05	AO	MAC	AO
Colour (CU)	7	<5.0	-		,	15
Conductivity (uS/cm)		290	-			
Total Dissolved Solids	156	171	-			500
Hardness CaCO3	137	126	-	AO >200 = p	000 r , > 500 ur	acceptable ^A
рН	8.29	8.16	-	6,5		8.5
Tarbidity (NTU)	<u>4.1</u>	<u>3.29</u>	<u>11.7</u>		1	5
UV Absorbance			0.0060			
% UV Transmittance			98.6			
Ulssolved Anions (ALS)	120	110				
Auxannity-10tal CaCO3	<0.5	0.62				250
Fluoride F	<0.5	0.059			1.5	230
Silicate SiO4	.0,00	0.007	-			
Sulphate SO4	28.9	32.6	-			500
Nitrate Nitrogen N	0.2	0.22	-		10	
Nitrite Nitrogen N	< 0.05	<0.10	-		3.2	
Ammonia Nitrogen N			-			
Total Phosphate PO4						
T						
Aburiana TAL	<0.005	<0.010				
Antimony T-Sh	<0.003	<0.00050			0.006	
Arsenic T-As	0.0006	0.00041	-		0.025	
Barium T-Ba	0.011	< 0.020	-		1	
Boron T-B	0.026	<0.10	-		5	
Cadmium T-Cd	< 0.00001	< 0.00020	-		0.005	
Calcium T-Ca		39.3	-		-	
Chromium T-Cr	0.0005	<0.0020			0.05	
Copper T-Cu	0.059	0.102	-		1	
Iron T-Fe	0.27	0.209	<u> </u>		0.01	0.3
Lead 1-rD	0.0014	6.67	· · ·		0.01	
Manganese T-Mn	0.014	0.0090				0.05
Mercury T-Hg		<0.00020	-		0.001	
Potassium T-K		1.08	-			
Selenium T-Se		< 0.0010			0.01	
Sodium T-Na	3.0	2.5	-			200
Uranium T-U	<0.0005	0.00030			0.02	
Vanadium T-V	1.47	1.02				
Zinc I-Zn	1.4/	1.02				,
Organic Parameters			1			t
Tannin and Lignin			<0.10			
Total Organic Carbon C			0.90			
Extractable Hydrocarbons			<0.30		I	
EPH10-12			<0.30			
CFR19-32	l		<1.0		<u> </u>	
нерн						
Field Chemistry (EBA)						
pH			8.31	6.5		8.5
TDS (ppm)			127			500
EC (uS/cm)			17.5			
Free Available Chlorine	1		17.5			
Notae						

A. Guidelines indicated for hardness are not CDWQG, rather they are general aesthetic guidelines

- exceedences are indicated in yellow highlighting.

Italics and underline indicates exceedence of proposed MAC (ie. arsenic)

Bold with Yellow highlighting indicates exceedence of CDWQG Aesthetic Objective (AO)

Bold Underline with Yellow highlighting indicates exceedence of CDWQG MAC

Results are expressed as milligrams per litre except for pH and Colour (CU)

Conductivity (umhos/cm), Temperature (°C) and Turbidity (NTU)

< = Less than the detection limit indicated.

AO = Aesthetic Objective

MAC = Maximum Acceptable Concentration (Health Based)



Creating and Delivering Better Solutions

SMALL PUBLIC WATER SYSTEM ASSESSMENT

PART A: EBA Site Inspection

Inspector: Ryan Martin

Date July 27, 2005

WELL ID #	Owner	Location Description
3125	Y7G	Beaver Creek Airport Terminal Building

1. Well Location and Potential Contaminant Sources

a. General location of well: (Community, Subdivision, etc.) Beaver Creek

b. Specific location: (Road or street, Building number, name of owner and/, legal description, Mile 1204 Alaska Highway

c. G	PS location: N 6919562 E 507085 elv 654m ± 5m					
d	Is there electric power? Xes INO					
e	Is there outside water access? \$ The I No but is in locked enclosure on side of building					
f.	Does the well system have:					
□ 1	Airport Terminal Building					
\Box	5 or more delivery sites on a trucked distribution system? If so how many					
g.	Nearest building, specify <u>Airport terminal building</u>					
h.	Distance from well to building $\sim 2 \text{ M}$					
i. j.	If there is an effluent disposal field, is its location known? \cancel{K} Yes \square No Distance from well to nearest point of known field: $\sim 57 \text{ m}$ $(5 \text{ m} \text{ for } 4 \text{ mk})$					
k.	Well location relative to field: upslope downslope lateral					

Is there any part of a sewage disposal system(s)or other potential sources of pollution that may pose a 1.

hea	lth and safety risk within 30 m? 🛛 Yes 🗌 No
5	eptic tank @ 5m and service lines \$30m
m.	Is the well located within 300 m from a sewage lagoon or pit? \Box Yes \boxtimes No unlikely
n.	Is the well located within 120 m from a solid waste site or dump, cemetery? \Box Yes $\bigotimes_{v \in U} No$
0.	Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment plant designed and secured to prevent:
	Unauthorized access by humans? I Yes X No Entrance by animals? X Yes No Unlocked enclosure
p.	Is well site subject to flooding? Yes No
q.	Is the well site well drained? I Yes I No ground around well head is flat.
r.	Is there a buried fuel tank on the property? \Box Yes \Box No
	If yes, is it 🗋 in use 🗋 abandoned
	Is the location known? Yes No Distance from the well to known buried tank
s.	Are there any other known contaminant sources on the property?
	Yes No Describe
	If yes, specify the source: dump sewage lagoon cemetery other
	Potential Source 1: <u>AS7</u> ; Distance from well to Potential Source 1: <u>Sym</u>
	Potential Source 2: <u>orldrums</u> ; Distance from well to Potential Source 2: <u>30</u> m
	Potential Source 3: vehicle parking; Distance from well to Potential Source 3: 10 m
	Potential Source 4: <u>alrcraft parking</u> ; Distance from well to Potential Source 4: <u>5</u> m Avgas, jet fuel storage area within 30m
t.	Are there other wells on this property? \Box Yes \boxtimes No
	How many? in use abandoned require proper sealing

<u>2. v</u>	Vell and Wellhead information:				
a.	When was well installed? Year vnknown Month				
b.	Type: 🕅 drilled 🗆 dug 🗆 sand point 🗖 other				
c.	Is there a drillers log for the well: \Box Yes \swarrow No				
d.	Is there a surface seal to 6 m 🗌 Yes 🔯 No 🗍 unknown 🖾 unlikely				
e.	Surface casing: Yes Diameter No No				
f.	Well casing: Diameter <u>15 cm</u> Material: Steel plastic Concrete				
g.	Depth of well: $\underline{unknown}$ \Box measured (if possible) \Box reported \Box from log				
h.	Static water level below ground: Un Known				
	\Box measured (if possible) \Box reported \Box from log \Box flowing				
i.	(If granular) Is the well completed: \Box open end casing \Box with a well screen				
	\Box with slotted pipe \Box unknown other <u>unknown</u>				
j.	(If bedrock) Does the well have a liner? $\Box_{yes} \Box$ No $\Box_{steel} \Box$ plastic				
k.	If there is a well screen: length slot size(s) Location of screen: from to from log reported				
1.	Is there a sump below the screen? \Box Yes \Box No unknown				
m.	Is the well head: \Box in pumphouse \bigtriangledown in pit \Box pitless adaptor \Box in a building concrete pit				
	in a wooden enclosure other, describe				
n.	If the well head is located in a wooden enclosure,				

	i. Is the well head below grade? describe in detail ~ 1.15 m below grade
	ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? \square Yes \square No
	iii. Is the wellhead enclosed by fiberglass insulations? Yes D No
	iv. Any evidence of rodents? Specify No
	v. Does the well casing have a proper seal cap? \boxtimes Yes \square No
	If no, describe condition Salid plate cap
3. V	Vater Supplying This Well:
a.	By definition is the water from a surface water source or under the direct influence of surface water?
	\boxtimes Yes \square No \square farther investigation required.
	If yes is there treatment or disinfection \Box Yes \Box No
	Explain (filtration, disinfection etc)
<u>4.</u>	Aquifer Supplying This Well:
a.	The aquifer is: \Box bedrock \bowtie granular sediment \Box unknown $i i \mathcal{N}_e i \mathcal{V}_e$
b.	Does water level and/or well capacity show seasonal fluctuation? \Box Yes $\bigvee_{i \in V_{e}} No$
<u>5.</u>	Pump Installation:
a.	Is the well equipped with a pump? 🛛 yes 🛛 No
b.	Type of pump: hand Belectric submersible D jet
	□ shallow well centrifugal □ other,
c.	Description: Manufacturer Model
	horsepower capacity voltage
	//11
	·*/ 11

E	BA Engineering Consultants Ltd.
Cre	ating and Delivering Better Solutions
d.	Date installed: By:
e.	For submersible pump, depth of setting below surface
f.	Drop pipe for submersible pump: \Box steel \bigtriangledown plastic $likeky$
g.	Pump delivers water to: D pressure tank clevated tank clevated tank
h.	Are there automatic pump controls: 🖾 Yes 🗌 No
i.	Is there provision for taking water samples before water reaches storage? Yes No
j.	Is there a water meter on the system? \Box Yes \bowtie No
k.	Is the pump and piping protected from freezing? 🛛 Yes 🗌 No
	If yes, describe: In substion and heat trace
1.	Comments on pump installation:
<u>6.</u> a.	Conclusions Comments on overall installation:
b.F	Recommendations:
<u></u>	

EBA Engineering Consultants Ltd. Creating and Delivering Better Solutions PART B: EBA Site Inspection Inspector: BERT ALBISSER Date July 26 05 **Location Description** WELL ID # Owner YTG 3125 BEAVER CREEK AIRPORT Water Treatment 6. Is well water treated? Yes No; Type of treatment: a. □ chlorination □ iron and or manganese removal □ other Is water entering plumbing or piped distribution system treated with chlorine or another treatment that is Ь. as effective as chlorine used to achieve disinfection throughout the system? I No If so how_____ **Yes** If treated with chlorine, is the free residual chlorine concentration less than 0.2 mg/L c. Yes No _____reading. Tested at _____ (location) d. Is testing for chlorine residual concentration done at the tap (eg. Kitchen faucet) or from representative points in a piped distribution system, including a point from tap at the end line I No T Yes If yes how often? If the drinking water is being transported by water delivery truck does it have a minimum chlorine free e. residual of 0.4 mg/L at the time of fill. \Box Yes M No Water Quality (observations): 7. Does the water stain plumbing? Uyes No slight severe a. Type of stain: D brown D red black \square No \square occasional Constant Does the water contain sediment? UYes b.

6/11

Is there an unpleasant odour? \Box Yes \Box No \Box H₂S \Box Other

C.

d.	Is there an unpleasant taste? Yes No brackish Other
e.	Is there a history of bad bacterial analyses? Yes No ?
f.	Is there a chemical analysis? Yes No adequate incomplete
g.	Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? \Box Yes \Box No
h.	Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the
rang	ge 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? 🗌 Yes 🖸 No 🗹 unknown
i.	If yes is the test performed in accordance with manufactures directions? \Box Yes \Box No \Box unknown
j.	Is a record of the date, time, name of person performing the test and results of the drinking water sample
	kept? 🗌 Yes 🗖 No
	TANK AND PIPING DETAILS
	Tank Room
	Is there a water tank? Yes No Details: FRESURE TAJK
	Where is it located? Comments: MERHANICAR Room
	Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water? YES NO Comments:
	Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES NO
	Comments:
	Are there other heat sources near the tank? YES NO Comments:
	Is there waterproof flooring with a sealed base to contain spills? YES NO Comments:

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

Overall Tank

What are the tank size and dimensions?

What material is the tank constructed of?

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments: _____

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

See the second sec

Are there signs of staining or biofouling? YES NO Comments:_____

Is there any sediment or scum in bottom of tank? YES NO Comments: ______

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

 $\overline{\mathbf{v}}$

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

8. Conclusions

a. Comments on overall installation:

MORKMANSHIP & MATERIAL. THERE IS NO RENTMENT. b. Recommendations: INSPAN TREATMENT IF REQUIRED TO SUIT A LIV STERILIZER (NSF55 CERTFIED). INSTAN APPROPRIATE LIV STERILIZER TO SHIT FLOW REDYIRE MENTS.







