#### 10.0 BUILDING 4797: SWIFT RIVER UTILITY BUILDING 10.1 Description of Existing Water system

The water system for the Swift River Utility Building is supplied by a 23 m deep well located inside the pumphouse room of the utility building. The well location and other details about the surrounding area are provided in Figure 4797-A in Appendix A10. The coordinates of the wellhead were recorded as:

- UTM ZONE 9
- Northing: 6653544
- Easting: 377959

There is no treatment system present, and the water is stored in a 5800 L galvanized steel tank to serve the maintenance truck fill, and also serves the foreman's residence. A schematic detailing the water system is provided as Figure 4797-B in Appendix A10.

#### **10.2 Description of Existing Wastewater Systems**

A septic field that serves both the Swift River Living Complex and the foreman's residence is located approximately 60 m to the northeast of the utility building. A site plan showing the location of the septic system is given by Figure 4797-A in Appendix A10.

#### **10.3 Water Quality Results**

10.3.1 Water Quality Results from Previous Sampling

#### Bacteriological

Six samples were collected by YTG representatives from the Swift River Utility Building water system between September 2004 and March 2005 and were tested for total coliform and *E. coli* by Yukon Environmental Health Services using the presence/absence test method. Results are tabulated in Table 4797-1 in Appendix A10. *E. coli* bacteria were reported as absent in each of the six samples for which results were provided. One sample, however, taken November 9, 2004, tested positive for Total Coliform bacteria.



#### Potability

A water sample was collected by YTG representatives from the Swift River Utility Building water system on September 13, 2004 was submitted to Northwest Labs for detailed potability analyses. Additional analyses results were provided by YTG for a sample collected on June 22, 2005 from this system. The results of these analyses are summarized in Table 4797-2 in Appendix 10. EBA reviewed the analytical results to compare them with the Canadian Drinking Water Quality Guidelines (CDWQG) to observe general water quality, identify and recommend additional sampling, and to identify potential indicators of contamination.

- At 4.6 and 3.32 NTU, turbidity exceeded the CDWQG health based upper limit of 1.0 NTU;
- The water quality results indicated that all other health based and aesthetic objectives were met for the parameters analyzed. The total dissolved solids concentration was approximately 40 mg/L and is considered to be very fresh.
- The hardness (as CaCO<sub>3</sub>) was approximately 34 mg/L, and is considered very soft.

#### 10.3.2 Identification of Additional Analytical Testing Required

Additional analytical for the Swift River Utility Building that was identified to be included during the water system assessments is detailed below:

- UV absorbance, as well as tannins and lignin, to determine potential for UV treatment as a disinfection option for this water system;
- As turbidity had previously been in exceedence of CDWQG MAC, a subsequent sample was obtained;
- Total organic carbon (TOC), to assist in disinfection system selection; and,
- Measurements in the field for total dissolved solids, conductivity, pH, and temperature.



#### Additional Analytical Results

A water sample obtained by EBA during the field program on June 20, 2005 was submitted to ALS Environmental in Vancouver, BC for analysis of the previously mentioned additional parameters. These results are summarized in Table 4797-2 in Appendix A10 and the laboratory reports are included in Appendix B.

- At 2.69 NTU, turbidity was similar to the previous sample results, and above the CDWQG MAC; and,
- Field chemistry indicated that the temperature of the water at the point of consumption in the foreman's residence was 40.6 °C.

#### 10.3.3 Indicators of Potential Contamination

Chloride, nitrate and nitrite concentrations can indicate impacts from surface water sources or septic waste. Chloride concentrations were low and are considered to be within the normal background ranges for groundwater in the region.

No elevated concentrations of indicator parameters were observed in the sample results reviewed.

#### 10.4 Conceptual Hydrogeology

No log was available for this well, or any other wells in the Swift River area. This well is reported to be 23.0 m deep with a static water level of 4.41 m below ground. The direction of groundwater flow as inferred from topography and air photos is south towards the Swift River (40 m away).



#### **10.5 Potential Contaminant Sources**

Potential contaminant sources observed during the site investigation are provided in field notes in Appendix A10. Photos of potential contaminant sources are provided in Appendix A10.

A summary of potential contaminant sources within 30 m of the well is provided below:

- An oil heater at 3 m inside the same building;
- An above ground fuel storage tank at 4 m; and,
- An abandoned diesel tank at 10 m.

10.5.1 Spills Records and Contaminated Sites Search Results

The Government of Yukon Environmental Programs Branch and Environment Canada Environmental Protection Branch identified three spill events for sites neighbouring the Swift River Utility Building, and they are outlined below.

On August 17, 2000, 1 L of gasoline was reportedly spilled at the Swift River Lodge. This, however, likely poses a minimal risk to this water system.

On March 1, 1993, it was identified that approximately 250 L of calcium chloride solution had been accidentally dumped at the Swift River Lodge during a de-icing, but there had been no effort made to collect the solution. The runoff had reportedly travelled towards Swift River, downgradient from this well and would not likely have posed a risk to this water system.

On February 1, 1999, it was identified that approximately 10 L of diesel fuel was spilled at the Yukon Electric Company facility when an EnviroTank was overfilled. The contaminated snow was reportedly removed and this spill likely poses a minimal risk to this water system. This spill location is likely greater than 60 m cross-gradient from this well.



#### **10.6 Identified Water System Deficiencies and Associated Risk**

10.6.1 High and Medium Risk Deficiencies

The following deficiencies were identified as high or medium risk for the Swift River Utility Building:

- Poor surface completion of the well (well casing is completed at grade and without a well cap);
- The well is not equipped with a surface sanitary seal as required by the Canadian Groundwater Association's Well Construction Guidelines;
- By definition of the Draft Yukon GUDI Assessment Guideline, the well is potentially under the direct influence of surface water because it is a vulnerable type (unconfined aquifer), and does not meet the requirements of the Guidelines for Water Well Construction;
- The turbidity has been in exceedence of CDWQG MAC;
- A positive total coliform count has been reported;
- There is no treatment or disinfection system present;
- The well is located within 30 m of potential sources of contamination, including an oil heater, an above ground fuel storage tank, and an abandoned diesel tank;
- The pressure tank is of galvanized steel construction, which, is not suitable for drinking water storage; and,
- There are several other open holes in the concrete slab floor of the utility building (potentially abandoned wells) that could act as conduits for contamination to enter the subsurface.

#### 10.6.2 Low Risk Deficiencies

The following deficiencies were identified as low-risk for the Swift River Utility Building:

• The heat trace on the piping to the foreman's residence is left on at all times of the year. If the water is stagnant in the piping for any period of time then the water at the point of consumption is very hot. Aside from this being non-aesthetically pleasing and uneconomical, it likely also leads to accelerated encrustation and biofouling.



#### **10.7 Mitigative Options for Deficiencies**

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

10.7.1 Priority 1

The existing water system at the Swift River Utility Building should not be used for potable water due to poor construction and proximity to potential contaminant sources. It is recommended that the foreman's residence be disconnected from this system. The well at the utility building should only be used as a source of non potable water such as road watering and vehicle cleaning. Wellhead upgrades for should be completed, however, in order to protect the aquifer. There are two options being presented to provide the foreman's residence with a water supply.

#### **Option 1:**

The existing well at the Swift River Living Complex has better water quality and is considered less vulnerable to contamination. This option proposes that the living complex well be used to supply the foreman's residence. During the water system assessment it appeared that the Complex well had the least deficiencies and had superior water quality to the other YTG maintained wells in Swift River. This option would involve the following:

- Further study would have to be done on the living complex well in order to determine that the Complex well is suitable to serve the other YTG maintained buildings at Swift River. This would involve obtaining the well log in order to determine the depth, and other wellhead construction details that were unavailable during this assessment. Sustainable well yield would also need to be verified by pumping tests;
- The wellhead at the living quarters requires improvement. Upgrades would involve installing a surface sanitary seal (grout or bentonite) to a depth of at least 3 m, and extending the well casing at least 500 mm above grade;
- A underground piped water distribution line should be installed, and should be properly freeze-protected through heat-trace and insulation; and,
- An NSF/ANSI 55 certified UV disinfection system complete with NSF-61 certified pre-filtration to 1 micron absolute should be installed near the point of entry in the Swift River Living complex.



#### **Option 2:**

The second option considered involves construction of a new well. A new well could potentially be used to supply all the YTG maintained buildings in Swift River, including the grader station, living complex, and foreman's residence. The new well should be constructed in consideration of the following recommendations:

- The well should be equipped with a surface seal to at least 6 m and the casing should be extended above grade (500 mm) within a lockable enclosure that is inaccessible to animals and unauthorized personnel;
- The well should be located upgradient from the current well and must be greater than 30 m from any potential source of contamination;
- The water from the new well must meet all CDWQG health based guidelines. If there are any exceedences in the CDWQG health-based guidelines then a treatment system must be designed and installed as necessary; and
- An NSF/ANSI certified UV disinfection system should be installed at a centralized location complete with adequate NSF approved pre-filtration.

10.7.2 Priority 2

There are no Priority 2 recommendations for this site, assuming that Priority 1 recommendations are carried implemented.

#### 10.7.3 Priority 3 – Low Risk

Low-risk deficiencies would also be mitigated when Priority 1 mitigative options are carried out. There are no Priority 3 recommendations.

#### **10.8** Cost Estimates for Mitigative Options

Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

10.8.1 Priority 1

The estimated cost to upgrade the wellhead in the utility building to protect the aquifer, and to disconnect the Foreman's residence from this water system would

1260002002\_Eastern\_Draft\_Report\_April\_6.doc



cost about **\$1,000**. Class D cost estimates for all other upgrade options are outlined below.

#### **Option 1:**

Some of the costs associated with this option depend on whether or not the Swift River Grader Station will also be supplied by the living complex well (costs to this system that can be distributed among multiple sites are reported as the average of the cost with two systems and the cost with three systems).

- Obtaining the well log, an additional site inspection, and additional water system assessment, would cost in the order of **\$2,000**. This cost could be divided equally among the buildings proposed to be supplied by the living complex well, and would be approximately **\$800**;
- The cost associated with improving the living quarters well would be in the order of **\$5,000**. This cost could be divided equally among the buildings supplied by the living complex well, and would be approximately **\$2,100**;
- Approximately 90 m of water distribution line, assuming \$120 per metre (installed in shallow trench with required frost protection) would cost about **\$10,800**;
- The proposed disinfection system to serve this water system would cost approximately **\$1500**.

#### **Option 2:**

- It is recommended that **\$30,000** be budgeted for materials and labour to drill, test, and complete the well. Since this well would serve three sites, the cost to this system would be approximately **\$10,000**;
- Approximately 200 m of water distribution line would be required to serve all three buildings, and assuming \$120 per metre, this would cost approximately **\$24,000**. Since this well would serve three sites, the cost to this system would be approximately **\$8,000**;
- The proposed disinfection system to serve this water system would cost approximately **\$1500**.









#### Eastern Region – Swift River Utility Building Building # 4797

#### **DISTRIBUTION & TREATMENT SYSTEM DATA**

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	SUB PUMP	MONARCH	SBILDISE	-	Z8 92	<b>A</b> "
2	PRESSURG SWITCH	Sa. D	GSG-Z	ZZ4330		
3	PRESSURE GAMER	MARSH	0-100			211
4	PRESSURE TANK	N(A.	LARGE			14' x 41
5	PRUSSURE TAND	CHAUENGER	PC 66			DOMESTIC
6	PRESSURE GALLE	5 0-100	4" Din			K
7						
8						
9						
10						



		Number of	<b>Time Period</b>	Any Positive	Fraction of	Any positive	Most Recent	ls Most
		Sampling	over which	<b>Total Coliform</b>	Positive	E.Coli results?	Sampling Event	Recent Result
		Events	Sampling	Results?	Total	(yes or no)	Available for	Positive?
			was Done	(yes or no)	Coliform		EBA Review	
					Results vs.			
					Total			
					Sampling			
					Events			
Building #	Building Name							
	Swift River Utility		Sept-04 to	VOR	1/6	<b>n</b> 0	9-Mar-05	<b>n</b> 0
4797	Building	6	Mar-05	yes	1/0	no	3-Iviai-03	110

#### TABLE 4797- 1: SUMMARY OF BACTERIOLOGICAL RESULTS



AdaceSum 1MaineSum 1Marcel VanSum 1Sum 2Sum 1Sum 2Sum 2 </th <th></th> <th></th> <th></th> <th>quanty</th> <th>liteouno</th> <th></th> <th></th>				quanty	liteouno		
AddressAutomation	I antim/ Paridant		Outife Divers				
AddressAttrave<	Location/ Resident		Swiit River				
NumberNoCOUNTLYPartor diversionNon-Adding Addin	Address Treatment	km 11	81 Alaska H	lighway			
Domain of the sectorDescription of the sectorDescription of the sectorSerie of the sectorNumber of the sectorNumber of the sectorSerie of the sectorNumber of the sectorNumber of the sectorSerie of the sectorNumber of the sectorNumber of the sectorSerie of the sectorNumber of the sectorNumber of the sectorSerie of the sectorNumber of							
Nerrent interpretation of the series of	Disinfection		NO		G	CDWQ Criter	ia
Proof suppleNome Nome Nome Nome 	Source of Water		On-Site We				
One of the part of the pa	Purpose of Sampling	Baseline	Additional	Baseline			
SampleJongJongJongJongJongJongJongPart MathII </td <td>r in pose of biampining</td> <td>Dischine</td> <td>Foreman's</td> <td>Duscinc</td> <td></td> <td></td> <td></td>	r in pose of biampining	Dischine	Foreman's	Duscinc			
Backgroup15.50015.50015.50015.50015.50015.50015.500Call778881013.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.503.50Call3.503.503.503.503.503.503.50 <td< td=""><td>Sample Location</td><td></td><td>Kesidence Kitchen Tap</td><td></td><td></td><td></td><td></td></td<>	Sample Location		Kesidence Kitchen Tap				
Control <t< td=""><td>Date Sampled Physical Tests (ALS)</td><td>13-Sep-04</td><td>20-Jun-05</td><td>22-Jun-05</td><td>Lower Limit</td><td>Upper MAC</td><td>Limit</td></t<>	Date Sampled Physical Tests (ALS)	13-Sep-04	20-Jun-05	22-Jun-05	Lower Limit	Upper MAC	Limit
Dension (Note)01/2000 <td>Colour (CU)</td> <td>7</td> <td></td> <td>&lt;5</td> <td></td> <td>Mile</td> <td>15</td>	Colour (CU)	7		<5		Mile	15
haloCACDCACDCACDCACDCACDCACDSASASASALadar, OTO6.0070.007	Conductivity (uS/cm) Total Dissolved Solids	40		72.3 43			500
Data         Desc         Desc         Desc         Desc         Desc           Stansing         Desc         Desc         Desc         Desc         Desc           Stansing         Desc         Desc         Desc         Desc         Desc           Mainery Desc         Desc         Desc         Desc         Desc         Desc         Desc           Mainer Desc	Hardness CaCO3	32.6		34	AO >200 = po	or, > 500 unace	eptable <sup>A</sup>
Dyy MachineDDDDFrameworkAAAAARando Maio (A)AAAAAChain (C)AAAAAAChain (C)AAAAAAChain (C)AAAAAASolar (C)AAAAA </td <td>pri Turbidity (NTU)</td> <td>4.6</td> <td><u>2.69</u></td> <td><u>3.32</u></td> <td>0.5</td> <td>1</td> <td>5</td>	pri Turbidity (NTU)	4.6	<u>2.69</u>	<u>3.32</u>	0.5	1	5
Anal.etImageImageImageImageAnal.et	UV Absorbance % Transmittance		0.027				
Akaday rol737742.6756757750750Dank P0720.6720.6721.5500Dank P0720.6720.6721.5500Dank P0.720.6720.6721.6500Nata Nang N-0.110.101.01.01.0Nata Nang N-0.110.101.01.01.0Ameen Naty N0.011.00.001.01.0Ameen Naty N0.0070.0000.001.01.0Ameen Naty N0.0020.00010.0001.01.0Ameen Naty N0.0020.00010.0001.01.0Ameen Naty N0.0020.00010.0001.01.0Ameen Naty N0.0010.0001.00.051.0Ameen Naty Naty Naty Naty Naty Naty Naty Naty	Dissolved Anions (ALS)						
JamasJongJongJongJongJongJongJongShaha336336332JongJongShaha336332JongJongJongShaha336336332JongJongShaha337JongJongJongJongShahaJongJongJongJongJongShahaJongJongJongJongJongShahaJongJongJongJongJongShahaJongJongJongJongJongShahaJongJongJongJongJongShahaJong	Alkalinity-Total CaCO3	37		42.6			250
No. 50.01No. 7.32No. 7	Fluoride F	0.72		0.692		1.5	230
Name Normage<	Silicate SiO4 Sulphate SO4	3.56		3.32			500
Auenak Songe NIndIndIndIndIndIndIndAuenam TAN0.007	Nitrate Nitrogen N Nitrite Nitrogen N	<0.1 <0.05		<0.10 <0.10		10	
International of the set of	Ammonia Nitrogen N						
tat Mamin TA10.007-0.000Allong TS0.0020.00010.00010.00010.0001Jamo TS0.00120.00010.00010.0001Bren TB0.0010.00010.00010.0001Calum TCA0.00010.00010.00010.0001Calum TCA0.00010.00010.00010.0001Calum TCA0.00010.00010.00010.0001Calum TCA0.00010.00040.0010.001Calum TCA0.00010.00040.0010.001Magner TAN0.0110.01040.0110.011Magner TAN0.0110.00030.0100.011Magner TAN0.0110.00030.0100.011Magner TAN0.0110.00030.0100.011Magner TAN1.80.00030.0120.001Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0120.011Magner TAN1.80.00030.0110.011Magner TAN1.80.00030.0110.011Magner TAN1.80.00030.0110.011 <td>coal ritophate PO4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	coal ritophate PO4						
Anome AccesControlContr	Total Metals (ALS) Aluminum T-Al	0.007		< 0.010			
PartsDataDataDataDataCalumC.Q.Q.Q.0.005C.G.Q.Q.0.005Calum T.C0.0001-0.00201C.G.Q.Comm T.C0.00020.00521C.G.Q.Comm T.C0.00030.00211C.G.G.Calum T.C0.00140.00140.0140.01Calum T.G.0.0210.00140.0140.01Marger Hig0.0211.00440.010.01Marger Hig0.0211.00440.010.01Marger Hig0.0210.00100.0010.05Paster T.S.1.8-0.020.0010.01Stam T.S.1.8-0.020.0010.01Stam T.S.1.8-0.020.010.01Stam T.S.1.8-0.010.010.01Stam T.S.1.8-0.011.81.8Stam T.S. <td>Antimony T-Sb Arsenic T-As</td> <td>&lt;0.0002</td> <td></td> <td>&lt;0.0005</td> <td> </td> <td>0.006</td> <td></td>	Antimony T-Sb Arsenic T-As	<0.0002		<0.0005		0.006	
nomNotitCAUMCAUMSCAUM100001000050000500005CAUM1000030000020.00.0CAUM000130000020.00.0Part Tr0.0230.000040.010.0Marger TAM0.010.00140.010.0014Marger TAM0.010.00140.010.010Marger TAM0.010.0180.0010.001Marger TAM0.010.0020.0010.001Marger TAM0.0050.00200.0020.001Marger TAM0.0050.00030.020.000Marger TAM1.80.00030.020.000Marger TAM1.80.00030.020.000Marger TAM1.80.00030.020.02Samar TU0.0050.00030.020.02Yamin TV0.0050.00030.020.02Yamin TV0.0050.00030.020.02Yamin TV0.0050.00030.020.02Yamin TV0.0050.00030.020.02Yamin TV0.010.0050.00030.02Yamin TV0.010.0050.00030.02Yamin TV0.010.010.0010.000Yamin TV0.010.010.0000.000Yamin TV0.010.010.0000.000Yamin TV0.010.010.010.01Yamin TV	Barium T-Ba	0.012		0.020		1	
Channe T-Co.ODDSII.0ODDSODDSODDSCorpor T-Co.0.0330.0320.0530.010.031Car T-Fo.0.0310.0340.010.0110.0140.01Lan T-Fo.0.0010.0040.0010.0010.0010.001Magnine T-Fo.0.0010.0020.0020.0010.001Magnine T-Fo.0.0010.0020.0020.0010.001Magnine T-Fo.0.0010.0020.0020.0010.001Marine T-Fo.0.0010.0020.0020.0010.001Marine T-Fo.0.0010.0020.0020.0010.001Marine T-Fo.0.0030.0020.0020.0010.001Marine T-Fo.0.0030.0020.0020.0010.001Marine T-Fo.0.0030.0030.0030.0030.001Marine T-Fo.0.0030.0030.0030.0030.003Marine T-Fo.0.0030.0030.0030.0030.003Marine D-Fo.0.0030.0030.0030.0030.003Marine D-Fo.0.0030.0030.0030.0030.003Marine D-Fo.0.0030.0030.0030.0030.003Marine D-Fo.0.0030.000.0030.0030.003Marine D-Fo.0.010.010.010.010.01Marine D-Fo.0.010.010.010.010.01Marine D-Fo.0.0	Boron T-B Cadmium T-Cd	0.011		<0.010 <0.00020		5 0.005	
Copy         From         0.023         0.0392         1         mathematical state of the st	Calcium T-Ca Chromium T-Cr	< 0.0005		11.0 <0.0020		0.05	
no.no.no.no.no.no.Magner Tak0.0110.01480.0150.005Magner Tak0.0210.01480.0050.001Magner Tak0.020.00100.001Panama TA0.0050.00100.01Scham Tas0.0050.00030.002Scham Tas1.8<.0010	Copper T-Cu Iron T-Ea	0.023		0.0392		1	0.3
Magener TAgIIISAIIMaray TAgO.21O.0140.0130.01Maray TAgO.21O.00180.010.01Maxam TAIO.00030.010.01Maiam TAIO.00030.000.01Sam TAIO.00030.000.01TagC.200.00030.000.00TagC.200.00030.000.00TagC.200.00030.000.00TagC.200.00030.000.00TagC.200.00030.000.00TagC.200.000.00030.00TagC.200.000.00030.00TagC.200.000.000.00TagC.200.000.000.00Mainen DaC.20C.200.000.00Annin DAC.20C.20C.200.00Annin DAC.20C.20C.200.00Annin DAC.20C.20C.200.00Calaim DCC.20C.20C.20C.20Calaim DCC.20C.20C.20C.20Calaim DCC.20C.20C.20C.20Calaim DAC.20C.20C.20C.20Mayere DAC.20C.20C.20C.20Mayere DAC.20C.20C.20C.20Mayere DAC.20C.20C.20C.20Mayere DAC.	Lead T-Pb	0.23		0.235		0.01	0.5
herrory Trigorcontrol0.0000.001Steinan Txa1.8<.0000	Magnesium T-Mg Manganese T-Mn	0.021		1.56 0.0148			0.05
SectorT.S.I.B.I.O.DODO.D.DVanion T.V.<10005	Mercury T-Hg Potassium T-K	-		<0.00020 0.32		0.001	
Solam         1/20         1/20         1/20         1/20           Vandam         TV         0.0005         0.0005         0.0005         0.0005           Yandam         1007         0.076         0.076         0.076         0.076           Yandam         0.010         0.096         0.000         0.000         0.000           Samara         0.000         0.000         0.000         0.000         0.000           Maimam, D.A         0.000         0.000         0.000         0.000         0.000           Maimam, D.A         0.000         0.000         0.000         0.000         0.000           Barin         D.B         0.000         0.000         0.000         0.000         0.000           Galiam D.C         0.000         0.000         0.000         0.000         0.000         0.000           Galiam D.C         0.000	Selenium T-Se	1.0		<0.0010		0.01	200
Vandem TAVDOTSDOTSDOTSDOTSDOTSSAminen Matinam DADADADADADAAminen DASDADADADADAAtoms DASDADADADADAAtoms DASDADADADADAAtoms DASDADADADADAAtoms DASDADADADADABana DBDADADADADACalaim DCADADADADADACalaim DCADADADADADACalaim DCADADADADADACalair DASDADADADADACalair DASDADADADADACalair DASDADADADADAMagnere DMADADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADADAMaray DJIDADADADAMaray DJIDA	Uranium T-U	<0.0005		0.00038		0.02	200
Desired Marka         Image         Image <thimage< th="">         Image</thimage<>	Vanadium T-V Zinc T-Zn	0.073		0.096			5
Number         DA1         Image         Image <thi< td=""><td>Dissolved Metals</td><td></td><td></td><td></td><td></td><td></td><td></td></thi<>	Dissolved Metals						
Annino DAS	Aluminum D-Al						
Barin D.B.         Image D.B.         Image D.B.         Image D.B.           Cathiam D.C.         Image D.B.         Image D.B.         Image D.B.           Choreine D.C.         Image D.P.         Image D.P.         Image D.P.           Image D.P.         Image D.P.         Image D.P.         Image D.P.           Image D.P.         Image D.P.         Image D.P.         Image D.P.           Mage D.P.         Image D.P.         Image D.P.         Image D.P.           Marcey D.P.         Image D.P.         Image D.P.         Image D.P.           Marcey D.P.         Image D.P.         Image D.P.         Image D.P.           Marcey D.P.         Image D.P.         Image D.P.         Image D.P.           Station D.N.         Image D.P.         Image D.P.         Image D.P.           Station D.P.         Image D.P.         Image D.P.         Image D.P.           Station D.P.         Image D.P	Antimony D-Sb Arsenic D-As						
CalairDCdImage: Delta of the sector of	Barium D-Ba Boron D-B						
Decision DCO         Image by the second of the second	Cadmium D-Cd Calcium D-Ca						
Caye         D-Cs         Image: D-Cs         Image: D-Cs           Lad         D-P6         Image: D-Cs         Image: D-Cs           Magencin         D-P6         Image: D-Cs         Image: D-Cs           Magencin         D-F6         Image: D-Cs         Image: D-Cs           Selom         D-S         Image: D-Cs         Image: D-Cs           Tad Trabinethans         Image: D-Cs         Image: D-Cs         Image: D-Cs           Chone Consorts         Image: D-Cs         Image: D-Cs         Image: D-CS         Image: D-CS           Chone Consorts         Image: D-CS         Image: D-CS         Image: D-CS         Image: D-CS           Chone Consorts         Image: D-CS         Image: D-CS         Image: D-CS         Image: D-CS           Chone Consorts         Image: D-CS<	Chromium D-Cr						
Lad         DPs           Magacine         DMs           Magacine         DMs           Magacine         DMs           Magacine         DMs           Magacine         DMs           Nation         DMs           Steluim         DAs           Steluim         DA           Steluim	Copper D-Cu Iron D-Fe						
Magner DMa         Image         Image <thimage< th="">         Image         Image</thimage<>	Lead D-Pb Magnesium D-Mg						
Jong	Manganese D-Mn						
Scheim DAs	Potasium D-K						
UnationD.UImageImageImageZaxDataImageImageImageZaxDataImageImageImageZaxDataImageImageImageThabarechaneImageImageImageImageBronscherhameImageImageImageImageBronscherhameImageImageImageImageDetromscherhameImageImageImageImageDetromscherhameImageImageImageImageDetromscherhameImageImageImageImageTamin and LipinImageImageImageImageTamin and LipinImageImageImageImageTamin and LipinImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImageImageBromscherhameImageImageImage <td>Selenium D-Se Sodium D-Na</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Selenium D-Se Sodium D-Na						
Zam         D-Za         Image: Same sector of the sector o	Uranium D-U Vanadium D-V						
Tablemethan         Image of the second blocks of the second block o	Zinc D-Zn						
Bander Advocations         Image: Control of the sector of the secto	Trihalomethanes						
Classifier         Image: Classifier         Image: Classifier           Tail Trichauschase:         Image: Classifier         Image: Classifier           Tail Trichauschase:         Image: Classifier         Image: Classifier           Orgaic Parameters         Image: Classifier         Image: Classifier           Tail Trichauschase:         Image: Classifier         Image: Classifier           Paloychauschase:         Image: Classifier         Image: Classifier           Tail Trichauschase: </td <td>Bromodichloromethane Bromoform</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Bromodichloromethane Bromoform						
Table Transmerson         Image: Second	Chloroform Dibromochloromethane						
Organic Parameters               Linnin and Lyain:         <0.10	Total Trihalomethanes						
tama actignm         <.0.10            Call Ognic Cabo         0.70             Banacki Colo         0.70              Banacki Colo         0.70               Banacki Colo                 Banacki Colo <td< td=""><td>Organic Parameters</td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	Organic Parameters						
Idencit Acid         Idencit Acid         Idencit Acid           Bromschleracit Acid         Idencit Acid         Idencit Acid           Bromschleracit Acid         Idencit Acid         Idencit Acid           Dichonacit Acid Acid         Idencit Acid         Idencit Acid           Acraphalizes         Idencit Acid         Idencit Acid           Barti Acid Acid         Idencit Acid         Idencit Acid           Barti Acid Acid         Idencit Acid         Idencit Acid           Barti Acid Acid Acid         Idencit Acid         Idencit Acid           Barti Acid Acid Acid         Idencit Acid Acid Acid         Idencit Acid Acid Acid           Barti Acid Acid Acid Acid Acid Acid Acid Aci	Fannin and Lignin Total Organic Carbon C		<0.10 0.70				
Descrick Add         Image of the second base of the seco	Haloacetic Acids						
District Add         Image	Bromoacetic Acid						
Determine And	Chloroacetic Acid						
Tachleroscik Add (TCA)  Physycle Aramatic Hydrocarbos  Physycle Aramatic Hydrocarbos  Ascraphbox  Ascraphox  Ascraphbox  Ascraphbox  Ascraphbox  Ascra	Dibromoacetic Acid Dichloroacetic Acid					·	
Phytyck Aromatic Hydrocarbos   <	Trichloroacetic Acid (TCA)						
National Stress         Image of the stress	Polycyclic Aromatic Hydrocarbons						
Aninkees         Image: Constraint of the second secon	Acenaphthylene						
Bactionariances         Image: Second press	Acridine Anthracene	L					
Base         Image         Image <thi< td=""><td>Benz(a)anthracene Benzo(a)nyrene</td><td></td><td></td><td></td><td> </td><td>-</td><td>-</td></thi<>	Benz(a)anthracene Benzo(a)nyrene					-	-
procession/opcycle@	Benzo(b)fluoranthene						
Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Phorenatheme         Image: Chryster         Image: Chryster         Image: Chryster           Phorenatheme         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Phorenatheme         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Phorenatheme         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Phorenatheme         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Quanditie         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Statistic Hydercarboux         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Extractable Hydercarboux         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Extractable Hydercarboux         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Extractable Chryster         Image: Chryster         Image: Chryster         Image: Chryster         Image: Chryster           Extractable Chryster         Image: Chryster	Benzo(k)fluoranthene						
Phonome         Phonome <t< td=""><td>Chrysene Dibenz(a,h)anthracene</td><td></td><td></td><td></td><td></td><td>·</td><td></td></t<>	Chrysene Dibenz(a,h)anthracene					·	
indext(12)-cdayres              Naphalades               Press         0.1              Quoinfanc	Fluoranthene Fluorene					-	-
Autonome         0.1           Parenatheres         0.1           Quinding         0.1           Extractable Hydrocarboas         0.1           Extractable Hydrocarboas         0.1           EM10-10         0           EM201-20         0           EM301-20         0           EM301         0.5           EM301         500           EC (Scing)         82           Transpersame (CO)         40.6           Pare Availly Clubrice         0           Memore         0	Indeno(1,2,3-c,d)pyrene						
Dyrac         Operation         Operation         Operation           Candidate         Construction         Construction         Construction           Extractable Hydrocarbons         Construction         Construction         Construction           Difful 0-10         Construction         Construction         Construction         Statistical Construction           Difful 0-10         Construction         Construction         Statistical Construction         Statistical Construction           Difful 0-10         Construction         Construction         Construction         Construction           Difful 0-10         Construction         Construction         Construction         Construction         Construction	rvapnthalene Phenanthrene					0.1	
Extratable Physicachons         Image: Construction of the second se	Pyrene Quinoline	L_					
FMI0-19         Image: Constraint of the second	Extractable Hydrocarbons						
permission         permiss	EPH10-19						
BH2P1         Image: Construct of the second se	LEPH19-32 LEPH						
Field Chemistry (EBA)         7.43         6.5         8.5           pit         7.43         6.5         8.5           TSK (ppm)         4.1         500         500           EC (65:m)         8.2         500         7           Temperature (°O)         40.6         90         90           Pirek Available Chlorine         90         90         90	HEPH						
image         image         0.3         8.3           ToS (ppm)         4.1         500           EC (65:m)         8.2         50           Temperature (°O)         40.6         50           Pires Available Ollorine         50         50	Field Chemistry (EBA)		7 4 2		65		85
Rc. (uo.rm)         8.2           Temperature (°C)         40.6           Piece Available Chlorine	TDS (ppm)		41				500
Free Available Chlorine	EC. (uS/cm) Temperature (°C)		82 40.6				
11072	Free Available Chlorine						

Table 4797-2: Water Quality Results

# A. Guidelines indicated for hardness are not CDWGG, rather they are general aesthetic guid exceedences are indicated in yolivo highlighting. (<u>Indica</u>, and underline indicates exceedence of Cryoces MAC (is arenic)). Bold with Yeldow highlighting indicates exceedence of CDWGG Asthetic Objective (AO) <u>Bold Underline with Yellow</u>, highlighting indicates exceedence of CDWGG Asthetic Objective (AO) <u>Bold Underline with Yellow</u>, highlighting indicates exceedence of CDWGG Asthetic Objective (CO) Conductivity (Imdication), Tergenerature (<sup>CO</sup>) and Turbidity (NTU) < = Less than the detection limit indicated. AO = Asthetic Objective MAC = Maximum Acceptable Concentration (Health Based).



# Table 4797-3: Summary of Well Assessment ResultsSMALL PUBLIC DRINKING WATER SYSTEMS

We	ll Identificat	tion		GPS Coord	inates
Building #	Building Name	Location	Northing (+/- 10 m)	Easting (+/- 10 m)	Grade Elevation (+/- 10 m)
4797	Utility Building	Swift River	6643544	377959	884

			We	ell Details			
Well Casing Diameter (mm)	Year Well Installed	Well Log?	Well Depth (m bg)	Reported Low Permeabilty Protective Layer?	Pump Setting (m bg)	Well Capacity - Tested, or Reported by User	Static Water Level Below Ground (m-btwc)
150		No	23	Unknown	10.11		4.41

	Р	otential Cor	ntaminant S	ources	
Distance from well to nearest point of septic field (m)	Distance from well to nearest building (m)	Distance to surface water body (m)	AST present on property?	Distance from well to AST (m)	Other potential sources of contamination observed on property, and distance to well
	Inside utility	40 m to Swift	AST	4	01111 - 10
60	building	River	Abandoned Diesel Tank	10	Oil Heater at 10 m

		We	ll Construct	tion Details	
Wellhead Above ground (m)	Well Cap	Well Screen	Surface Seal	Apron Grading	Comments
Wellhead is at grade	No			Concrete floor around well is not sloped	Well services a highway maintenace truck fill and the forman's residence. The heat trace to the residence had been left on at the time of inspection so all water was hot.



#### SMALL PUBLIC WATER SYSTEM ASSESSMENT

PART A: EBA Site InspectionInspector: Ryan MartinLuke Lebel -			
	WELL ID #	Owner	Location Description
	4797	YTG	Swift River Utility Building
ı. <u>v</u>	Vell Location and Potentia	al Contaminant Sources	
a.	General location of well: Swift River	(Community, Subdivisio	n, etc.)
b.	Specific location: (Road of Swift River,	or street, Building number Alaska Hwy	r, name of owner and/, legal description,
c. G	PS location: N 6653	544 E 377950	1 elv 884m ±6
1	Is there electric power?	Yes D	No
e	Is there outside water acco	ess? 🗆 Yes 🕅	No
f.	Does the well system have	<del>2</del> :	
□1  -	5 or more service connections or eman's Residence	ns to a piped distribution s + fill line	ystem? If so how many
	5 or more delivery sites on	a trucked distribution sys	tem? If so how many
g.	Nearest building, speci	ify inside utilit.	y building
h.	Distance from well to bui	lding	·
i.	If there is an effluent disp	osal field, is its location k	nown? X Yes INO
j.	Distance from well to nea	rest point of known field:	60m
k.	Well location relative to f Slight	ield: Dupslope J Cownslope	図 downslope 図 lateral N 6653545 E 377976

### EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

1. Is there any part of a sewage disposal system(s) or other potential sources of pollution that may pose a

hea	Ith and safety risk within 30 m? $\Box$ Yes $\Box$ No
100	Lae septic >50m, sever proe @ 35m
m.	Is the well located within 300 m from a sewage lagoon or pit? $\Box$ Yes $\boxtimes$ No
n.	Is the well located within 120 m from a solid waste site or dump, cemetery? $\Box$ Yes X No
0.	Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment
	plant designed and secured to prevent:
	Unauthorized access by humans? I Yes I No Entrance by animals? I Yes I No inside locked building Access possible
p.	Is well site subject to flooding? I Yes No no sighs of ponding
q.	Is the well site well drained? A Yes I No
r.	Is there a buried fuel tank on the property? $\Box$ Yes $\bowtie$ No $vh kely < 150m$
	If yes, is it 🗌 in use 🗌 abandoned
	Is the location known? $\Box$ Yes $\Box$ No
	Distance from the well to known buried tank
s.	Are there any other known contaminant sources on the property?
	Yes No Describe
	If yes specify the source: dump sewage lagoon cemetery other
	Potential Source 1: $0$ ; heater; Distance from well to Potential Source 1: $5$ m
	Potential Source 2: $A ST$ ; Distance from well to Potential Source 2: $Y M$
	Potential Source 3: (aban donned); Distance from well to Potential Source 3: (C in
	Potential Source 4: Julif Kiver ; Distance from well to Potential Source 4: 102
t.	Are there other wells on this property? Ares INO possible - There is pipene may
	How many? [I in use A abandoned require proper sealing
	- living complex + grader sta wells >150m

<u>2. v</u>	Vell and Wellhead information:
a.	When was well installed? Year unknown Month
b.	Type: A drilled $\Box$ dug $\Box$ sand point $\Box$ other
c.	Is there a drillers log for the well: $\Box$ Yes $$ No
d.	Is there a surface seal to 6 m $\Box$ Yes $\widecheck{\Delta}$ No $\Box$ unknown $\grave{\Delta}$ unlikely
e.	Surface casing:  Yes Diameter  No
f.	Well casing: Diameter $\frac{15 \text{ cm}}{15 \text{ cm}}$ Material: 🖾 steel 🗆 plastic $\Box$ concrete
g.	Depth of well: $10.11 \text{ measured (if possible)} $ reported $\square$ from log
h.	Static water level below ground: 4. 41m Je
	$\swarrow$ measured (if possible) $\Box$ reported $\Box$ from log $\Box$ flowing
i.	(If granular) Is the well completed: $\Box$ open end casing $\Box$ with a well screen
	with slotted pipe unknown other unknown
j.	(If bedrock) Does the well have a liner? $\Box_{yes} \Box$ No $\Box_{steel} \Box$ plastic
k.	If there is a well screen: length _vn h vo vn slot size(s) Location of screen: from to from log reported
1.	Is there a sump below the screen? I Yes I No Unknown
m.	Is the well head: $\Box$ in pumphouse $\Box$ in pit $\Box$ pitless adaptor $\widecheck{\Delta}$ in a building
	in a wooden enclosure other, describe
n	If the well head is located in a wooden enclosure

	i. Is the well head below grade? describe in detail at grade approx.
	ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? $\Box$ Yes $\widecheck{\boxtimes}$ No
	iii. Is the wellhead enclosed by fiberglass insulations? $\Box$ Yes $\bowtie$ No
	iv. Any evidence of rodents? Specify Access possible, bt no evidence
	v. Does the well casing have a proper seal cap?  Yes X No
	If no, describe condition Steel 11d above casing
<u>3. V</u>	Water Supplying This Well:
a.	By definition is the water from a surface water source or under the direct influence of surface water?
	$\checkmark$ Yes $\square$ No $\square$ farther investigation required.
	If yes is there treatment Tyes X No
	Explain (filtration, disinfection etc)
<u>4.</u> /	Aquifer Supplying This Well:
a.	The aquifer is: $\Box$ bedrock $\bowtie$ granular sediment $\Box$ unknown $like/\gamma$
b.	Does water level and/or well capacity show seasonal fluctuation? $\Box$ Yes $\bowtie$ No $vhknewr$
<u>5.</u>	Pump Installation:
a.	Is the well equipped with a pump? X yes INO
b.	Type of pump: hand Relectric submersible D jet
	shallow well centrifugal other,
c.	Description: Manufacturer Model
	horsepower capacity voltage
	4/11

	5 5	
d.	Date installed:	By:
e.	For submersible pump, depth of setting	ng below surface
f.	Drop pipe for submersible pump: $\Box$ s	steel D plastic
g.	Pump delivers water to: Dipressure to	e tank delevated tank dother truck fril
h.	Are there automatic pump controls: $\Sigma$	Yes I No
i.	Is there provision for taking water samp	mples before water reaches storage?□ Yes⊠ No
j.	Is there a water meter on the system?	TYes No
k.	Is the pump and piping protected from	n freezing? 🛛 Yes 🛛 No
	If yes, describe: <u>Heater</u> - n	na insulation or heat trace
1.	Comments on pump installation:	
<u>6. (</u>	<u>Conclusions</u>	
a. (	omments on overall installation:	
b.R	ecommendations:	
		······································

DA	ating and Delivering Better So	lutions		
	RT B: EBA Site Inspectio	<u>n</u>		
Ins	pector: BIERT AL	BISSER	Da	te JUNE ZO 05
	WELL ID #	Owner	1 1	( acation Description
	4797	YTG	SWITT	RIVER UTILTY BL
	L			
6.	<u>Water Treatment</u>	/		
a.	Is well water treated?	Yes 🗹 No; Type	of treatment:	
	$\Box$ chlorination $\Box$ iror	and or manganese ren	noval 🗌 o	ther
b.	Is water entering plumbing	or piped distribution s	ystem treated w	th chlorine or another treatment t
	as effective as chlorine u	used to achieve disinfed	tion throughou	t the system?
		If so how		
		11 30 110 w	• • •	
c.	If treated with chlorine, is t	the free residual chlorin	e concentration	1 less than 0.2 mg/L
	□ Yes □ No	readiu	ıg.	
	Tested at		(location)	
d.	Is testing for chlorine residu	al concentration done	at the tan (eq. K	itchen faucet) or from representat
ч.	points in a piped distribution	n system, including a p	oint from tap at	the end line
			-	
	∐ Yes ∐ No	If yes how of	ten?	
e.	If the drinking water is bein	ng transported by water	delivery truck	does it have a minimum chlorine
e.	If the drinking water is bein residual of 0.4 mg/L at t	ng transported by water the time of fill. $\Box$ Ye	r delivery truck s □ No	does it have a minimum chlorine
e.	If the drinking water is bein residual of 0.4 mg/L at t	ng transported by water he time of fill.	r delivery truck s □ No	does it have a minimum chlorine
e. 7.	If the drinking water is bein residual of 0.4 mg/L at t <u>Water Quality (observation</u>	ng transported by wates the time of fill.  □ Ye <u>ons):</u>	r delivery truck s □ No	does it have a minimum chlorine
е. 7. а.	If the drinking water is bein residual of 0.4 mg/L at t <u>Water Quality (observation</u> Does the water stain plumb	ng transported by wates the time of fill.	s □ No	does it have a minimum chlorine
е. 7. а.	If the drinking water is bein residual of 0.4 mg/L at t <u>Water Quality (observation</u> Does the water stain plumb	ng transported by wates the time of fill.	s □ No	does it have a minimum chlorine
e. 7. a.	If the drinking water is being residual of 0.4 mg/L at the <b>Water Quality (observation</b> ). Does the water stain plumber Type of stain:	ng transported by water the time of fill.  Ye ons): oing?  yes  No brown  red	r delivery truck s □ No slight □ seve □ black	does it have a minimum chlorine
e. 7. a.	If the drinking water is being residual of 0.4 mg/L at the <b>Water Quality (observation</b> ) Does the water stain plumb Type of stain:	ng transported by water the time of fill. <b>ons):</b> bing? yes No brown red iment? Yes	r delivery truck s □ No slight □ seve □ black No □ occas	does it have a minimum chlorine re ional 🔲 constant
e. 7. a.	If the drinking water is being residual of 0.4 mg/L at the second of 0	ng transported by water the time of fill. <b>ons):</b> oing? yes No brown red iment? Yes	delivery truck s I No slight seve black No ccas	does it have a minimum chlorine re ional Constant

d.	Is there an unpleasant taste? Yes No brackish Other				
e.	Is there a history of bad bacterial analyses? $\Box$ Yes $\Box$ No				
f.	Is there a chemical analysis? $\Box$ Yes $\Box$ No $\Box$ adequate $\Box$ incomplete				
g.	Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? $\Box$ Yes $\Box$ No				
h.	Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the				
rang	ge 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L?  Yes No unknown				
i.	If yes is the test performed in accordance with manufactures directions? $\Box$ Yes $\Box$ No $\Box$ unknown				
j.	Is a record of the date, time, name of person performing the test and results of the drinking water sample kept? $\Box$ Yes $\Box$ No				
	TANK AND PIPING DETAILS				
	Tank Room Is there a water tank? Yes No Details: PRESSURE TANK				
	Comments: UTILITY BLDG.				
	Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water? YES NO Comments:				
	Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES				
2	NO				
	Comments:				
	Are there other heat sources near the tank? YES O				
	Is there waterproof flooring with a sealed base to contain spills? YES NO				

### EBA Engineering Consultants Ltd.

**Creating and Delivering Better Solutions** 

#### **Overall** Tank

What are the tank size and dimensions?

16' Lx

What material is the tank constructed of? Gmv. Steel

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES

Comments:

#### Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

#### WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO Comments:

Is there any sediment or scum in bottom of tank? YES NO Comments:

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

### EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

#### 8. Conclusions

a. Comments on overall installation:

WERL IS AT FLOOR LEVER. PRESSURE TANK TON DRINKING WARDE. SUT ABUS or IS No IN PLACE TRAFT MENT HERE No SEAL on WEU OAN I TAM

b. Recommendations: END CALING TO PROFER HEIGHT. Sy stom SEM NITARY WATE SEDMER 174 UT 0 APPROPMANE 125 Supply ALL DOMESTIC REAT MENT



Environment Environnement Canada Canada

### Spill Report Information

#### Enforcement and Emergencies Section 91782 Alaska Highway, Whitehorse, YT Y1A 5B7 PH: 867.667.3400 FAX: 867.667.7962

Spill #	9321
Jurisdiction	Yukon
Community	
Address	
Highway	Alaska Highway
Milepost	M 733
Feature	Swift River
Location and Cause	Swift River Lodge - de-icing operation being conducted without collection of solution
Latitude	60.0080555555556
Longitude	-131.1841666666667
Incident Date	3/1/1993
Lead Agency	Environment Canada - Environmental Protection Service
Other Agency	
Company(s)	Swift River Lodge
Amount	250
Units	Litres
Quantity	Estimate
<b>Release Description</b>	Dumped
Additional Quanitit	
Concentration	
<b>Concentration Unit</b>	
Phase	Liquid
Major Contaminant	Calcium Chloride
2nd Contaminant	
3rd Contaminant	
4th Contaminant	
Outcome	de-icing solution not being contained - no runoff to river yet but potential - advised operation to be moved and solution contained - toxic to fish

Wednesday, July 13, 2005



Environment Environmement Canada Canada

### Spill Report Information

Enforcement and Emergencies Section 91782 Alaska Highway, Whitehorse, YT Y1A 5B7 PH: 867.667.3400 FAX: 867.667.7962

Spill #	9902
Jurisdiction	Yukon
Community	Swift River
Address	
Highway	Alaska Highway
Milepost	M 733
Feature	Swift River
Location and Cause	YECL Envirotank overfilled - tanker truck driver unsure of storage tanks capacity
Latitude	60.004
Longitude	-131.1864
Incident Date	2/1/1999 11:50:00 AM
Lead Agency	Yukon Government - Environmental Programs
Other Agency	
Company(s)	Healey Enterprises (Fort Nelson, BC)
Amount	10
Units	Litres
Quantity	Estimate
<b>Release Description</b>	Spilled
Additional Quanitit	
Concentration	
Concentration Unit	
Phase	Liquid
Major Contaminant	Diesel
2nd Contaminant	
3rd Contaminant	
4th Contaminant	
Outcome	fuel ran down sides of tank into snow - contaminated snow to be recovered and free product soaked up - pump shut off as soon as fuel came out vent - no further information







