4.0 BUILDINGS M0107, M0108, AND M0109 – TESLIN RCMP DETACHMENT AND RESIDENCES

4.1 Description of Existing Water system

Water well M0107 serves three RCMP buildings including the Teslin RCMP Detachment (Building M0107) and two Teslin RCMP Residences (Buildings M0108 and M0109). The well is located approximately 5 m from the RCMP Detachment, as shown on Figure M0107-A in Appendix A4, and is completed with a pitless connection. However, the wellhead is located in a pit below grade and the well casing does not extend above ground level. All three buildings are equipped with a water softener, but at the time of inspection only the softener in Building M0108 appeared to be functional. Each of the residences (M0108 and M0109) are equipped with reverse osmosis (RO) systems to provide drinking water to dedicated point of use taps in each of the kitchens. Schematics detailing the water systems are given by Figure M0107-B, and M0109-B in Appendix A4.

There is also an abandoned well that is located in a below grade add-on from the basement of the M0109 RCMP Residence. The well is equipped with a proper cap, but it has yet to be properly decommissioned. The well was reported in the drillers log to be 143 m deep, but when measured during the site inspection was only 37 m deep, indicating that the well had been inundated with sediment and/or debris since it was abandoned. This well would require extensive rehabilitation if it were to be re-commissioned.

4.2 Description of Existing Wastewater Systems

All three RCMP buildings (M0107, M0108 and M0109) are connected to the community sewage collection system with the sewer main located along Johnson Street. The well is located approximately 40 m east of the sewer main.



4.3 Water Quality Results

4.3.1 Water Quality Results from Previous Sampling

A total of twenty bacteriological samples were taken from the three buildings served by this water system between September 2004 and March 2005. The test results did not indicate any positive coliform or *E. coli* results for samples collected from any of these systems. A summary of historical bacteriological results is presented in Table M0107-1 in Appendix A4.

Detailed potability analyses were performed on samples collected from the three RCMP buildings on September 9, 2004. The results are presented in Table M0107-2 in Appendix A4, and summarized in the following:

- The groundwater supplied by well M0107 is very hard and highly mineralized;
- The TDS concentration exceeded the CDWQG aesthetic objective (AO) of 500 mg/L in all three buildings;
- The hardness was observed to be approximately 440 mg/L in buildings M0107 and M0108, but only 1.7 mg/L in M0109. These extremely high hardness concentrations indicate the need for properly operating water-softening systems. Based on water quality results, the water softening systems for M0107 and M0108 did not appear to be functioning properly, however, the softener for M0109 did appear operational. Problems associated the softeners might be resolved by replacing the regenerant but may require further assessment.
- The sodium concentration from the M0109 water system was reported as 166 mg/L. Although the sodium concentration is below the CDWQG aesthetic objective of 200 mg/L, it should be noted that there might be some health effects for some people associated with elevated sodium in their diet. Potassium chloride would be a regenerant alternative to reduce sodium levels.
- The total and dissolved arsenic concentrations were below the current CDWQG MAC of 0.025 mg/L, but were greater than the proposed MAC of 0.005 mg/L for samples collected from all three buildings;
- The total and dissolved manganese concentrations exceeded the CDWQG AO of 0.05 mg/L for samples collected from RCMP buildings M0107 and M0108. The total manganese concentrations were below the CDWQG AO for samples collected from building M0109;

1260002002_Eastern_Draft_Report_April_6.doc



• All other parameters analyzed were below the applicable CDWQG criteria for the sample(s) submitted.

4.3.2 Identification of Additional Analytical Required

Additional parameters requiring analysis were identified prior to and/or during the site inspection and included UV absorbance, silicate, ammonia, phosphate, vanadium and confirmation of manganese and arsenic concentrations. These parameters were analyzed to confirm previous results and will be used in future disinfection system selection.

Samples for additional analytical testing were obtained by EBA during the water system assessment on June 16, 2005. Analytical results are presented in Table M0107-2 in Appendix A4, and laboratory reports are summarized in Appendix B. Results are summarized below:

- Arsenic concentrations, although not above the current CDWQG MAC of 0.025 mg/L, were observed to be above the proposed MAC of 0.005 mg/L. The concentrations of dissolved arsenic with respect to total arsenic indicated that the arsenic concentration in this well water could be almost entirely attributed to dissolved particles;
- Manganese concentrations were above the CDWQG aesthetic objective of 0.05 mg/L at each of the buildings; and,
- Measurements in the field indicated that pH at the M0107 RCMP detachment and the M0109 residence (8.66 and 8.72), were above the CDWQG aesthetic objective of 8.5. Laboratory results, however, reported the pH below 8.5 and the field pH values may be within the error of the instrument.

4.3.3 Indicators of Potential Contamination

The chloride concentrations in samples collected from taps supplied by well M0107 were observed to be greater than 20 mg/L. This may be associated with the use of water softener, but appears to be more likely representative of the aquifer chloride concentrations. Chloride concentrations in this range may occur naturally in groundwater, but may also be an indication of impacts from surface sources of contamination such as road salting, septic disposal, and/or other human activities.



4.4 Conceptual Hydrogeology

The site is located near the center of a small peninsula extending into Teslin Lake. In general, there are two primary aquifer zones identified by previous EBA studies in the Teslin area. These zones may be generalized as shallow unconfined aquifer(s) and deeper confined aquifer(s). Based on topography and proximity to surface water, the groundwater flow direction in the vicinity of the site is inferred to be southerly, but may possibly range from westerly to easterly.

4.5 Potential Contaminant Sources

Potential contaminant sources observed during the site investigation are compiled in field notes provided in Appendix A4. Photos of potential contaminant sources are also provided at the end of this appendix.

Potential contaminant sources within 30 m of wellhead M0107 (the well currently servicing the three buildings) included:

• Three above ground fuel storage tanks (ASTs).

Potential contaminant sources within 30 m of wellhead M0109 (the abandoned well) included:

• Three above ground fuel storage tanks (ASTs).

In addition, the community sewer main is located within about 40 m of well M0107 and approximately 55 m from well M0109.

4.5.1 Spills Records and Contaminated Sites Search Results

The Environment Canada Environmental Protection Branch did not identify any contaminated sites issues for this site or neighboring sites. Spill records for nighbouring sites were identified.

On four separate occations raw sewage was spilled at lift station 2 on Jackson Avenue, approximately 175 m from the active well on this site. It is unlikely that these spills impacted on groundwater quality at this site.

 $1260002002_Eastern_Draft_Report_April_6.doc$



4.6 Identified Water System Deficiencies and Associated Risk

- 4.6.1 High and Medium-Risk Deficiencies;
 - Wellhead M0107 is below grade in a well pit.
 - From observations made during the field investigation, and given general well construction techniques employed at the time that this well was drilled, it is considered very unlikely that a surface sanitary seal was installed as required by the Canadian Groundwater Association Guidelines for Water Well Construction.
 - By definition of the Draft Yukon GUDI Assessment Guideline, the well is potentially under the direct influence of surface water because it is a vulnerable type (unconfined aquifer) and does not meet the requirements of the Guidelines for Water Well Construction.
 - Lack of disinfection for the water system from well M0107.
 - Non-functional water softening systems.
 - Proximity of well to three ASTs.
 - Abandoned well M0109 not properly decommissioned.

4.6.2 Low Risk Deficiencies

- Arsenic concentrations in exceedence of proposed MAC.
- Total dissolved solids and manganese in exceedence of CDWQG AO.
- pH in exceedence of CDWQG AO for M0107 and M0109 from field chemistry.

4.7 Mitigative Options for Deficiencies

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

4.7.1 Priority 1

The Priority 1 upgrades recommended for this site to immediately mitigate high or medium risk deficiencies consist of:

• The water system should be superchlorinated;



- The existing softener systems should be brought back into service and maintained as necessary so that UV disinfection systems will function properly. Sodium levels should be monitored and residents advised when they are higher than 20 mg/L, so they can contact their physicians and get instructions regarding water intake; and,
- UV disinfection systems should be installed following each pretreatment softener system.

4.7.2 Priority 2

- The wellhead at M0107 should be extended to a minimum of 500 mm above the surrounding grade, and the well pit should be backfilled with a low-permeability material to provide a surface seal around the well casing;
- A NSF-61 certified filtration system (to 1 micron absolute) should be installed in the RCMP detachment to serve that building, and another filtration system should also be installed in the M0109 residence to serve both RCMP residences;
- Well M0109 should be decommissioned in accordance with Guidelines for Water Well Construction; and,
- The above ground fuel storage tank located near the RCMP garage should be moved to a suitable location greater than 30 m from the well and preferably downgradient. Alternatively, secondary containment could be installed at the AST.
- 4.7.3 Priority 3
 - A reverse osmosis treatment system should be installed in the RCMP detachment to provide point of use drinking water; and,
 - Improve operation and/or replace water-softening systems. The water softener for the M0109 RCMP residence can likely be replumbed to serve both residences.

The recommendations pertaining to water system upgrades provided above are considered conceptual based on the information available and are intended for planning and budgeting purposes. Engineering input will be required for final treatment system design.



4.8 Cost Estimates for Mitigative Options

Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

4.8.1 Priority 1

- Supply and installation of UV disinfection systems would cost in the order of **\$4,400** for both systems, and,
- Required maintenance to reactivate the softener systems and system superchlorination would cost approximately **\$400**.

4.8.2 Priority 2

- Standard wellhead upgrades would cost in the order of **\$3,000** for materials and labour;
- NSF 61 certified filtration systems would cost approximately **\$1,500** each;
- Properly decommissioning the existing well in the M0109 residence would cost in the order of **\$1,000**; and,
- To move the AST servicing the RCMP garage to a location greater than 30 m from the well, or to install secondary containment would cost in the order of \$1,000.

4.8.3 Priority 3

- Installing a reverse osmosis system in the RCMP detachment building would cost in the order of **\$600**.
- Repairing the water softeners would be covered by normal operation and maintenance costs.











Eastern Region – R.C.M.P. Detachment Building # M0107

DISTRIBUTION & TREATMENT SYSTEM DATA

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	Sur Pump	NA	NIA			4"-IHD.
2	PRESSURE TANK.	WELL RITE	WR 140			
3	PRESSURE SWITCH	59. D	F5G-2			240- 1/4"FIPT
4	PRESSURE GAMBE	MARSH	0-100			2" - 1/4" MIP
5	WATER SOFTNER	NOVATER	HISOMI		206674	50K
6						
7						
8						
9						
10						



0201-1260002.002

May 2005

Eastern Region - R.C.M.P. Housing Building # M0108

DISTRIBUTION & TREATMENT SYSTEM DATA

ltem	Description	Manufacturer	Model	Part No.	Serial No.	Size
1			,,,			
2	PRESSURE TANK	CHALLENGER	PC266			11/4" FIFT
3	WATER SOFTENER	NOVATER	HT50MI		Z06675	50K
4	REVERSE OSMOSIS	HYDROTECH	ETFC-Z4			Z4GPD.
5						
6						
7						,
8						
9						
10						

SOFTUER REMOVED FOR SEPAIR



Eastern Region – R.C.M.P. Housing Building # M0109

DISTRIBUTION & TREATMENT SYSTEM DATA

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	WATER FILTER	AMETER	10"BB			11/z-10"
2	PRESSURE TANK	CHALLENGER	PCZ66			114" F.PT
3	WATER SOFTENER	NOVATER	HTSOMI		206675	SOK
4	REVERSE OSMOSIS	HYDROTECH	ETFC-ZA			Z4GPD
5						
6						
7						
8						
9						
10						



		Number of	Time Period	Any Positive	Fraction of	Any positive	Most Recent	Is Most
		Sampling	over which	Total Coliform	Positive	E.Coli results?	Sampling Event	Recent Result
		Events	Sampling	Results?	Total	(yes or no)	Available for	Positive?
			was Done	(yes or no)	Coliform Results vs. Total Sampling		EBA Review	
					Events			
Building #	Building Name							
M0107	R.C.M.P Detachment	7	Sept-04 to Mar-05	no	0/7	no	1-Mar-05	no
M0108	R.C.M.P Housing	7	Sept-04 to Mar-05	no	0/7	no	1-Mar-05	no
M0109	R.C.M.P Housing	6	Sept-04 to Mar-05	no	0/6	no	1-Mar-05	no

TABLE M0107- 1: SUMMARY OF BACTERIOLOGICAL RESULTS



Table M0107-2: Water Quality Results

SOURCE:	Building R.C.M.P. D	M0107 - etachment	Building R.C.M.P.	M0108 - Housing	Building R.C.M.P.	M0109 - Housing			
Location/ Resident	Tes	slin	Tes	slin	Te	slin			
Address	Bloc	k 11	Bloc	k 12	Bloc	k 13			
	Water Soft	ener (not in	Water Soft	ener (not in	Water Soft	ener, Filter,			
Treatment	us	e)	use)	, RO	R	0			
Disinfection	N	0	N	0	N	0	GG	CDWQ Criter	ia
Source of Water	M010	7 Well	M010	7 Well	M010	7 Well			
Purpose of Sampling	Bacelina	Additional	Receline	Additional	Bacalina	Additional			
r ur pose or sampling	Daseillie	Downstairs	Dasemie		Daseinie	Sampling			
		Laundry Tub							
Sample Location		Тар		Kitchen Sink		Kitchen Tap			
Date Sampled	9-Sep-04	16-Jun-05	9-Sep-04	16-Jun-05	9-Sep-04	16-Jun-05	Lower Limit	Upper	Limit
Physical Tests (ALS)							AO	MAC	AO
Colour (CU)	<5.0		<5.0		<5.0				15
Total Dissolved Solids	502		506		617				500
Hardness CaCO3	442		440		1.7		AO >200 = poo	or, > 500 unaco	ceptable ^A
pH	8.3		8.3		8.47		6.5		8.5
Turbidity (NTU)	0.7		0.8		0.4			1	5
UV Absorbance		0.0260		0.0280		0.0260			
Dissolved Anions (ALS)									· · · · · · · · · · · · · · · · · · ·
Alkalinity-Total CaCO3	229		229		227			_	
Chloride Cl	20.7		21.2		22.1			1.5	250
Fluoride F	0.18	12.5	0.18	14.4	0.18	14.2		1.5	
Silicate SiO4	190	13.5	104	14.4	104	14.3			500
Suprate SO4	189 <0.1		194		194			10	. 500
Nitrite Nitrogen N	<0.0		<0.05		<0.1			10	
Ammonia Nitrogen N	-0.05	0.293	-0.05		-0.05				
Total Phosphate PO4		0.0576		0.0593		0.0686			
								-	
Total Metals (ALS)									
Aluminum T-Al	< 0.005		< 0.005		< 0.005			0.1	
Antimony T-Sb	<0.0002		< 0.0002		< 0.0002			0.006	
Arsenic T-As	0.0067	0.00849	0.0083	0.00861	0.0074	0.00736		0.025	
Barium T-Ba	0.052		0.049		< 0.001			1	
Boron T-B	0.03		0.028		0.026			5	
Chromium T-Cd	<0.0001		<0.00001		0.00001			0.005	
Conner T-Cu	<0.0007		<0.0010		<0.0012			1	
Iron T-Fe	0.05		0.14		<0.001			1	03
Lead T-Pb	0.0006		<0.0001		<0.001			0.01	0.2
Manganese T-Mn	0.077	0.0891	0.079	0.0915	< 0.005				0.05
Sodium T-Na	23.7		23.3		166				200
Uranium T-U	< 0.0005		< 0.0005		< 0.0005			0.02	
Vanadium T-V		0.033		< 0.030		< 0.030			
Zinc T-Zn	0.003		0.002		0.003				5
Dissolved Metals		0.00700		0.00011				0.005	
Arsenic D-As		0.00798		0.00811		0.00773		0.025	0.05
Manganese D-Mn		0.0897		0.0905					0.05
Organic Parameters		·							
Tannin and Lionin		0.56		0.68		<0.10			
Total Organic Carbon C		2.78		1.71		1.87			
Field Chemistry (EBA)									
pH		8.66		8.35		8.72	6.5		8.5
TDS		405		406		480			500
EC (uS/cm)		810		815		958			
Temperature (°C)		10							

Notes:

A. Guidelines indicated for hardness are not CDWQG, rather they are general aesthetic guidelines - exceedences are indicated in yellow highlighting.

Italics and underline indicates exceedence of proposed MAC (ie. arsenic)

Bold with Yellow highlighting indicates exceedence of CDWQG Aesthetic Objective (AO)

Bold Underline with Yellow highlighting indicates exceedence of CDWQG MAC

Results are expressed as milligrams per litre except for pH and Colour (CU), Conductivity (umhos/cm), Temperature (°C) and Turbidity (NTU)

< = Less than the detection limit indicated.

AO = Aesthetic Objective

MAC = Maximum Acceptable Concentration (Health Based)



SMALL PUBLIC WATER SYSTEM ASSESSMENT

Ì

PA	RT A: EBA Site Inspect	on	
Ins	pector: Ryan Martin	<u> </u>	Date June 16, 2005
	WELL ID #	Owner	Location Description
	M 0107	R.C.M.P	Teslin RCMP Detachment
1. <u>\</u>	Vell Location and Potenti	al Contaminant Sourc	es
a.	General location of well: Teslin	(Community, Subdivis	sion, etc.)
b.	Specific location: (Road Johnson Arenve	or street, Building num	ber, name of owner and/, legal description,
c. (JPS location:		
d	Is there electric power?	Yes 🗆] No
e	Is there outside water acc	ess? 🛛 Yes 🗆] No
f.	Does the well system hav	e:	
	15 or more service connection and Services MO107 p	ons to a piped distribution retachment, and	n system? If so how many Molog and Molog Residences
	5 or more delivery sites on	a trucked distribution s	system? If so how many
g.	Nearest building, spec	ify Teslin RCMP	Detachment
h.	Distance from well to but	lding ~ 5 m	
i.	If there is an effluent disp	oosal field, is its location	n known? 🗆 Yes 🕅 No
j. k.	Well location relative to	field: upslope	downslope lateral

Creating and Delivering Better Solutions
1. Is there any part of a sewage disposal system(s)or other potential sources of pollution that may pose a
health and safety risk within 30 m? A Yes INO
m. Is the well located within 300 m from a sewage lagoon or pit? \Box Yes \bigotimes No
n. Is the well located within 120 m from a solid waste site or dump, cemetery? \Box Yes $\overleftarrow{\Box}$ No
 Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment plant designed and secured to prevent:
Unauthorized access by humans? I Yes No Entrance by animals? Yes No No Access likely possible, but no eviden
p. Is well site subject to flooding? \Box Yes $\overleftarrow{\Delta}$ No
q. Is the well site well drained? \swarrow Yes \Box No
r. Is there a buried fuel tank on the property? \Box Yes $\boxtimes N_0 \longrightarrow W^{k_0} \gamma$
If yes, is it 🛛 in use 🖓 abandoned
Is the location known? Yes No Distance from the well to known buried tank
s. Are there any other known contaminant sources on the property?
□ Yes □ No Describe
If yes, specify the source: \Box dump \Box sewage lagoon \Box cemetery \Box other
Potential Source 1: $A571$; Distance from well to Potential Source 1: $\sim 9 \text{ m}$ inside build
Potential Source 2: $\frac{457}{2}$; Distance from well to Potential Source 2: $\frac{6}{10}$
Potential Source 5: <u>A 5 1</u> ; Distance from well to Potential Source 5: <u></u>
t. Are there other wells on this property? \bowtie Yes \square No

How many? Molog well	in use 🖾	abandoned 🛛	require proper sealing
----------------------	----------	-------------	------------------------

<u>2. </u>	Well and Wellhead information:
≭ a.	When was well installed? Year Month
b.	Type: A drilled and dug sand point other
c.	Is there a drillers log for the well: \Box Yes $\widecheck{\Delta}$ No
d.	Is there a surface seal to 6 m \Box Yes \Join No \Box unknown \bigstar unlikely
e.	Surface casing: Yes Diameter No
f.	Well casing: Diameter $\frac{15 \text{ cm}}{15 \text{ cm}}$ Material: 🗹 steel \Box plastic \Box concrete
≯ g.	Depth of well:
¥ h.	Static water level below ground:
	\square measured (if possible) \square reported \square from log \square flowing
∦ i.	(If granular) Is the well completed: \Box open end casing \Box with a well screen
	□ with slotted pipe □ unknown other
<mark>⊁-</mark> j.	(If bedrock) Does the well have a liner? $\Box_{yes} \Box$ No $\Box_{steel} \Box$ plastic
¥k.	If there is a well screen: length slot size(s) Location of screen: from to from log reported
★ 1.	Is there a sump below the screen? \Box Yes \Box No
m.	Is the well head: 🗆 in pumphouse 🕅 in pit 🖾 pitless adaptor 🗆 in a building
	in a wooden enclosure other, describe
n	If the well head is located in a wooden enclosure

	i. Is the well head below grade? describe in detail piping 2.20m below grade	
	ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? \Box Yes 🕅 No	
	iii. Is the wellhead enclosed by fiberglass insulations? Xes I No likely within enclosed	re
	iv. Any evidence of rodents? Specify No	
	v. Does the well casing have a proper seal cap? \square Yes \square No $S_p^{1/4}$ Seal gastle f If no, describe condition	
3	ater Supplying This Well:	
a	By definition is the water from a surface water source or under the direct influence of surface water?	
	Yes No farther investigation required.	
	If yes is there treatment I Yes INO MOIO7 - Boftening, but non-functional MOIO8 - Softening, but non-functional	
	Explain (filtration, disinfection etc) Morog - softening	
4	quifer Supplying This Well:	•
∦a	The aquifer is: \Box bedrock \overleftarrow{X} granular sediment \Box unknown	
ł	Does water level and/or well capacity show seasonal fluctuation? \Box Yes \boxtimes No $Ohlikely$	
5	Pump Installation:	
8	Is the well equipped with a pump? \square yes \square No	
ł	Type of pump: hand Relectric submersible ist	
	□ shallow well centrifugal □ other,	
c	Description: Manufacturer Model	
	horsepower capacity voltage	
	4/11	

d.	Date installed: By:
e.	For submersible pump, depth of setting below surface
f.	Drop pipe for submersible pump: \Box steel \swarrow plastic $\frac{l/ke}{\gamma}$
g.	Pump delivers water to: D pressure tank clevated tank clevated tank
h.	Are there automatic pump controls: \square Yes \square No
i.	Is there provision for taking water samples before water reaches storage? Use No hone observed
j.	Is there a water meter on the system? \Box Yes \Box No
k.	Is the pump and piping protected from freezing? X Yes INO Heat trace and insulation, theater in prit If yes, describe:
1.	Comments on pump installation:
<u>6. (</u> a. (Conclusions Comments on overall installation: The well supplies the 3 RCMP Buildings Molo7, Molog and Molog.
b.R	ecommendations:

SMALL PUBLIC WATER SYSTEM ASSESSMENT

<u>PA</u> Insp	RT A: EBA Site Inspect Dector: Ryan Marti Lyke Lebel	<u>ion</u>	Date June 16, 2005	
	WELL ID #	Owner	Location Description	
	MOIO9	RCMP	Teslin RCMP Residence	
1. <u>V</u>	Vell Location and Potent	ial Contaminant Sourc	es	
a.	General location of well: Teslin	(Community, Subdivis	sion, etc.)	* -
b.	Specific location: (Road Johnson Avenu	or street, Building num	ber, name of owner and/, legal description,	
c. G	PS location:			/
d	Is there electric power?	TYes 🕅	No	
e	Is there outside water acc	ess? 🗆 Yes 🛛	No	1
f.	Does the well system have	ze:		
	5 or more service connection well is no long	ons to a piped distribution	n system ? If so how many 1//4	
	5 or more delivery sites or	a trucked distribution s	system? If so how many	
g.	Nearest building, spec	ify Located off	of basement of Molog Residen	_(~ L
h.	Distance from well to bu	ilding		
i. j.	If there is an effluent disp Distance from well to ne	oosal field, is its location arest point of known field	n known? 🗆 Yes 🖄 No	
k.	Well location relative to	field: 🗌 upslope	downslope lateral	

Creating and Delivering Better Solutions
1. Is there any part of a sewage disposal system(s)or other potential sources of pollution that may pose a
health and safety risk within 30 m? \Box Yes \Box No
Community sewage system and service piping
m. Is the well located within 300 m from a sewage lagoon or pit? \Box Yes \overleftarrow{X} No
n. Is the well located within 120 m from a solid waste site or dump, cemetery? 🛛 Yes 🕅 No
o. Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment
plant designed and secured to prevent:
Unauthorized access by humans? X Yes No Entrance by animals? Yes X No located inside locked residence Access possible. No evidence
p. Is well site subject to flooding? \Box Yes \boxtimes No
q. Is the well site well drained? I Yes I No well head enclosure faces up slope
r. Is there a buried fuel tank on the property? \Box Yes \boxtimes No \cup_n is kely
If yes, is it in use abandoned
Is the location known? \Box Yes \Box No
Distance from the well to known buried tank
s. Are there any other known contaminant sources on the property?
Yes No Describe
If yes, specify the source: \Box dump \Box sewage lagoon \Box cemetery \Box other
Potential Source 1: $A S7 I$; Distance from well to Potential Source 1: $\sim 28 \text{ m}$ in separate
Potential Source 2: $A 572$; Distance from well to Potential Source 2: $\sim 2^{1}m$ out side
Potential Source 3: 4573 ; Distance from well to Potential Source 3: ~2m in some building
Potential Source 4:; Distance from well to Potential Source 4:
t. Are there other wells on this property? \blacksquare Yes \Box No

How many? Molor well in use \Box abandoned \Box require proper sealing

Creating and Delivering Better Solutions

<u>2. V</u>	<u>Well and Wellhead information:</u>
a.	When was well installed? Year Month
b.	Type: Adrilled and dug sand point other
c.	Is there a drillers log for the well: \Box Yes \widecheck No
d.	Is there a surface seal to 6 m \Box Yes $\overleftarrow{\Delta}$ No \Box unknown $\overleftarrow{\Delta}$ unlikely
e.	Surface casing: 🖸 Yes Diameter 🥂 🔥 No
f.	Well casing: Diameter <u>15 cm</u> Material: X steel D plastic Concrete Split Seal gasket w/ proper plugs
g.	Depth of well: $36.175 \text{ m} \approx 10^{10}$ measured (if possible) \Box reported \Box from log
h.	Static water level below ground: 8,470 mbc
	\bigtriangledown measured (if possible) \Box reported \Box from log \Box flowing
i.	(If granular) Is the well completed: \Box open end casing \Box with a well screen
	with slotted pipe unknown other
j.	(If bedrock) Does the well have a liner? $\Box_{yes} \Box$ No $\Box_{steel} \Box$ plastic
k.	If there is a well screen: length $\frac{h/c}{s}$ slot size(s)
	Location of screen: from to from log reported
1.	Is there a sump below the screen? \Box Yes $\boxtimes No$ \longrightarrow
m.	Is the well head: \Box in pumphouse \Box in pit \Box pitless adaptor $\overleftarrow{\Delta}$ in a building Inside Molog Residence
	in a wooden enclosure other, describe

n. If the well head is located in a wooden enclosure,

Creating and Delivering Better Solutions i. Is the well head below grade? describe in detail1.70 m	E	BA Engineering Consultants Ltd.
 i. Is the well head below grade? describe in detail <u>1.70 m below grade</u>. ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? Yes No iii. Is the wellhead enclosed by fiberglass insulations? No <u>1/kely inside unlis</u> iv. Any evidence of rodents? Specify <u>no observe evidence</u>, <u>access possible</u>. v. Does the well easing have a proper seal cap? No <u>1/kely proper plugs</u> 3. Water Supplying This Well: a. By definition is the water from a surface water source or under the direct influence of surface water? Yes No ☐ farther investigation required. If yes is there treatment Yes No <u>N/A</u> Explain (filtration, disinfection etc) 4. Aquifer Supplying This Well: a. The aquifer is: ☐ bedrock ☐ granular sediment ☐ unknown b. Does water level and/or well capacity show seasonal fluctuation? Yes No 5. Pump Installation: a. Is the well equipped with a pump? Yes ☐ No <u>N/A</u> b. Type of pump: ☐hand ☐electric submersible ☐ jet <i>N/A</i> c. Description: Manufacturer Model	Cre	eating and Delivering Better Solutions
 ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? □ Yes ⊠ No iii. Is the wellhead enclosed by fiberglass insulations? ⊠Yes □ No 1/Wely inside walls iv. Any evidence of rodents? Specify <u>no observe evidence</u>, <u>access possible</u> v. Does the well casing have a proper seal cap? ☑ Yes □ No If no, describe condition <u>split seal</u> <u>sasket</u> <u>v/graper</u> <u>plugs</u> 3. Water Supplying This Well: a. By definition is the water from a surface water source or under the direct influence of surface water? □ Yes □ No □ farther investigation required. If yes is there treatment □ Yes □ No M/A Explain (filtration, disinfection etc) 4. Aduifer Supplying This Well: a. The aquifer is: □ bedrock □ granular sediment □ unknown b. Does water level and/or well capacity show seasonal fluctuation? □ Yes □ No ½/6 5. Pump Installation: a. Is the well equipped with a pump? □ yes □ No M/A b. Type of pump: □hand □electric submersible □ jet M/A c. Description: Manufacturer Model c. Description: Manufacturer Model 		i. Is the well head below grade? describe in detail 1.70 m below grade
 iii. Is the wellhead enclosed by fiberglass insulations? ⊠Yes □ No 1/1/4e/Y inst/de wn¹¹s iv. Any evidence of rodents? Specify <u>records observe evidence</u>, access poss/b¹e. v. Does the well casing have a proper scal cap? ☑ Yes □ No If no, describe condition <u>split scal gasket v/greper plugs</u> 3. Water Supplying This Well: a. By definition is the water from a surface water source or under the direct influence of surface water? □ Yes □ No □ farther investigation required. If yes is there treatment □ Yes □ No <i>N</i>/<i>A</i> 4. Aquifer Supplying This Well: a. The aquifer is: □ bedrock □ granular sediment □ unknown b. Does water level and/or well capacity show seasonal fluctuation? □ Yes □ No <i>V</i>/<i>A</i> 5. Pump Installation: a. Is the well equipped with a pump? □ yes □ No fV/<i>A</i> b. Type of pump: □hand □electric submersible □ jet <i>N</i>/<i>A</i> c. Description: Manufacturer Model 		ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? \Box Yes 🕅 No
 iv. Any evidence of rodents? Specify <u>ne observe evidence</u>, <u>access pass/b¹e</u> v. Does the well casing have a proper seal cap? Ø Yes □ No If no, describe condition <u>Split Seal gasket v/proper plugs</u> 3. Water Supplying This Well: a. By definition is the water from a surface water source or under the direct influence of surface water? Yes □ No □ farther investigation required. If yes is there treatment □ Yes □ No <i>N/A</i> Explain (filtration, disinfection etc) 4. Aquifer Supplying This Well: a. The aquifer is: □ bedrock □ granular sediment □ unknown b. Does water level and/or well capacity show seasonal fluctuation? □ Yes □ No <i>h</i>/_A 5. Pump Installation: a. Is the well equipped with a pump? □ yes □ No <i>N/A</i> b. Type of pump: □hand □ electric submersible □ jet <i>N/A</i> c. Description: Manufacturer Model		iii. Is the wellhead enclosed by fiberglass insulations? Are No 1/kely inside walls
 v. Does the well casing have a proper seal cap? ^[A] Yes □ No If no, describe condition <u>\$p i+ \$exal \$exited v/ \$proper plug \$s</u> 3. Water Supplying This Well: a. By definition is the water from a surface water source or under the direct influence of surface water? □ Yes □ No □ farther investigation required. If yes is there treatment □ Yes □ No N/A Explain (filtration, disinfection etc) 4. Aquifer Supplying This Well: a. The aquifer is: □ bedrock □ granular sediment □ unknown b. Does water level and/or well capacity show seasonal fluctuation? □ Yes □ No N/A 5. Pump Installation: a. Is the well equipped with a pump? □ yes □ No N/A b. Type of pump: □ hand □ electric submersible □ jet N/A c. Description: Manufacturer Model horsepower capacity voltage 		iv. Any evidence of rodents? Specify no observe evidence, access possible
If no, describe condition $\frac{ s + s }{ s + s + s + s + s + s + s + s + s + s $		v. Does the well casing have a proper seal cap? \square Yes \square No
3. Water Supplying This Well: a. By definition is the water from a surface water source or under the direct influence of surface water? □ Yes □ No □ farther investigation required. If yes is there treatment Yes □ No N/A Explain (filtration, disinfection etc)		If no, describe condition split seal gasket w/proper plugs
 a. By definition is the water from a surface water source or under the direct influence of surface water? Yes No farther investigation required. If yes is there treatment □ Yes □ No N/A Explain (filtration, disinfection etc) 4. Aquifer Supplying This Well: a. The aquifer is: □ bedrock □ granular sediment □ unknown b. Does water level and/or well capacity show seasonal fluctuation? □ Yes □ No N/A S. Pump Installation: a. Is the well equipped with a pump? □ yes □ No N/A b. Type of pump: □hand □electric submersible □ jet N/A c. Description: Manufacturer Model horsepower capacity voltage 	<u>3. V</u>	Water Supplying This Well:
$ \begin{array}{ c c c c c c } \hline Yes & & No & & & farther investigation required. \\ \hline If yes is there treatment & Yes & & No & N//* \\ \hline Explain (filtration, disinfection etc) \\ \hline Explain (filtration, disinfection etc) \\ \hline Explain (filtration, disinfection etc) \\ \hline \hline \\ \hline $	a.	By definition is the water from a surface water source or under the direct influence of surface water?
If yes is there treatment \Box Yes \Box No N/A Explain (filtration, disinfection etc) 4. Aquifer Supplying This Well: a. The aquifer is: \Box bedrock \Box granular sediment \Box unknown b. Does water level and/or well capacity show seasonal fluctuation? \Box Yes \Box No N/A 5. Pump Installation: a. Is the well equipped with a pump? \Box yes \Box No N/A b. Type of pump: \Box hand \Box electric submersible \Box jet N/A \Box shallow well centrifugal \Box other, N/A c. Description: Manufacturer Model horsepower voltage voltage		\Box Yes \Box No \Box farther investigation required.
Explain (filtration, disinfection etc) 4. Aquifer Supplying This Well: a. The aquifer is: bedrock granular sediment unknown b. Does water level and/or well capacity show seasonal fluctuation? Yes Model V/A 5. Pump Installation: a. Is the well equipped with a pump? yes No V/A b. Type of pump: hand electric submersible jet shallow well centrifugal other, Model		If yes is there treatment \Box Yes \Box No N/A
4. Aquifer Supplying This Well: a. The aquifer is: bedrock granular sediment unknown b. Does water level and/or well capacity show seasonal fluctuation? Yes No 5. Pump Installation:		Explain (filtration, disinfection etc)
 a. The aquifer is: □ bedrock □ granular sediment □ unknown b. Does water level and/or well capacity show seasonal fluctuation? □ Yes □ No <i>M</i>/<i>A</i> 5. Pump Installation: a. Is the well equipped with a pump? □ yes □ No <i>N</i>/<i>A</i> b. Type of pump: □ hand □ electric submersible □ jet <i>N</i>/<i>A</i> c. Description: Manufacturer Model c. Description: Manufacturer Model 	4. <i>A</i>	Aquifer Supplying This Well:
 b. Does water level and/or well capacity show seasonal fluctuation? ☐ Yes ☐ No 5. Pump Installation: a. Is the well equipped with a pump? ☐ yes ☐ No Ŵ/A b. Type of pump: ☐ hand ☐ electric submersible ☐ jet N/A ☐ shallow well centrifugal ☐ other,M/t c. Description: Manufacturer Model b. Type of pump: ☐ hand facturer Model 	a.	The aquifer is: 🗌 bedrock 🔲 granular sediment 🗖 unknown
 5. Pump Installation: a. Is the well equipped with a pump? □ yes □ No N/A b. Type of pump: □ hand □ electric submersible □ jet N/A □ shallow well centrifugal □ other,	b.	Does water level and/or well capacity show seasonal fluctuation? \Box Yes \Box No
 a. Is the well equipped with a pump? yes No N/A b. Type of pump: hand electric submersible jet N/A c. bescription: Manufacturer Model horsepower capacity voltage voltage 	<u>5.</u>	Pump Installation:
 b. Type of pump: hand electric submersible jet N/A shallow well centrifugal other, <u>N/A</u> c. Description: Manufacturer Model horsepower capacity voltage 	a.	Is the well equipped with a pump? \Box yes \Box No N/h
c. Description: Manufacturer Model horsepower capacity voltage	b.	Type of pump: \Box hand \Box electric submersible \Box jet N/A
c. Description: Manufacturer Model horsepower capacity voltage		shallow well centrifugal other, <u>N/h</u>
horsepower capacity voltage	c.	Description: Manufacturer Model
		horsepower capacity voltage

B	A Engine	eering Cons	ultants Lt	d.		
eat	ing and Deliveri	ng Better Solutions				
.]	Date installed:	N/A	By:			
.]	For submersibl	e pump, depth of setti	ng below surface			
:)	Drop pipe for s	ubmersible pump:	steel 🛛 p	lastic N/A		
;.]	Pump delivers v	water to: D pressure	e tank 🛛 elev	ated tank	other N/A	
l	Are there autom	natic pump controls:	□Yes □N	io Ma		
. 1	s there provisio	on for taking water sar	mples before water	reaches storag	e? 🗆 Yes 🗆	No 11/4
.]	s there a water	meter on the system?	□ Yes □	No MA		
c.]	s the pump and	l piping protected fror	n freezing? 💢 Y	es 🛛	No	
	If yes, desc	cribe:				
. (Comments on p	oump installation:				
<u>5. C</u> (a. Co - -	onclusions omments on ove	erall installation:				
- .Re	commendation	s:				
		·····				
			- ··· ··· ···			
	· <u> </u>					

PART B: EBA Site Inspection

<u>.</u>

Ins	pector: BERT A	LBISSER		Date VUJE16	05
	WELL ID #	Owner		Location Descript	ion
	M0107	YTG.	RCMP	DETACHMENT	TESLIN
6.	Water Treatment	/			
a.	Is well water treated?	Yes 🗹 No; Type o	f treatment		
	\Box chlorination \Box ire	on and or manganese remo	oval 🗌	other	
b.	Is water entering plumbin	g or piped distribution sys	stem treate	d with chlorine or ano	ther treatment that is
	as effective as chlorine	used to achieve disinfection	ion through	10ut the system?	
	Yes IN No	If so how			
c.	If treated with chlorine, is	s the free residual chlorine	concentra	tion less than 0.2 mg/I	L
	Yes No _	reading	g.		
	Tested at		(location	1)	
d.	Is testing for chlorine resid points in a piped distribution	lual concentration done at on system, including a poi	the tap (egint from tap	g. Kitchen faucet) or fr p at the end line	om representative
	□ Yes □ No	If yes how ofte	en?		
e.	If the drinking water is be	ing transported by water of	delivery tru	ick does it have a min	imum chlorine free
	residual of 0.4 mg/L at	t the time of fill. \Box Yes		0	
7.	Water Quality (observa	<u>tions):</u>	/		
a .	Does the water stain plun	ıbing? □yes □ No s	slight \square s	evere	
	Type of stain: \Box	brown 🗹 red 🛛	black		
b.	Does the water contain se	ediment? 🗆 Yes 🖄	to 🗆 oc	casional 🗌 consta	ant
c.	Is there an unpleasant odd	our? 🗆 Yes 🗹 N	lo □	H_2S \Box Other	
		6/1	1		

Creating and Delivering Better Solutions

d.	Is there an unpleasant taste? Types No brackish Dother										
e.	Is there a history of bad bacterial analyses? Yes No										
f.	Is there a chemical analysis? Yes No adequate incomplete										
g.	Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? \Box Yes \Box No										
h.	. Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the										
rang	ge 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? Yes No unknown										
i.	If yes is the test performed in accordance with manufactures directions? \Box Yes \Box No \bowtie unknown										
j.	Is a record of the date, time, name of person performing the test and results of the drinking water sample										
	kept? I Yes I No										
	TANK AND PIPING DETAILS										
	Tank Room										
	Is there a water tank? Yes No Details:										

Where is it located? Comments: ____ PRESSURE TANK - BASEMEN

Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water? YES NO Comments:

Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES

NO

Comments:

Are there other heat sources near the tank? YES NO Comments:

Is there waterproof flooring with a sealed base to contain spills? YES NO Comments:

Creating and Delivering Better Solutions

Overall Tank

What are the tank size and dimensions?

What material is the tank constructed of?

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments:

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO Comments:

Is there any sediment or scum in bottom of tank? YES NO Comments:

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

Creating and Delivering Better Solutions

8. Conclusions

a. Comments on overall installation:

THE CASING IS APPROX BEROW GRADE. THE WATER SYSTEM. INSTAULATION IS GOOD QUALITY MATCRIAL AND WORKMANSTHIP. THE WATER SOFTENEN IS BY PASSED. APPLICENTLY THE MINGER TANK LEAKS.

b. Recommendations: EXTEND WELL CASING TO APPROPRIATE EIGHT ABOVE GRADE. INSTALL SURFACE TAR. SUPERCHORINATE WATER WELL AND SYSTEM. INSTITUTE A PIPING WER MANTENANCE PROGRAM. WATER REDORD WER MANTENANCES

PA Ins	RT B: EBA Site Inspecti pector: BEXT A.	on Brsser	Date LINE	16 05
	WELL ID #	Owner	Location Des	cription
	M 108	YTG.	TESUN RCMP	KESIPENCE
6.	Water Treatment			
a.	Is well water treated?	Yes D No; Type of	treatment:	
	C chlorination I iro	on and or manganese remo	val 🛛 other <u>R.</u>	s. System
b.	Is water entering plumbin as effective as chlorine	g or piped distribution sys used to achieve disinfecti	tem treated with chlorine o on throughout the system?	r another treatment that is
	🗆 Yes 🗹 No	If so how		
c.	If treated with chlorine, is	the free residual chlorine	concentration less than 0.2	mg/L
	□ Yes □ No _	reading		
	Tested at		_(location)	
d.	Is testing for chlorine resid points in a piped distributio	ual concentration done at on system, including a poi	the tap (eg. Kitchen faucet) nt from tap at the end line) or from representative
	□ Yes □ No	If yes how ofte	n?	
e.	If the drinking water is be	ing transported by water of	lelivery truck does it have a	a minimum chlorine free
	residual of 0.4 mg/L at	the time of fill. \Box Yes	🗆 No	
7.	Water Quality (observat	tions):		
a.	Does the water stain plum	ıbing? 🗆 yes 🗆 No 🗹 s	light 🗆 severe	
	Type of stain:	brown red	black	
b.	Does the water contain se	diment? 🗆 Yes 🗖 N	to \Box occasional \Box o	constant
c.	Is there an unpleasant odd	our? 🗆 Yes 🗹 N	to \Box H_2S \Box Other	er

E	BA Engineering Consultants Ltd.
Cre	ating and Delivering Better Solutions
d.	Is there an unpleasant taste? Yes No brackish Other
e.	Is there a history of bad bacterial analyses? \Box Yes \Box No
f.	Is there a chemical analysis? \Box Yes \Box No \Box adequate \Box incomplete
g.	Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well
	under the direct influence of surface water? \Box Yes \Box No
h.	Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the
ran	ge 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? Yes No unknown
i.	If yes is the test performed in accordance with manufactures directions? \Box Yes \Box No \Box unknown
j.	Is a record of the date, time, name of person performing the test and results of the drinking water sample
	kept? 🛛 Yes 🔲 No
	TANK AND PIPING DETAILS
	Tank Room Is there a water tank? Yes No Details: Petessure TANK Where is it located? Comments: Lis the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water?
	YES NO Comments:
	Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES
	NO
	Comments:
	Are there other heat sources near the tank? YES NO Comments:
	Is there waterproof flooring with a sealed base to contain spills? YES NO Comments:

Creating and Delivering Better Solutions

Overall Tank

What are the tank size and dimensions?

What material is the tank constructed of?

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments: _____

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO Comments:

Is there any sediment or scum in bottom of tank? YES NO Comments:

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

Creating and Delivering Better Solutions

8. Conclusions

a. Comments on overall installation:

THIS UNIT IS FED FROM THE DETACHMENT WELL THE INSTANATION IS PROFIESSIONAC. b. Recommendations: TREATMENT AS WELL HAS NO SURFACE Som.

PA	RT B: EBA Site Inspecti	on	1	
lns	pector: <u>Bent Mbissen</u>		Date June	16 05
	WELL ID #	Owner	Location Desc	ription
	M0109	YTG	REMP HOUSING	TESLIN
6.	Water Treatment	/		
a.	Is well water treated?	Yes 🖾 No; Type o	f treatment:	
	□ chlorination □ ire	on and or manganese remo	oval D other	
b.	Is water entering plumbin as effective as chlorine	g or piped distribution sys used to achieve disinfect	stem treated with chlorine or ion throughout the system?	another treatment that is
	□ Yes □ No	If so how		
c.	If treated with chlorine, is	the free residual chlorine	concentration less than 0.2 r	ng/L
	□ Yes □ No _	reading	<u>z</u> .	÷.
	Tested at		_(location)	
d.	Is testing for chlorine resid points in a piped distribution	lual concentration done at on system, including a po	the tap (eg. Kitchen faucet) int from tap at the end line	or from representative
	□ Yes □ No	If yes how ofte	en?	
e.	If the drinking water is be	eing transported by water	delivery truck does it have a	minimum chlorine free
	residual of 0.4 mg/L at	t the time of fill. \Box Yes	🗆 No	
7.	Water Quality (observa	tions):		
a.	Does the water stain plun	nbing? 🗆 yes 🗆 No 🗹	slight 🗆 severe	
	Type of stain:	brown 🗹 red 🛛	black	
b.	Does the water contain se	ediment? 🗆 Yes 🗹 I	No 🗆 occasional 🔲 co	onstant
c.	Is there an unpleasant ode	our? 🗆 Yes 🗹 N	No \square H ₂ S \square Other	·

E	BA Engineering Consultants Ltd.
Cre	ating and Delivering Better Solutions
d.	Is there an unpleasant taste? Yes YNO brackish D Other
e.	Is there a history of bad bacterial analyses? \Box Yes \Box No
f.	Is there a chemical analysis? \Box Yes \Box No \Box adequate \Box incomplete
g.	Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well
	under the direct influence of surface water? \Box Yes \Box No
h.	Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the
rang	ge 0 to 3.5 mg/L of free chlorine residual in increments of 0.1 mg/L? Yes No unknown
i.	If yes is the test performed in accordance with manufactures directions? \Box Yes \Box No \Box unknown
j.	Is a record of the date, time, name of person performing the test and results of the drinking water sample
	kept? 🗌 Yes 🔲 No
	TANK AND PIPING DETAILS
	Tank Room Is there a water tank? Yes No Details: PRESSURE TANK PCZ66 Where is it located? Comments: Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water? YES NO YES NO
(Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES NO Comments:
	Are there other heat sources near the tank? YES NO
	Is there waterproof flooring with a sealed base to contain spills? YES NO

Creating and Delivering Better Solutions

Overall Tank

What are the tank size and dimensions?

What material is the tank constructed of?

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments:

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO Comments:

Is there any sediment or scum in bottom of tank? YES NO Comments:

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

Creating and Delivering Better Solutions

8. Conclusions

a. Comments on overall installation:

THIS IS A GOOD INSTALLTION BOTH IN EQUIPMENT & WORKMANSHIP. THE ABANDONED WELL CASING NEEDS TO BE PROCESSED OR EXTENDED ABOVE GRADE. b. Recommendations: ABANDON WATCH WEN NOT IN USE ACCORDING To REGULATION

						TYPE	BI	DDAA	ant	3			
- -	K £Y	TO TON LO	G	ς.	j	FIELD R	EPORT		600 I.	Mailing P.O.	Box 210	ss: 06	
rown	Clay	- br	cl		•				49	Whiteho	orse, Y	kon	
lue and	Clay	- bl - sd	cl	M	ID	NIG	ΉT	SU	N [°]	Phone:	667 - 4	795	
andy	Clay Shale	- sdy - s s	r cl shl	T A T			Jc	ов (Мол	nth) ((Day)	(Year)		
lard	Rock	- hd	rk					· .	Started.			. 7.0.	
`ine	Grave	- 53 1- f g	gr		DR	ILLIN	G CO. 1	LTD.	Complete	ed	c. 7 19	.70.	
Jould	iers ce No	- bar											
						DOODTDO	TON OD	HODK	T.	DO A OT ON			all ¹
<u>ME A</u>	IND AD	DRESS	OF CL	JLENT		ESCRIPI	CLON OF	WORK	L. Soc	<u>DCATTON</u>	Dr wor	LA	
DEP	ARTMI	NT NT			<u></u> ¥¥ H	IEKW			B C O		Derecu	MENT	-
WH WH	TEHO		<u>ка</u> Ү. т.				-		Tr.	stin	URON		-
F()EMATI	ON LOC	ž	[TI	ME		-
<u>'OM_</u>	TO	FORMA	TION	Move	DESCR	IPTION	OF WORK	Κ	Date_	From	To	Hours	-
					5et.	up D	ue in	Pir					
		To	P.	DRiL	L	і тн (Bit	TO 50'					
2	I	Roci	к						Nov 1	14.00	20:00		- (
<u> </u>		CAUI	NTO C	RAUEL					2	07:30	10 00		-
24	30	Pan											-
30	45	GRAV	EL						3	0 9:00	19:00	11	_
45	50	BROW	A CL.										
50	58	PEA		WATER	3 B	EABING							-
58	60	HAR	к 	Nov	3_13:	30 -	Nov4 I	9:30	4	08:00	20:00	12	_
60		BLUE	CLAY	L					5	08:00	21:00	13	_
-5_	12	HAT Bec	ND	Novs	12:4	20 - H	OVL ZI	130	6	08.00	20:00	17	- 4
72	ies	BL. C	CRED P	DR		<u> 117н 4</u>	<u>то 4</u>	<u>45</u>	7			ļ	_ 7
05	ilB.	50	dD										-
			9D	WAITO	۹c F	OR R	EPAIRS_	8, 5, 10	×				-
18	119	Rec	<u>к</u>	Novi	12:0	x - Nov	11- 15:3	0	IL	10:00	01:00		_
19	130	BLUE	CLAY										-
30	15%	SCATT	no B	<u>сх</u>									_
55	157	<u>5</u> A	<u>дн</u>	~	\sim								-
d.	of Cas	sing &	Pipe	Remark	ACE (S:	2					1	I	=
ze	Type	Size	Type							1			-
	Troh	Feet	Troh									<u>_</u>	-
<u>et</u>	THCU	reet	THOU										-
						· ·							
													_
													-
													~
				Well		Casing		ft. I	Total B	ig Time			-
				Cased:	asing	to	ft.	and	(above) Total S	tandby		hrs.	_
				TATIC	rom	from a	to ground 1	ft. level	<u>(above)</u> Drillin	g Mud		hrs.	-
<u> </u>				LEVEL	f	rom toj		sing 📜	used (al	l l		Sacks	

rell Moloy (page 1 of 2)

`or	Midnight	Sun	••	•	•	•	•	•	•	•	•	•	•	•	•	•	•	
-----	----------	-----	----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--

For Client.....

KEY TO		Mailing Address:
FURMATION LOG	FIELD REPORT	P.O. Box 2106 Whitehorse, Yukon
rown Clay - br cl		
and - sd	MIDNICHT SUN	Phone: 007-4795
andy Clay - sdy cl oft Shale - s shl	Job (Month)	(Day) (Year)
ard Rock - hd rk	Starte	d
andstone - ss ine Gravel- f gr oulders - bdrs	DRILLING CO. LTD. Comple	ted19

nvoice No.....

OF WOR	ĸ
Rge.	W
an a	
To	Hours
	<u> </u>
24:00	15
24.00	
03:00	17
Dec B	
06/00	20
	L
135	hrs.
	hrs
	135

SIGNATURES

Well Molog (page Zofz)



Environment Environnement Canada Canada

Spill Report Information

Spill #	0104
Jurisdiction	Yukon
Community	Teslin
Address	Jackson Ave
Highway	
Milepost	
Feature	Teslin
Location and Cause	Teslin septic tank - mechanical failure of auto dialer alarm - sewage spill
Latitude	60.16491
Longitude	-132.72162
Incident Date	1/7/2001
Lead Agency	Department of Indian Affairs and Northern Development
Other Agency	
Company(s)	Village of Teslin
Amount	800
Units	Litres
Quantity	Estimate
Release Description	Spilled
Additional Quanitit	
Concentration	
Concentration Unit	
Phase	Liquid
Major Contaminant	Raw Sewage
2nd Contaminant	
3rd Contaminant	
4th Contaminant	
Outcome	spill migrated to shoreline of Teslin Lake but was contained in snow and ice - contaminated snow removed and bleach used as disenfectant - clean-up was completed

*

Environment Environnement Canada Canada

Spill Report Information

Spill #	0333
Jurisdiction	Yukon
Community	Teslin
Address	Jackson Ave
Highway	
Milepost	
Feature	Teslin
Location and Cause	spill at Lift Station #2 - due possibley to faulty truck guage - cause to be determined
Latitude	60.16491
Longitude	-132.72162
Incident Date	9/23/2003 11:00:00 AM
Lead Agency	
Other Agency	
Company(s)	Village of Teslin
Amount	100
Units	Litres
Quantity	Estimate
Release Description	Spilled
Additional Quanitit	
Concentration	
Concentration Unit	
Phase	Liquid
Phase Major Contaminant	Liquid Raw Sewage
Phase Major Contaminant 2nd Contaminant	Liquid Raw Sewage
Phase Major Contaminant 2nd Contaminant 3rd Contaminant	Liquid Raw Sewage
Phase Major Contaminant 2nd Contaminant 3rd Contaminant 4th Contaminant	Liquid Raw Sewage



Environment Environmement Canada Canada

Spill Report Information

Spill #	0340
Jurisdiction	Yukon
Community	Teslin
Address	Jackson Ave
Highway	
Milepost	
Feature	Teslin
Location and Cause	Lift Station #2 (Jackson Ave) - spill due to non-secured coupling device
Latitude	60.16491
Longitude	-132.72162
Incident Date	11/27/2003 2:30:00 PM
Lead Agency	Yukon Government - Water Inspections
Other Agency	
Company(s)	Village of Teslin
Amount	80
Units	Litres
Quantity	Estimate
Release Description	Spilled
Additional Quanitit	
Concentration	
Concentration Unit	· · · · · · · · · · · · · · · · · · ·
Phase	Liquid
Major Contaminant	Raw Sewage
2nd Contaminant	
3rd Contaminant	
4th Contaminant	
Outcome	driver of truck bleached area - contaminated area being cleaned up and material removed to landfill - copy of letter from Village of Teslin to YT Water Board on file



Environment Environnement Canada Canada

Spill Report Information

Spill #	8706
Jurisdiction	Yukon
Community	Teslin
Address	Jackson Ave
Highway	
Milepost	
Feature	Teslin
Location and Cause	Jackson Ave pump station - truck overturned in avoiding oncoming traffic
Latitude	60.16491
Longitude	-132.72162
Incident Date	3/17/1987 2:10:00 PM
Lead Agency	Federal Government - other
Other Agency	Environment Canada - Environmental Protection Service
Company(s)	Walter Geddes
Amount	4500
Units	Litres
Quantity	Estimate
Release Description	Spilled
Additional Quanitit	
Concentration	
Concentration Unit	
Phase	Liquid
Major Contaminant	Raw Sewage
2nd Contaminant	
3rd Contaminant	
4th Contaminant	
Outcome	no specific environmental concerns - possiblity of contamination of 1 or 2 near-by water wells - contained in snow berm - removed to sewage lagoon

Photo 0212: M0107 Wellhead enclosure (front), Teslin RCMP Detachment building M0107 (back)	Photo 0213: M0107 Wellhead enclosure (front), Teslin RCMP Residences M0109 (right) and M0108 (behind), and above ground fuel storage tank in front of RCMP garage (back left)
Photo 0211: M0107 Wellhead in pit (pitless adapter)	Photo 0013: M0107 Water softener (centre), pressure tank (left), and brine tank (right)







