

5.0 BUILDING M0181 – TESLIN RCMP RESIDENCE

5.1 Description of Existing Water system

Building M0181, the Teslin RCMP Residence on Sawmill Road, is served by a truck delivered water supply that sources water from a community well operated by the Village of Teslin. The domestic system at M0181 is equipped with a 6,000 L cylindrical water storage tank. A schematic detailing the water system is provided as Figure M0181-B in Appendix A5. The coordinates of the water intake measured by a hand held GPS device, were recorded as:

- UTM ZONE 8
- Northing: 6673483
- Easting: 627320

5.2 Water Quality Results

5.2.1 Water Quality Results from Previous Sampling

Regular bacteriological sampling carried out between September 2004 and March 2005 did not indicate any positive coliform or *E. coli* testing results. A summary of historical bacteriological results is presented in Table M0181-1 in Appendix A5.

Detailed potability analyses were performed on samples collected from the RCMP building M0181 on September 9, 2004. The results are given in Table M0181-2 in Appendix A5, and summarized in the following:

- The water supplied by delivery appears to be hard and highly mineralized;
- The hardness concentration was observed to be 263 mg/L, which exceeds the CDWQG aesthetic objective of 200 mg/L;
- The total and dissolved arsenic concentrations were below the current CDWQG MAC of 0.025 mg/L, but were greater than the proposed MAC of 0.005 mg/L; and,
- All other parameters analyzed were below the applicable CDWQG criteria for the sample submitted.

5.2.2 Identification of Additional Analytical Required

Additional parameters requiring analysis were identified prior to and/or during the site inspection and included UV absorbance, silicate, phosphate, vanadium and

confirmation of arsenic concentrations. These parameters were chosen to confirm previous results and to assist in treatment system selection. Results from additional analytical sampling are presented in Table M0181-2 in Appendix A5, and laboratory results are provided in Appendix B. The analytical results are summarized below:

- At 0.0211 mg/L, the arsenic concentration was reported to be greater than the proposed guideline of 0.005 mg/L, but lower than the current MAC of 0.025 mg/L.
- Field chemistry reported that the residual chlorine concentration was only 0.05 mg/L, below the recommended 0.2 mg/L for all points of service for a water delivery system.

5.2.3 Indicators of Potential Contamination

No elevated concentrations of indicator parameters were observed in the sample results reviewed.

5.3 Conceptual Hydrogeology

The RCMP building M0181 is supplied by water delivery and there are no wells on the property included in this study, therefore, very limited subsurface information was readily available and an assessment of the hydrogeology in the vicinity of this building was not required.

Jacobsen (2003) examined water source, treatment, storage, pumping, and water distribution facilities as well as operations and maintenance procedures for the Village of Teslin Community well. The well is very deep, and has several confining low permeability units above it. As such, the aquifer from which this well obtains water is not likely under the direct influence of surface water, however, the well is approximately 60 m from Teslin Lake and may warrant further investigation.

5.4 Potential Contaminant Sources

Potential contaminant sources observed during the site investigation are compiled in field notes in Appendix A5. Photos of potential contaminant sources are also provided at the end of this appendix.

The sewer lift stations sporadically spill raw sewage as documented in spills reports and a previous study prepared for the Teslin Tlingit Council near the Village of Teslin community well. Lift Station #4, which is close to the Village of Teslin community well, is particularly disconcerting because the tank or education system have frequently spilled or leaked. Based on a conceptual understanding of the hydrogeological regime for the area, the Village of Teslin community well is 34 m cross-gradient to lift station #4. Government spills reports confirm that large spills routinely occur at Lift Station #4. The depth to the aquifer (84 m) and thick confining layers provide reasonable protection for the Village of Teslin community well from surficial sources of contamination.

5.5 Identified Water System Deficiencies and Associated Risk

5.5.1 High or Medium Risk Deficiencies

- Low free available chlorine concentration; and,
- Lack of regular water holding tank cleaning and residual chlorine monitoring.

5.5.2 Low Risk Deficiencies

- Piping is constructed of ABS and is not suitable for drinking water.

5.6 Mitigative Options for Deficiencies

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

5.6.1 Priority 1

- Undertake immediate cleaning of holding tank including superchlorination of the tank and piping.
- Institute a regular FAC monitoring program and if residual chlorine concentrations continue to be low, consult with the Village of Teslin to ensure that concentrations upon delivery are above 4 mg/L as required by regulation.
- Implement a regular water storage tank cleaning program every 6 months.

5.6.2 Priority 2

- There were no Priority 2 mitigative options identified.

5.6.3 Priority 3

- Replace ABS piping with PVC piping.

5.7 Cost Estimates for Mitigative Options


Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

5.7.1 Priority 1


- Initiating a water storage tank cleaning schedule and monitoring regularly for residual chlorine should fall under normal operations and maintenance costs.

5.7.2 Priority 3

- Replacing the ABS fill pipe with PVC would cost in the order of **\$200** for materials and labour.




NOTES:
 1. UTM COORDINATES OBTAINED WITH A HAND HELD GPS USING NAD83 SYSTEM AND ARE CONSIDERED TO BE ACCURATE TO 10.0 m, APPROXIMATELY.

 30 m RADIUS FROM WATER WELL FOR CONSIDERATION OF PROXIMITY TO POTENTIAL CONTAMINANT SOURCES.

No.	DESCRIPTION	DATE	APPROVED
0	ISSUED FOR CLIENT REVIEW	DD/MM/YY	XXX
REVISION			

EBA Engineering Consultants Ltd.

DESIGNED BY: R. MARTIN
 DRAWN BY: J. BUYCK
 DATE: JULY 2005
 SCALE: AS SHOWN
 PROJECT No.: 1260002.002
 ACAD FILENAME: 002-EASTERN REGION

CLIENT:

 Highways and Public Works
 Property Management Branch

SMALL PUBLIC WATER SYSTEMS ASSESSMENT
 EASTERN REGION

GOVERNMENT OF YUKON
 HIGHWAYS & PUBLIC WORKS

TESLIN RCMP RESIDENCE
 M0181
 SITE LOCATION DIAGRAM
 WELL ID: N/A

REVISION ISSUE
 0

FIGURE No.
 FIGURE M0181-A

LEGEND



PUMP



PRESSURE GAUGE



GATE VALVE



CHECK VALVE



SOLENOID

#2

COMPONENT ID. No.
(SEE TABLE ON FOLLOWING PAGE)



FLOW METER



WATER FILTER
(CARTRIDGE TYPE)




PRESSURE TANK



CL₂


CHLORINE RESERVOIR AND
INJECTION PUMP



DUPLEX WATER
SOFTENER



WELL WITH
SUBMERSIBLE PUMP



ACTIVATED
CARBON

Z:\0201\Drawings\1260002 - Water Assessment YTG\002 - Eastern Region\1260002\003 Eastern Schematic_LEGEND.dwg, 4/11/2006 10:31:08 AM, Adobe PDF, jbuyck



EBA Engineering Consultants Ltd.

PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT
EASTERN REGION

CLIENT



TITLE
**SCHEMATIC SYSTEM
LEGEND**


DATE APRIL 2006

DWN. JSB



CHKD. RMM

FILE NO. 1260002

DRWG. LEGEND



SCHEMATIC PRODUCED BY BERT ALBISSER OF AQUA TECH SUPPLIES & SERVICES LTD.

 EBA Engineering Consultants Ltd.		PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT EASTERN REGION	
CLIENT 		TITLE WATER SYSTEM DISTRIBUTION/TREATMENT SCHEMATIC SYSTEM ID.: M0181 TESLIN RCMP RESIDENCE	
DATE	JULY 2005	DWN.	JSB
CHKD.	FMM	FILE NO.	1260002.002
		DWG.:	FIGURE M0181-B

Eastern Region – R.C.M.P. Housing
Building # M0181

DISTRIBUTION & TREATMENT SYSTEM DATA

Item	Description	Manufacturer	Model	Part No.	Serial No.	Size
1	WATER TANK	N/A	1250 VERTICAL			1250 GALLON
2	JET PUMP	GRUNDFOS	JPF-3A			1/2 HP - 1"
3	WATER SOFTENER	AQUA TECH	L5600-304I			30K
4						
5						
6						
7						
8						
9						
10						

TABLE M0181- 1: SUMMARY OF BACTERIOLOGICAL RESULTS

		Number of Sampling Events	Time Period over which Sampling was Done	Any Positive Total Coliform Results? (yes or no)	Fraction of Positive Total Coliform Results vs. Total Sampling Events	Any positive E.Coli results? (yes or no)	Most Recent Sampling Event Available for EBA Review	Is Most Recent Result Positive?
Building #	Building Name							
M0181	R.C.M.P Housing	7	Sept-04 to Mar-05	no	0/7	no	1-Mar-05	no



Table M0181-2: Water Quality Results

SOURCE:		Building M0181 - R.C.M.P. Housing		GCDWQ Criteria		
Location/ Resident		Teslin				
Address		Block 26				
Treatment		Water Softener				
Disinfection		No				
Source of Water		Water Delivery				
Purpose of Sampling		Baseline	Additional Sampling			
Sample Location		Kitchen Tap	Downstairs Laundry Tub Tap			
Date Sampled		9-Sep-04	16-Jun-05	Lower	Upper Limit	
Physical Tests (ALS)				AO	MAC	AO
Colour (CU)		5				15
Total Dissolved Solids		345				500
Hardness CaCO3		262		AO >200 = poor, > 500 unacceptable ^A		
pH		8.37		6.5		8.5
Turbidity (NTU)		0.4			1	5
UV Absorbance			0.030			
Dissolved Anions (ALS)						
Alkalinity-Total CaCO3		223				
Chloride Cl		4.0				250
Fluoride F		0.14			1.5	
Silicate SiO4			9.4			
Sulphate SO4		88.0				500
Nitrate Nitrogen N		<0.1			10	
Nitrite Nitrogen N		<0.05			1	
Total Phosphate PO4			0.0616			
Total Metals (ALS)						
Aluminum T-Al		<0.005			0.1	
Antimony T-Sb		<0.0002			0.006	
Arsenic T-As		<u>0.0193</u>	<u>0.0211</u>		0.025	
Barium T-Ba		0.03			1	
Boron T-B		0.033			5	
Cadmium T-Cd		<0.00001			0.005	
Chromium T-Cr		0.0006			0.05	
Copper T-Cu		0.017			1	
Iron T-Fe		0.17				0.3
Lead T-Pb		0.0002			0.01	
Manganese T-Mn		0.029				0.05
Sodium T-Na		37.3				200
Uranium T-U		<0.0005			0.02	
Vanadium T-V			<0.030			
Zinc T-Zn		0.008				5
Dissolved Metals						
Arsenic D-As			<u>0.0158</u>		0.025	
Organic Parameters						
Tannin and Lignin			0.14			
Total Organic Carbon C			2.14			
Field Chemistry (EBA)						
pH			8.45	6.5		8.5
TDS (ppm)			287			500
EC (uS/cm)			573			
Temperature (°C)			14			
Free Available Chlorine			0.05			

Notes:

A. Guidelines indicated for hardness are not CDWQG, rather they are general aesthetic guidelines - exceedences are indicated in yellow highlighting.

Italic and underline indicates exceedence of proposed MAC (ie. arsenic)

Bold with Yellow highlighting indicates exceedence of CDWQG Aesthetic Objective (AO)

Bold Underline with Yellow highlighting indicates exceedence of CDWQG MAC

Results are expressed as milligrams per litre except for pH and Colour (CU), Conductivity (umhos/cm), Temperature (°C) and Turbidity (NTU)

< = Less than the detection limit indicated.

AO = Aesthetic Objective

MAC = Maximum Acceptable Concentration (Health Based)



EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

SMALL PUBLIC WATER SYSTEM ASSESSMENT

PART A: EBA Site Inspection

Inspector: Ryan Martin
Luke Lebel

Date June 16, 2005

WELL ID #	Owner	Location Description
M0181	RCMP	Teslin RCMP Residence

1. Well Location and Potential Contaminant Sources

a. General location of well: (Community, Subdivision, etc.)

Teslin

b. Specific location: (Road or street, Building number, name of owner and/, legal description,

Sawmill Road

c. GPS location: N 6673483 E 627320 elev. 721m ± 12m

d. Is there electric power? Yes No

e. Is there outside water access? Yes No
Not accessible to public

f. Does the well system have:

The system is for the residence only and is from delivery
 15 or more service connections to a piped distribution system? If so how many _____

5 or more delivery sites on a trucked distribution system? If so how many _____

g. Nearest building, specify N/A - Tank is located inside building

h. Distance from well to building N/A

i. If there is an effluent disposal field, is its location known? Yes No

j. Distance from well to nearest point of known field: ~15m from residence

N 6673479
E 627343

k. Well location relative to field: upslope downslope lateral
from residence

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- l. Is there any part of a sewage disposal system(s) or other potential sources of pollution that may pose a health and safety risk within 30 m? Yes No

No part of the property, however, is greater than 30m from a septic source

- m. Is the well located within 300 m from a sewage lagoon or pit? Yes No *N/A*

- n. Is the well located within 120 m from a solid waste site or dump, cemetery? Yes No *N/A*

- o. Is the infrastructure protecting the ^{tank} wellhead, pumphouse, storage tank and/or water treatment plant designed and secured to prevent:

Unauthorized access by humans? Yes No *located inside residence* Entrance by animals? Yes No *n/a*

- p. Is well site subject to flooding? Yes No *N/A*

- q. Is the well site well drained? Yes No *N/A*

- r. Is there a buried fuel tank on the property? Yes No *unlikely*

If yes, is it in use abandoned

Is the location known? Yes No

Distance from the well to known buried tank _____

- s. Are there any other known contaminant sources on the property?

Yes No Describe _____

If yes, specify the source: dump sewage lagoon cemetery other

Potential Source 1: _____; Distance from well to Potential Source 1: _____

Potential Source 2: _____; Distance from well to Potential Source 2: _____

Potential Source 3: _____; Distance from well to Potential Source 3: _____

Potential Source 4: _____; Distance from well to Potential Source 4: _____

- t. Are there other wells on this property? Yes No

How many? _____ in use abandoned require proper sealing

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

2. Well and Wellhead information:

- a. When was well installed? Year N/A Month _____
- b. Type: drilled dug sand point other N/A
- c. Is there a drillers log for the well: Yes No N/A
- d. Is there a surface seal to 6 m Yes No unknown unlikely N/A
- e. Surface casing: Yes Diameter N/A No
- f. Well casing: Diameter N/A Material: steel plastic concrete
- g. Depth of well: N/A measured (if possible) reported from log
- h. Static water level below ground: N/A
 measured (if possible) reported from log flowing
- i. (If granular) Is the well completed: open end casing with a well screen N/A
 with slotted pipe unknown other N/A
- j. (If bedrock) Does the well have a liner? yes No steel plastic N/A
- k. If there is a well screen: length N/A slot size(s) _____
Location of screen: from _____ to _____ from log reported
- l. Is there a sump below the screen? Yes No N/A
- m. Is the well head: in pumphouse in pit pitless adaptor in a building N/A
 in a wooden enclosure other, describe _____
- n. If the well head is located in a wooden enclosure,

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- i. Is the well head below grade? describe in detail N/A
- ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? Yes No
N/A
- iii. Is the wellhead enclosed by fiberglass insulations? Yes No
N/A
- iv. Any evidence of rodents? Specify N/A
- v. Does the well casing have a proper seal cap? Yes No
If no, describe condition N/A

3. Water Supplying This Well:

- a. By definition is the water from a surface water source or under the direct influence of surface water?
 Yes No farther investigation required.
N/A
- If yes is there treatment Yes No
- Explain (filtration, disinfection etc...) _____

4. Aquifer Supplying This Well:

- a. The aquifer is: bedrock granular sediment unknown
N/A
- b. Does water level and/or well capacity show seasonal fluctuation? Yes No
N/A

5. Pump Installation:

- a. Is the well equipped with a pump? yes No N/A
- b. Type of pump: hand electric submersible jet N/A
 shallow well centrifugal other, _____
- c. Description: Manufacturer _____ Model _____
horsepower _____ capacity _____ voltage _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

d. Date installed: N/A By: _____

e. For submersible pump, depth of setting below surface N/A

f. Drop pipe for submersible pump: steel plastic
N/A

g. Pump delivers water to: pressure tank elevated tank other
N/A

h. Are there automatic pump controls: Yes No
N/A

i. Is there provision for taking water samples before water reaches storage? Yes No
N/A

j. Is there a water meter on the system? Yes No
N/A

k. Is the pump and piping protected from freezing? Yes No
N/A

If yes, describe: _____

l. Comments on pump installation: _____

6. Conclusions

a. Comments on overall installation:

b. Recommendations: _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

PART B: EBA Site Inspection

Inspector: BERT ALBISCHER

Date June 16 / 05

WELL ID #	Owner	Location Description
M0181	YCS	TRCHA RES. TESLIN SAWMIK ROAD.

6. Water Treatment

a. Is well water treated? Yes No; Type of treatment:

chlorination iron and or manganese removal other _____

b. Is water entering plumbing or piped distribution system treated with chlorine or another treatment that is as effective as chlorine used to achieve disinfection throughout the system?

Yes No If so how _____

c. If treated with chlorine, is the free residual chlorine concentration less than 0.2 mg/L

Yes No _____ reading.

Tested at _____ (location)

d. Is testing for chlorine residual concentration done at the tap (eg. Kitchen faucet) or from representative points in a piped distribution system, including a point from tap at the end line

Yes No If yes how often? _____

e. If the drinking water is being transported by water delivery truck does it have a minimum chlorine free residual of 0.4 mg/L at the time of fill. Yes No

7. Water Quality (observations):

a. Does the water stain plumbing? yes No slight severe

Type of stain: brown red black

b. Does the water contain sediment? Yes No occasional constant

c. Is there an unpleasant odour? Yes No H₂S Other _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- d. Is there an unpleasant taste? Yes No brackish Other _____
- e. Is there a history of bad bacterial analyses? Yes No
- f. Is there a chemical analysis? Yes No adequate incomplete
- g. Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? Yes No
- h. Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the range 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? Yes No unknown
- i. If yes is the test performed in accordance with manufactures directions? Yes No unknown
- j. Is a record of the date, time, name of person performing the test and results of the drinking water sample kept? Yes No

TANK AND PIPING DETAILS

Tank Room

Is there a water tank? Yes No Details:

1250 Vertical PE TANK

Where is it located?

Comments: basement

Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water?

YES NO

Comments: _____

Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES

NO

Comments: _____

Are there other heat sources near the tank? YES NO

Comments: _____

Is there waterproof flooring with a sealed base to contain spills? YES NO

Comments: _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

Overall Tank

What are the tank size and dimensions?

87" ~~Ø~~ x 65" H

What material is the tank constructed of?

POLYETHYLENE

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments: _____

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO

Comments: _____

Is there any sediment or scum in bottom of tank? YES NO

Comments: _____

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

8. Conclusions

a. Comments on overall installation:

This is a typical water delivery
water system.
Piping system is in good condition with proper
supports

b. Recommendations:

Clean tank, superchlorinate
system.

Test chlorine residual
frequently.

Reinstall pipe with proper
support

Clean tank per manufacturer instructions.



Photo 0215: M0181 delivery water fill



Photo 0022: M0181 5000 L water storage tank



Photo 0023: M0181 Pressure tank



Photo 0025: M0181 Water softening system