



LORAX
ENVIRONMENTAL

MW14-06A / BH7 / CFD-0453

(Page 1 of 2)



Drilling Started : Sep 16, 2014
 Install Completed : Sep 22, 2014
 Drilling Method : Diamond / PQ
 Drilling Company : CYR Drilling

Northing Coord. : 6,974,582.81
 Easting Coord. : 585,202.21
 Ground Surface : 1183.0 m amsl
 Logged By : Kaminak
 Checked By

Coffee Creek Gold
 Project #: A362-4

Depth (m)	Elev. (m amsl)	DESCRIPTION	RQD (%)		Fracture = Fr Fault = FIt	Packer Test Interval (mbgs)	K (m/s)	Depth (m)
			0	50				
		Water Level: 1053.18 m amsl 07-Oct-14 @ 9:46						
0	1183.0	OVERBURDEN						Well: MW14-06A Elev.: 1183.9 m amsl (TOC)
0	1180	FELSIC GNEISS Felsic gneiss with muscovite rich mafic bands, fractures with limonite alteration and interstitial limonite *Drilling additive (Pure Vis) used at 10 m onwards						Stickup surface Casing Collapsed Abandoned in 2015
20	1160	Weak zone, weakly oxidised with fracture controlled limonite, strong fracture controlled clay alteration 21.9 to 25.3 m HYDROTHERMALLY ALTERED ROCK Zone, Oxidized and brecciated hydrothermally altered rock						
40	1140	FELSIC GNEISS Felsic gneiss with weak fracture controlled limonite and clay alteration						
60	1120	GNEISS Felsic gneiss mixed with minor mafic, amphibole rich, bands			N/A	N/A	N/A	2" Sched. 80 PVC Cement Grout
100	1080	ANDESITE Fine grained mafic dyke						
120		GNEISS Felsic gneiss ANDESITE Fine grained, massive, mafic dyke GNEISS Mixed felsic gneiss with mafic, amphibole rich mafic bands						

03-04-2016 P:\A362-4 (Coffee Gold Project - Hydrogeology)\Data\BH Logs\Quicklog\2014\MW14-06A.bor



Drilling Started : Sep 16, 2014
Install Completed : Sep 22, 2014
Drilling Method : Diamond / PQ
Drilling Company : CYR Drilling Ltd.
Supervised By : [REDACTED]

Northing Coord. : 6,974,582.81
Easting Coord. : 585,202.21
Ground Surface : 1183.0 m amsl
Logged By : Kaminak
Checked By : [REDACTED]

Coffee Creek Gold
Project #: A362-4

Depth (m)	Elev. (m amsl) 1183.0	DESCRIPTION	RQD (%)		Fracture = Fr	Fault = Ft	Packer Test Interval (mbgs)	K (m/s)	Depth (m)
			0	50	100				
		Water Level: 1053.18 m amsl 07-Oct-14 @ 9:46							
120	1060	*Minor circulation loss noted at 127.5 m, possibly entering formation at ~25 m *Stronger iron staining at 129.5 to 130.5 m suggests presence of water							120
140	1040				N/A	N/A	N/A		140
160	1020	*Minor iron stained fracture zones suggesting presence of water at ~165, 175, 181, and 187 m							160
180	1000	Strongly foliated mixed felsic gneiss, bleached, weak carbonate alteration, white clay alteration to feldspars, weak fracture controlled limonite alteration 171.6 to 177.42 m Zone, mixed gneiss, possible early mafic dyke with weak alteration 177.4 to 179.17 m Strongly foliated mixed felsic gneiss, weak carbonate alteration 179.2 to 183.2 m							180
200	980	Mixed felsic gneiss, 187.3 to 187.8 m, and EOH fracture zone with limonite alteration							200
220	960	EOH @ 216 m *Comment from supervising hydrogeologist, all other descriptions provided by Kaminak N/A: Borehole not packer tested or logged for structure							220
240									240

Well: MW14-06A
Elev.: 1183.9 m amsl (TOC)

