








<b>Project</b>		Groundwater Monitoring Well Installations		<b>Project #</b>		W801500	
<b>Location</b>		Al's Environmental Cleanup Inc. LTF		<b>BH number</b>		MW06	
<b>LSD</b>				<b>Zone</b>		08V	
<b>Community</b>		Mayo, YT		<b>GPS</b>		0457276 E	7058080 N
<b>Sample type</b>		<input type="checkbox"/> Disturbed	<input type="checkbox"/> No Recovery	<input checked="" type="checkbox"/> SPT			
<b>Backfill type</b>		<input checked="" type="checkbox"/> Bentonite	<input type="checkbox"/> Slough	<input type="checkbox"/> Concrete	<input type="checkbox"/> Filter sand	<input type="checkbox"/> Drill cuttings	
<b>Depth (m)</b>		<b>Soil Discription</b>		<b>MW06b</b>		<b>Sample Type</b>	<b>Depth (m bgs)</b>
from	to						
0.88	0	PVC stick up					
0	0.85	Organics 0.85 m top of bentonite					
1	2	SILT, sand, dry light brown 1.8 m top of drill cuttings					
2	8	GRAVEL, SAND, trace silt, cobbles, dry light 7.62 m harder drilling					
8	13.11	GRAVEL, SILT, sand, cobbles, dry 11.3 m top of bentonite 12.0 m top of sand					
13.11	17.68	SAND Silt 13.11 m top of screen 13.71 m saturated					14.53
		End of hole at 17.68 m					
West 80 Environmental Consulting Ltd.							