101130014

# Water Well Log

**Property owner's name and address**

[redacted]

Haines Junction, YT

**Well site address**

Next to MacKenzie Lodge
Beside Haines Jct




Sketch map of well location in the box above

| Formation log | colour | hardness | from | to |
|---|---|---|---|---|
| gravel, silt | | | 0 | 9 |
| gravel | | | 9 | 35 |
| silt | | | 35 | 45 |
| glacial till | | | 45 | 70' |
| gravel | | | 70 | 75' |
| silt | | | 75 | 77' |

Well depth 74'
Datum point ground
Use Domestic ✓ Industrial
Municipal Monitoring
Other

Method of drilling
Cable tool Air rotary ✓
Other

Casing type steel ✓
welded ✓ Drill Shoe ✓
shoe ID 5½"
Hole diameter
6" 0-74'

Screen None

Development method, duration
Air 2 hrs
Static water level 43
Specific capacity 7½ gpm
Pump

Other information

**Whitewater Resources**
Box 33012
Whitehorse, YT. Y1A 5W5

Driller [redacted]

Date completed Oct 24/02