



Field Report

13 MacDONALD ROAD
 WHITEHORSE, YUKON
 Y1A 4L1
 PHONE (867) 633-3070
 FAX (867) 633-5758

105D10

#204100538

Started June 16 2003

Completed June 18 2003

NAME & ADDR. OF CLIENT [REDACTED]	DESCRIPTION OF WORK Water Well	LOCATION OF WORK #6 LUPIN
BOY 31023		MARY LAKE SUBD
WHITEHORSE Y1A 5P7	03-9-4	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
120'	190'	Bedrock	MOVE				
190'	206'	Sands					
			* Note: Cut drill pad w/saw	June 16/03	1100	100	2
			- Wait @ shop for a Helper.	June 17	800	930	1.5
			- Mob.	June 17	930	1000	.5
			- Setup	June 17	930	1200	2.5
			- Develop	June 17	1200	130	1.5
			- Trip out out on D.H. trip in	June 17	130	200	.5
			- Drill 86'	June 17	200	600	4
			- Develop	June 17	600	630	.5
			- Trip out	June 17	630	700	.5
			- Back to Shop.	June 17	700	730	.5
			- Load H ₂ O; out to site	June 18	800	900	1
			- Trip in + develop	June 18	900	1030	1.5
			- Trip out.	June 18	1030	1100	.5
			- Set in pump + demob.	June 18	1100	200	3
			- Fix fence; drive back to shop	June 18	200	300	1

RECORD OF CASING & PIPE

SIZE	TYPE	SIZE	TYPE
4 1/2"	Conv. drill pipe		
FEET	INCH	FEET	INCH
86'			

REMARKS:

GPM	2.5 to 3
H2O TEMP	
STATIC LEVEL	16.77
GROUND LEVEL	14.85
TOP OF CASING	14.93
TOTAL DRILL	

June 24/03 Note
 m.s.d.
 We never drilled original well we just deepened it recently & got more H₂O in it also air developed it

SIGNATURES

MIDNIGHT SUN _____

CLIENT [REDACTED]

TITLE _____

TITLE _____