

# City of Dawson

# Borehole No: MW05-17

Project: Monitoring Well Installation - Quigley SWMF

Project No: ENW.WENW03037-01

Location: Quigley Solid Waste Management Facility

Dawson, Yukon

UTM: 583211 E; 7101589 N; Z 7

Depth (m)	Method	Soil Description	Notes and Comments	MW05-17	Depth (ft)
0	Solid and Hollow stem auger	SAND AND GRAVEL - some cobbles, trace silt, damp, brown, fine to coarse sand, fine to coarse rounded to subrounded gravel	Pipe stickup = 0.90 metres		0
1		SILT - trace sand, organics, damp, soft, dark grey			1
2		SAND AND GRAVEL AND SILT - some cobbles, moderately sorted, very wet, brown, fine to coarse sand, fine to coarse subrounded to rounded gravel			2
3		- increasing sand and gravel, moist			3
4				4	
5				5	
6				6	
6.10		END OF BOREHOLE (6.10 metres)			6.10
7					7
7.5					7.5



Contractor: Midnight Sun

Completion Depth: 6.1 m

Drilling Rig Type: Tracked MARL M4CT

Start Date: 2017 July 28

Logged By: AS

Completion Date: 2017 July 28

Reviewed By: SK

Page 1 of 1