



# Field Report

(167070007)

Started Oct. 10.....1989

Completed Oct. 11.....1989

PH. 633-3070 TELEX 036-8496  
P.O. BOX 4391  
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W/W	
		Destruction Bay
	89-1A-40	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Load, ing	Oct. 10	8:00	11:30	3.5
			Traveling	"	11:30	3:30	4
			start #69	"	3:30	4:00	0.5
			move on set up	"	4:00	5:00	1
0	10	silt	Gr. sand.	"	5:00	7:00	2.
10	46	silt	Gr. Clay				
46	60	till					
60	79	till		Oct. 11	8:00	9:30	1.5
79	85	Gr.	sand silt				
			set screen Develop	"	9:30	1:00	3.5
			move off.	"	1:00	1:30	0.5

Rcprd. of Casing & Pipe

Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
83	6		

Remarks:

1-6" odex shoe (ss)  
20 slot  
5 7/8" bit pin  
3" riser-K Packer  
20 GPM.

Static Level	Total Rig Time	hrs.
Ground Level 8'	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....