



Field Report

107-071013

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Started Sept. 29 1989

Completed Sept. 30 1989

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Municipal Engineering	W / W	Curling Rink
Whitehorse Yukon	89-1A-36	Destruction Bay

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			loading	Sept. 29	8:00	10:00	2
			Travel	"	10:00	3:00	5
			move on setup	"	4:00	5:00	1
0	7	silt		"	5:00	9:00	4
7	49	silt	Clay Gr. sand.				
49	55	Gr.	sand silt				
55	60	Clay					
60	71	clay		Sept. 30	8:00	10:30	2.5
71	93	Gr.	clay				
93	104	Gr.	sand some silt				
			set screen - Develop	"	10:30	2:30	4
			move off.	"	2:30	3:30	1

Rcd. of Casing & Pipe

Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
101			

Remarks:

1-6" o dex shoe (ss)
20 slot
5 7/8" bit pin
8" riser K Pack
5 GPM

Static Level	Total Rig Time	hrs.
Ground Level 19'	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....