



PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Field Report

109010055

Started Nov. 17 19.86
Completed Nov. 17 19.86

③

NAME AND ADDRESS OF CLIENT		DESCRIPTION OF WORK		LOCATION OF WORK	
[REDACTED]		W / N		Horden skid sub.	
[REDACTED]				Lot # 106 car marks	

FORMATION LOG		DESCRIPTION OF WORK	TIME	
FROM	TO		DATE	HOURS
		MOVE		
0'	27'	Gr. sand	Nov. 17 6:30	9:00 2.5
27'	52'	sand cob. silt	" 9:00	2:30 5.5
52'	61'	same Gr.		
		Trouble with casing hammer		
		set 10 slot screen	" 2:30	3:00 0.5
		Develop	" 3:00	4:30 1.5
		move to lot in town	" 4:30	5:30 1
		casing hammer not working	" 5:30	8:00 2.5
		Travel to Whitehorse	" 8:00	10:30 2.5

Rc'd. of Casing & Pipe			Remarks:	
Size	Type	Size Type		
Feet	Inch	Feet	Inch	
58				1- Drive shoe. 2- riser lead packer 1- 5 7/8" bit riser 10 slot screen. screen bottom 61'
			Static Level	hrs.
			Ground Level	47 hrs.
			Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....