



Field Report

(109150036)

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started..Sept..6.....1988

Completed..Sept..6.....1988

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
se/Kirk Indian Band Pelly	W/W 88-1A-33	House #1 [REDACTED]

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
0	3	silt		Sept 6	8:00	10:00	2
3	40	sand	Gr. Cobs.				
			set screen. Develop	"	10:00	12:00	2

Rcrd. of Casing & Pipe			
Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
38			

Remarks:	
1-shoe.	
20 slot screen	
2' riser - packer to bottom	
9 GPM	
Static Level	Total Rig Time hrs.
Ground Level 24'	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT [REDACTED].....
TITLE.....