



FIELD REPORT

201020068

Midnight Sun Drilling Co. Ltd.  
 #13 MacDonald Road  
 WHITEHORSE, Y.T. Y1A 4L1  
 Phone (403) 633-3070

Started. June 13... 1997  
 Completed. June 19... 1997

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W/W 97-8-10	Watson Lake

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Load	June 13	4:30	6:00	1.5
			Travel	"	7:00	11:00	4
			mud on set up	June 14	7:00	9:30	2.5
0	66	sand	Gr. silt	"	9:30	4:00	6.5
66	120	silt	clay				
			Pull Broken casing	"	4:00	8:00	4
			spun bit off hammer	June 15	7:00	7:30	12.5
			drive sub. lost retainer				
			Rings				
			reset casing to 120'				
120	140	silt	Clay	June 16	7:00	5:00	10
			Drilled open hole to				
			180' Trip out.				
			made retainer Ring	"	8:00	9:30	1.5
			trip in very slow				
			Drilling				

ord. of Casing & Pipe			
Size	Type	Size	Type
6			
feet	Inch	Feet	Inch
57			

Remarks:	1 - drive shoe -
STATIC LEVEL	Total Rig Time
Ground level	Total Standby
Top of casing	Drilling Mud

SIGNATURES

MIDNIGHT SUN.....  
 TITLE.....

CLIENT.....  
 TITLE.....



