



# Field Report

201020074

PH. 633-3070  
P.O. BOX 4391  
WHITEHORSE, YUKON

Started July...19...1985  
Completed July...19...1985

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W/U	New sub. Div.
Stanley Asca	Hole #2.	Watson Lake,
Whitehorse.		

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE Job #17.				
			move set up.	July 19	4:00	4:30	0.5
5'	46'	Gr. Sand.		"	4:30	6:00	1.5
16'	55'	fine sand silt some Gr.					
			pull back to 44' set screen	"	6:00	6:30	0.5
			Develop.	"	6:30	8:00	1.5
			move off.	"	8:00	8:30	0.5

rd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
42'		6 5/8"		42' casing 6 5/8"
				1- drive shoe
				Lead pack
				2' riser
				15 slot screen
				5 7/8" pit pin
				screen bottom 44'
				Static Level
				Ground Level 10'
				Top Of Casing
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....  
TITLE.....

CLIENT.....  
TITLE.....