

201020126

Field Report



PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

105 A 02
Zone 9



Started June 12 1971

Completed June 13 1971

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
LMA.	Water Well 6 3/8" Diam	Air Port. Watson Lake
	91-1A-10	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Move on set up	June 12	8:00	11:20	2.5
0	47	Gr.	sand	"	11:30	6:30	6.5
47	56	fine	sand silt				
56	62	silt					
62	112	sand	Gr.				
112	120	fine	sand Gr. sand				
			setting screen	June 13	7:00	11:00	4
			Develop	"	11:00	6:30	7.5

Rcprd. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
6"				1- odder shoe		
Feet	Inch	Feet	Inch	1- 40 slot screen		
107				5/8" bit pin		
				K-Packer		
				75 RPM		
				108' bottom of screen.		
				Static Level	Total Rig Time	hrs.
				Ground Level 16	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....