



201020128

Field Report

105 A 02
zone 9

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

Started... Sept. 18... 1999

Completed Sept. 21... 1999

PHONE (403) 633-3070
TELEX 036-8496

P.O. # 5402

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
town of Watson Lake	W/W 93-1A-16	SKI Club.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on setup	Sept 18	10:30	1:30	3
			Pull screen weld on drive casing 7'				
			Trip in to bottom				
73'	138'	BR	Broken Black shale	"	1:30	4:30	3
139'	148'	BR					
			Developer	"	4:30	7:00	2.5
			Trip out check hole	"	7:00	7:30	0.5
			Drove 13' casing cleaned hole	Sept. 21	8:00	1:30	5.5
			Developed				
			move off.	"	1:30	2:00	0.5
			(4.00 on loss)				

Rcrd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	
				5 GPM flowing
				20' casing

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing (Flowing)	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....