



# Field Report

# 201020149

Started *May 5*.....19*91*

PH. 633-3070 TELEX 036-8496  
P.O. BOX 4391  
WHITEHORSE, YUKON

Completed.....19...

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<i>Kilborn Eng.</i>	<i>TH #14</i>	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
<i>0</i>	<i>40</i>	<i>Gr</i>	<i>move set vs sand silt</i>	<i>May 16</i>	<i>4:00</i>	<i>5:30</i>	<i>1.5</i>
				<i>11</i>	<i>5:30</i>	<i>7:00</i>	<i>1.5</i>
<i>40</i>	<i>45</i>	<i>Gr.</i>	<i>sand silt</i>	<i>May 17</i>	<i>7:00</i>	<i>8:00</i>	<i>1</i>
<i>45</i>	<i>49</i>	<i>Broken BR.</i>					
<i>49</i>	<i>51</i>	<i>BR.</i>					
			<i>Pull 11' casing</i>	<i>11</i>	<i>8:00</i>	<i>8:30</i>	<i>0.5</i>

Rcrd. of Casing & Pipe

Size	Type	Size	Type
Feet	Inch	Feet	Inch
<i>6 5/8</i>			
<i>43</i>	<i>6</i>		

Remarks:

*1- o dex shoe.*

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....  
TITLE.....

CLIENT *[Redacted]*.....  
TITLE *Engineer*.....