



# Field Report

PH. 633-3070 TELEX 036-8496  
 P.O. BOX 4391  
 WHITEHORSE, YUKON

#201020152 Started May 5 1991  
 Completed.....19....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Kilborn Eng.	water well TH # 17	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move set up	May 23	1:30	3:30	2
2	16	Gr.	sand silt	"	3:30	7:30	4
2	22	silt	Clay Gr.				
2	54	silt	sand Gr.				
4	76	till	(brown)				
6	80	silt	Gr. sand.				
0	93	silt	Gr. sand	May 24	6:30	2:00	7.5
3	106	silt	sand Gr.				
6	131	Gr.	sand silt				
1	137	fine	sand silt some Gr.				
37	142	Gr	sand silt				
42	173	Gr	sand some silt				
23	175	BR.					
			cutting off shoe	"	2:00	3:00	1
			set screens	"	3:00	4:00	1
			Develop.	"	4:00	5:30	1.5

d. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
58				1- casing cut.		
				1- odex shoe		
feet	Inch	Feet	Inch	2- 20 slot screens		
69				screen bottom		
				2' visor pipe		
				K Packer		
				2' locking cap.		
				Name Plate		
				Static Level	Total Rig Time	hrs.
				Ground Level	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....  
 TITLE.....

CLIENT. KILBORN  
 TITLE. [REDACTED]