Field Report

#20102O156 Started May 5 19 91

Completed.....19....

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.
PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Kilborn Eng	water well TH#21	

FORMATION LOG FROM	TO	FORMATION
0	22	silt
22	85	Gr. sand silt
85	31	silt Gr. sand
31	66	Gr. sand silt
66	71	weathered BR.
71	75	BR

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE				
move set up	May 29	2:30	4:30	2
Gr. Sand	"	4:30	7:00	2.5
Sand silt				
Gr. Sand				
sand silt				
weathered BR.				
BR				
Develop	"	7:00	7:30	0.5
Develop	May 30	6:30	9:30	3

Casing & Pipe Size	Type	Size	Type
5/8			
Feet	Inch	Feet	Inch
6'	6		

Remarks:
1- odex shoe
2' locking cap.
Name Plate

Static Level		Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN..... CLIENT.. KILBORN .....

TITLE..... TITLE... [redacted] .....

ow Printers