



PH. 667-6144

P.O. Box 4391

FIELD REPORT

#23

Started Oct. 21.....1981

Completed Oct. 21.....1981

#201020168

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W / W	turn off to Watson Lake Flying Club.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up	oct. 21	8:00	9:00	1
0'	9'	Gr. sand		"	9:00	11:30	2.5
9'	37'	sand, fine					
37'	50'	Gr. sand some silt					
50'	60'	fine sand Gr.					
			set screen	"	11:30	12:00	0.5
			Develop	"	12:00	2:00	2
			move off. to Watson	"	2:00	2:30	0.5
Paid in full by Check # 3239							
total amount \$2650.00							

Rcd. of Casing & Pipe				Remarks:	
Size	Type	Size	Type		
6 5/8	280			1- drive shoe	
Feet	Inch	Feet	Inch	1- 5 7/8" bit pin (scrub bottom)	
58'				10 slot screen	
				2 riser lead packer	
				5 G.P.M.	
STATIC LEVEL				Total Rig Time	hrs.
Ground level 42'				Total Standby	hrs.
Top of casing				Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....