



P.O. Box 4391

FIELD REPORT

201060002

105 A 06
zone 9

Started... June 22 1974..

Completed... June 25 1974..

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Devil's Paw	Water Well	Same
Mile 721		
Alaska Highway		

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
0	9	sand gravel	MOVE boulders from Whitehorse	6/22/74	8:30	15:30	9
9	13	sandy silt	3.1 hrs - 9.4 hrs				
13	30	sand gravel	boulders drilling 10.3				
30	33	silty clay	(16')	6/23/74	08:30	18:30	10
33	49	sand gravel	boulders		19:30	22:00	2.5
		with silty sand layers					
49	86	brown gray till	(46)	6/24/74	09:00	21:00	12.0
86	118	brown bed rock			22:00	00:30	2.5
118	137	black bed rock					
137	160	green bed rock		6/25/74	08:00	12:00	4.0
					13:00	21:00	8.0

Rcrd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	drilled 7 3/8" Ø to 26'
22'				drilled 6 1/4" Ø to 59.5"
19				set 54' casing
20'				drilled with 4 7/8"
STATIC LEVEL				Total Rig Time 39 hrs.
Ground level 39'				Total Standby hrs.
Top of casing 40.5				Drilling Mud 9 sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....