



PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Field Report

B-ID 204030001

Started... Aug. 21 19. 84

Completed... Aug. 23 19. 84

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Mount Schookna Mine	W/W	Mount Schookna on Annie Lake Rd.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE TRAVEL from carcass cut off	Aug 21	1:00	3:30	
			FIRE - Fix Air Lines	"	3:30	7:00	
			Move CONT.	"	7:00	8:00	
			LOAD WATER - setup -	"	9:00	10:00	
0	17'	BR	Fractured Rock - Drive casing to 17'	Aug 22	7:30	8:30	
			Pullout - put on down hole hammer 5 3/4"	"	8:30	9:00	
17'	240'	BR.	Brown grey Rock with some green hard - same from 17'-240'	"	9:00 AM	10:00 PM	
240'	250'	Br	Same as above	Aug 23	7:30	8:00	
			Develop to H.G.P.M.		8:00	1:00	
			WATER Between 200'-250' gradual				
			Pullout - LOAD		1:00	2:30	
			TRAVEL to Shop		2:30	6:00	

ord. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
6"	280w			5 3/4" Hole 1 - Drive Shoe 1 - Well Seal - (Welder was not working Put on Well Seal instead of Cap)
Feet	Inch	Feet	Inch	
18'	0"			
				Static Level 107'
				Ground Level
				Top Of Casing
				Total Rig Time 34 hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN
TITLE.....

CLIENT.....
TITLE.....