



# Field Report

B-ID 204080004

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

Started June 19.....1990

Completed June 21....1990

PHONE (403) 633-3070  
TELEX 036-8496

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Box 3954	W/W	Lot 922 - Judas Creek subdiv.
21A 5M 90-1A-20		

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up	June 19	8:00	11:00	3
0	7	Gr. sand		"	11:00	5:00	6
7	11	silt					
11	97	Gr. sand					
97	120	Gr. sand silt					
			Broke off casing shoe.				
			crew travel	"	5:00	6:00	1
			crew travel	June 20	8:00	9:00	1
			Pull casing	"	9:00	12:00	3
			Redrill to 120'	"	12:00	5:30	5.5
120	124	Gr. sand silt					
124	127	clay					
			crew travel	"	5:30	6:30	1
			crew travel	June 21	8:00	9:00	1
			set screen	"	9:00	10:00	1
			Develop	"	10:00	1:00	3
			move off to shop	"	1:00	3:30	2.5

Rcprd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
6				lost 1- odex shoe
Feet	Inch	Feet	Inch	1- odex shoe.
123				25 slot - K Packer
				5 7/8" bit pin
				10 - GPM
				screen bottom 124'

Static Level	Total Rig Time	hrs.
Ground Level 96'	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....