



Field Report

204080017

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Started Nov. 21.....1988

Completed Nov. 22.....1988

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W/W	Lot #1012 Alaska Hwy
	88-1A-53	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			loading	Nov. 21	10:00	12:00	2
			move on set up	"	12:30	3:00	2.5
0	40	silt	clay layers	"	3:00	6:00	3
			Blow Power steering base #51				
			crew travel	"	6:00	7:00	1
			crew travel	Nov. 22	8:00	9:00	1
40	90	silt	Clay layers	"	9:00	1:30	4.5
90	104	silt	Gr. sand				
104	112	Gr.	sand some silt				
112	113	clay					
			set screen Develop	"	1:30	4:30	3
			move off	"	4:30	5:30	1
			crew travel	"	5:30	6:30	1

Rcrd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
6				1-odex shoe
Feet	Inch	Feet	Inch	20 slot screen
111	6			2 riser load Packer
				5 7/8" bit pin
				bottom of screen <u>112'</u>
				10 GPM
				Static Level
				Ground Level 22 + rising
				Top Of Casing
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT [REDACTED].....
TITLE [REDACTED].....

16 54