

204080036

105 D 08



Field Report

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1



Started.. Sept 2 .. 1988

Completed. Sept 3 .. 1988

PHONE (403) 633-3070
TELEX 036-8496

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[Redacted]	W/W	Lot # 28
	88-1A-32	New Constakology subd.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Loading	Sept 2	8:00	3:00	7
			move on set up	"	4:00	5:30	1.5
0	32	silt	Gr cobs.				
32	40	Till	Cobs, silt Gr. layers.				
40	131	Till	cobs. silt Gr. layers	Sept 3	7:00	5:30	10.5
131	176	clay					
176	190	Till	cobs. silt Gr. layers				
190	215	soft	weathered BR.				
			Develop	"	5:30	7:30	2
			move off to shop	"	7:30	9:00	1.5

Rcrod. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	1 - shoe
195				1.5 GPM. X
20'	B.P.R			
	Wen			
				Static Level
				Ground Level
				Top Of Casing
				Total Rig Time
				Total Standby
				Drilling Mud

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....