



Field Report

PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

204100037

Started... Nov. 11.....19.92

Completed... Nov. 13.....19.92

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	Water Well rig 9-	Dive Ridge Lot 6

FORMATION LOG			DESCRIPTION OF WORK	TIME			
DM	TO	FORMATION		DATE	FROM	TO	HOURS
	20	Gravel	MOVE				
	58	Sand/Gravel	2 min haul-unload	10th	15:30	18:30	3
3	62	Silt Gravel	3 haul	11	8:00	8:30	1/2
	69	Sand Gravel	3 Dhill	11	8:30	17:30	9
	88	Silt Gravel	3 haul	11	17:30	18:00	1/2
	96	Sand	3 haul	12	8:00	8:30	1/2
	110	Silt Gravel	3 Dhill	12	8:30	17:00	8 1/2
5	122	Silt Sand	3 haul	12	17:00	17:30	1/2
2	138	Clay till	3 haul	13	8:00	8:30	1/2
8	264	Weathered bed rock	Dhill	13	8:30	15:30	9
			Dhill	13	15:30	16:00	1/2
			haul-load water haul	15	8:00	9:00	1
			Packup Load		9:00	11:00	2

Ord. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
2 5/8	2500			
Feet	Inch	Feet	Inch	
56				

Static Level	83 1/2'	Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN. [REDACTED]

TITLE.....

CLIENT.....

TITLE.....