



PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Field Report

BID 204100290

105D10

Started... JUNE 10 1980

Completed... JUNE 12 1980

86-2A-6

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
XXXX [REDACTED]	W/W	Lot # 62 Mary Lake

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE	JUNE 10	1:30	2:00	
				"	2:00	5:00	
0'	6'	SAND					
6'	22'	FINE SAND					
22'	36'	SAND, SOME GRAVEL					
36'	51'	SAND & GRAVEL					
51'	50'	Silt (WET)					
			TRAVEL	"	5:00	5:30	
			LOAD FEEL + CASTING	JUNE 11	8:00	8:30	
			TRAVEL	"	8:30	9:00	
			(Hubs: fix pull down chains)	"	9:00	6:00	
50'	54'	WET Silt					
54'	107'	Silty clay					
107'	126'	Silty SAND + gravel (WATER) boulders					
			TRAVEL	"	6:00	6:30	
			TRAVEL	JUNE 12	8:00	8:30	
126'	128'	Silty SAND gravel + boulders (DEVELOP)		"	8:30	10:00	
			INSTALL SCREEN		10:00	11:00	
			DEVELOP		11:00	4:30	

Rcd. of Casing & Pipe

Size Type Size Type

Feet Inch Feet Inch

Remarks: Pullout - LOAD - TRAVEL

126' - 250 WALL 10" casing + shoe

10 SLOT - 2' RISER - 5 7/8" Bit Pin - LEADFREE

DEVELOPED TO 6 P.M.

Static Level	100 ?	Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN..... [REDACTED]

TITLE..... [REDACTED]

CLIENT.....

TITLE.....