



Field Report

Feb 2/05

B 204100469
M 2041004691

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Started.....19....

Completed.....19....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W/W	Lot 165
		Venus Place
	89-11A-42	Golden Horn Subdivision

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Load + Travel.	Oct 16	8:00	10:00	2
0	140'		Drilled to 140' + casing broke.	"	10:00	7:00	9
			Get casing jacks + Travel.	Oct 17	8:00	11:00	3
			Pull casing	"	11:00	5:00	6
			Re bevell all casings	"	5:00	7:00	2
2	140'	Sand + Cobbles.	Travel	Oct 18	8:00	9:00	1
				"	9:00		
10	155'	Gravel		"			
25	160'	Silt.		"		7:00	10
			Travel.	"	7:00	7:30	.5
			Travel.	Oct 19	8:00	8:30	.5
183	Silt						
	165	Silt			8:30		
2	183	Gravel.				12:00	3.5
			Develop Move off + Travel.		12:00	5:00	5

1. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
7/8				1 drive shoe Screen is at 180-183 1 - 20 slot 1 - K packer 1 screen bottom 1 - well cap.
1 1/2	Inch	Feet	Inch	
0'				
				3 gram.
				Static Level 130'
				Ground Level
				Top Of Casing
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN. [REDACTED].....
TITLE.....

CLIENT.....
TITLE.....