



PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON


Field Report

Feb 3

B-ID 204100472

Started... JUNE 5 1986

Completed... JUNE 7 1986


NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
 Box 4749 Whitehorse Y1A4N6	MARY LAKE - SOIL DECOMPOSITION W/W	MARY LAKE


FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE LOAD CASING - CHANGE SEAL ON CASTING HAMMER	JUNE 5	8:00	11:00	
			TRAVEL TO MARY LAKE	"	12:00	12:30	
			SET UP WELD ON SHOE	"	12:30	1:00	
0'	9'	FINE SAND	+ gravel	"	1:00	4:00	
9'	23'	FINE SAND					
23'	54'	FINE SAND	+ gravel (damp)				
54'	67'	COARSE SAND	+ gravel (WET)				
67'	40'	CLAY	TILL				
			TRAVEL	"	11:00	11:30	
			TRAVEL	JUNE 6	8:00	8:30	
			Pull back to 65' - DECOMPOSE	"	8:30	10:00	
50'	57'	CLAY TILL		"	10:00	1:00	
57'	97'	TILL	+ BOLLIDERS				
97'	110'	BR	DECOMPOSED GRANITE				
			Pull out - put on HAMMER	"	1:00	1:30	
110'	260'	BR	DECOMPOSED GRANITE 16:PM	"	1:30	7:00	
			TRAVEL	"	7:00	7:30	

Crd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN... 

TITLE..... 

CLIENT.....

TITLE.....