#20410054 2

Field Report

105 D 10

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.

PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

[redacted] Lot 41

86-2A-5

Started..JUNE...9.....19.86.

Completed..JUNE.10.....19.86.

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[redacted]	W/W	# 29 FIREWEED DRIVE MARY LAKE SUBDIV.

FORMATION LOG FROM	TO	FORMATION
0'	9'	SAND
9'	47'	SAND & gravel with Boulders
47'	69'	Silty Sand & gravel
69'	90'	Silty till with cobbles (wet)
90'	164'	B.R. Reddish Brown 2 gpm.
164'	232'	B.R.

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE LOAD	June 9	9:00	10:00	
SOME gravel	"	10:00	6:00	
TRAVEL	"	6:00	6:30	
TRAVEL - LOAD WATER	June 10	9:00	9:30	
	"	9:30	10:30	
DRILLED TO 6 G.P.M.	"	10:30	12:30	
PULL OUT - LOAD	"	12:30	1:30	

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

92' - 250 WALL - 10" Casing & Shoe

Static Level	58'	Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN..... [redacted] .....

TITLE..... .....

CLIENT.....

TITLE.....

Willow Printers