

204100543



Field Report

105D 10

Started... Oct 20... 1987

Completed... Oct 22... 1987

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON



NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[Redacted]	Water well	Mahy Lake
Lot 71 #96 FIREWHEEL MAAY LAKE Whitehorse		

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
0	42	Sand Gravel	MOVE	Oct 20	10:30	11:15	
42	160	Silt	Set up.		11:15	12:00	
160'	177'	Gravel	Drill 0-140'		12:00	18:00	
			Travel		18:00	18:30	
			Travel	Oct 21	8:30	9:00	
			Start up water Rig		9:00	9:30	
			Drill -140-177'		9:30	12:00	
			Pull Rods		12:00	12:30	
			Install Rods Screen		12:30	2:30	
			Develop		2:30	5:30	
			Travel		5:30	6:00	
			Load casing	Oct 22	8:00	8:30	
			Travel		8:30	9:00	
			Start up		9:00	9:15	
			Develop		9:15	11:00	
			Move over		11:00	12:00	

Rcprd. of Casing & Pipe			
Size	Type	Size	Type
6"	250		
Feet	Inch	Feet	Inch
172'			

Remarks:	
#20 slot Screen set at 177'	
3 1/2" pipe	
3 1/2" apt Pin on Screen Bottom	
1. 18" Risert Pipe	
1. Lead Pack	
1. Drive Show	
GPM	
Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES [Redacted]

MIDNIGHT SUN..... CLIENT.....

TITLE..... TITLE.....