







# Field Report

Started... JULY 11 ...1983

Completed... JULY 14 ...1983

PH. 633-3070  
P.O. BOX 4391  
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
LO BIRD TR. PARK	W/W	ICE LAKE

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE LOAD BIT + SUB TRAVEL	JULY 14	8:00	8:30	
			RUN IN RODS WITH H <sub>7</sub> BIT	"	8:30	9:30	
300'	340'	BR		"	9:30	12:30	
			DEVELOPE	"	12:30	2:30	
			PULL OUT - LOAD - CUT CASING	"	2:30	4:30	
			MOVE OFF - TRAVEL TO SHOP	"	4:30	5:30	

Rcord. of Casing & Pipe

Size	Type	Size	Type
Feet	Inch	Feet	Inch

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

--	--	--	--

Remarks:

10' - 6" casing + SHOE

H<sub>7</sub> TRICONE

DEVELOPED TO 5 G.P.M. AT SPOUT

ESTIMATED 8-10 G.P.M AT 300'

Down Hole hammer would not hammer past 300'

Static Level 7' 3"

Total Rig Time hrs.

Ground Level

Total Standby hrs.

Top Of Casing

Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....