



FIELD REPORT

Midnight Sun Drilling Co. Ltd.
 #13 MacDonald Road
 WHITEHORSE, Y.T. Y1A 4L1
 Phone (403) 633-3070

Started.... OCT 27 19. 97

Completed... OCT 30 19. 97

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	WATER WELL 6"	RADAR APPT. LOBIRD. Alaska Hwy South

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
1)	22'	SAND / GRAVEL	MOVE	OCT 27	8	11	3
2)	305'	BEDROCK	DRILL 0-24'6" O.D. / 24'6" - 58' D.H.		11	6	7
			CREW	OCT 28	7:30	6:30	11
			DRILL (DOWN TIME)		8	9	1
			DRILL 58' - 277' D.H.		9	6	9
			CREW	OCT 29	8	4	8
			DRILL		8:30	3:30	7
			DEVELOPING		10	2.	4
			CREW	OCT 30	8	10	2
			DRILL.		8:30	9:30	1

Size of Casing & Pipe				Remarks:
Size	Type	Size	Type	
5/8				① 6 5/8 O.D. DRUG SHOES CASING SET TO 24' 6"
26'	Inch	Feet	Inch	
				HOLE SOUNDED TO 306' 2" GROUND 307' 2" CASING
				GPM 10
				STATIC LEVEL
				Ground level 82' 6"
				Top of casing 84' 3"
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....
 TITLE.....

CLIENT.....
 TITLE.....