#20411029 3

Field Report

105 D 11

Started. July 11 19 87

Completed. July 13 19 87

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.
PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

[redacted]

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Main Street Minerals	W / W	Mile 910.5 Alaska Hwy Main St Mining ~~MacKay~~ (Maurice)
200-100 Main St.		
Whitehorse Y.T.		Lot 345/3 + 346

FORMATION LOG FROM	TO	FORMATION
0	60'	
0	15	silt
15	19	clay
19	51	Gr. sand Cobbs.
51	145	BR Bay silt
145	165	BR

DESCRIPTION OF WORK

DESCRIPTION OF WORK	DATE	TIME FROM	TO	HOURS
MOVE				
Loading	July 11	8:00	10:00	2
move on set up	"	10:00	11:30	1.5
Broke pin on Pilot bit	"	11:30	5:00	5.5
58 casing				
6" odex shoe				
Fishing for bit	July 12	8:00	11:00	3
move 2 set up	"	11:00	12:00	1
Gr. sand				
sand Cobbs.				
Bay silt				
Loading	July 13	8:00	9:00	1
	"	9:00	10:00	1
Develop &	"	10:00	12:00	2
move off.	"	12:00	1:30	1.5

rd. of Casing & Pipe

Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
165			

Remarks:

1-6" odex shoe. X

5 GPM

Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN..... CLIENT.....

TITLE..... TITLE.....

How Printers