

# 204110299

# Field Report



13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

PHONE (403) 633-3070  
TELEX 036-8496

105D11

Started. July... 28... 1998

Completed. July... 31... 1998



NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
	W/W	Paddle wheel
	94-17-16	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Load	July 28	9:00	12:00	3
			move on set up	"	12:30	2:30	2
0	26	Gr.	sand	"	2:30	6:00	3.5
26	58	Gr.	sand silt caps				
58	60	Till					
60	126	till		July 29	8:00	7:00	11
126	141	silt	clay				
141	166	till					
166	200	Hard	silt clay off cap.				
200	306	Hard	silt clay off cap.	July 30	8:00	6:00	10
306	312	runny	silt				
312	313	BR					
			trip hole, Broke sandline chain	July 31	9:00	12:00	3
313	317	Broken	BR		12:00		
			Develop	"	12:00	4:00	4
			Trip out	"	4:00	5:00	1

crd. of Casing & Pipe				Remarks: 60 GPM 1 - drive shoe
Size	Type	Size	Type	
6				
Feet	Inch	Feet	Inch	
314	6			
Static Level				Total Rig Time hrs.
Ground Level 35'				Total Standby hrs.
Top Of Casing				Drilling Mud sacks

### SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....