



PH: 668-2434

P.O. Box 4391

FIELD REPORT

B-ID 204140016

Started... Mar... 20... 1978.

Completed... Mar... 23... 1978.

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	water well	lot #5 M ^c Pherson Sub-division

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
0'	5'	silt	light brown	20 MARCH	7 ³⁰	12 ⁰⁰	12 H
5'	30'	silt	light grey	LOADING MOVING ETC			
30'	50'	silt	light grey	CLEANING DRILL SITE			
50'	138'	silt	blue grey (light)	12 ⁰⁰	4 ³⁰		
138'	155'	till-sandy		DRILLING LEG T. 161'			
155'	158'	till	light clay (white)	4 ³⁰	6 ³⁰		
158'	180'	rock	green	REAM 7 3/4 TO 113'			
180'	212'	rock	grey	6 ³⁰	7 ³⁰		
212'	240'	rock	grey black	CLEANING UP WATER			
215'		clamp		TRUCK TO SHOP			
235'	240'	wet		21 MARCH	8 ⁰⁰	3 ⁰⁰	12
				REAMING TO 161'			
				RUN & WICKED CASING			
				CLEANED HOLE TO 161'			
				WATER & AIR			
				3 ⁰⁰	7 ⁰⁰		
				TO SHOP FOR RODS			
				HAMMER & COMP			

Rcord. of Casing & Pipe			
Size	Type	Size	Type
6"			
Feet	Inch	Feet	Inch
21'	8"		
21'	8"		
21'	8"		
21'	8"		
21'	8"		
21'	8"		
21'	8"		
13'	8"		
161'	8"		

Remarks:		Total Rig Time	46.5	hr
WELL IS MAKING PILING ISLAND		Total Standby		hr
FROM BOTTOM OF CASING		Drilling Mud	4	sack
STATIC LEVEL				
Ground level	147'			
Top of casing	148'			

SIGNATURES

CLIENT... [REDACTED]

TITLE..... Driller