B·ID 2041140154

Field Report

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.

Started Sept 27 19 8

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Completed ..... 19..

(2)

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[redacted]	W/W	Hot Springs Rd
	88-1A-37	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			move 4' set up	sept. 27	5:00	7:00	2
0	160	silt	Broke inner tube	sept 28	8:00	4:00	8
			took hammer to shop	"			
			mounted hammer unable	sept. 29	8:30	7:00	10.5
			to get hammer working				
160	200	silt		"	7:00	8:30	1.5
			broke bottom 20' weld.				
			Trip out pull	sept 30	8:00	10:00	2
			180' casing				

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks: lost
30' casing
1 - shoe.

Static Level		Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN [redacted] ..... CLIENT .....

TITLE ..... [redacted] ..... TITLE .....

[redacted] - 21 hrs

Willow Printers