



13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1
PHONE (403) 633-3070
TELEX 036-8496

Field Report

14

Started Sept 28 1992
Completed Sept 24 1992

204140162

| NAME AND ADDRESS OF CLIENT | DESCRIPTION OF WORK | LOCATION OF WORK |
|----------------------------|---------------------|----------------------|
| [REDACTED] | WATER Well | near 2901500 Highway |
| | 92-10-28 | |

| FORMATION LOG | | | DESCRIPTION OF WORK | TIME | | | |
|---------------|-----|------------|------------------------|---------|-------|-------|-------|
| FROM | TO | FORMATION | | DATE | FROM | TO | HOURS |
| 0 | 20 | Silt | MOVE Loading | Sept 23 | 8:00 | 8:45 | :45 |
| 20 | 23 | till | Loading, haul - Set up | Sept 23 | 8:45 | 12:30 | 2:45 |
| 23 | 285 | B.R. | move on set Phil 0-165 | Sept 23 | 12:30 | 12:30 | 28:54 |
| 0 | 16 | silt | Phil - 165-285 | Sept 24 | 12:30 | 3:30 | 57.5 |
| 16 | 36 | clay | Wash - Develop | Sept 24 | 3:30 | 4:30 | 1 |
| 36 | 37 | clay | Bill - Move on R | Sept 24 | 4:30 | 5:15 | 4.5 |
| 37 | 90 | B.R. | thru - Shop | Sept 24 | 5:15 | 5:30 | :15 |
| 90 | 310 | B.R. | Loading | Sept 9 | 8:00 | 5:30 | 9.5 |
| | | Casing - C | | " | 5:30 | 6:00 | 0.5 |
| 310 | 490 | H.B.R. BR | - 5 1/8 | Sept 10 | 8:00 | 6:30 | 10.5 |
| 490 | 502 | B.R. | Loading | Sept 11 | 8:00 | 10:00 | 2 |
| | | | | " | 12:00 | 12:00 | 2 |
| | | | Broke 2 3/8" Pin on | " | 12:00 | 6:30 | 6.5 |
| | | | top of XL-5 hammer | | | | |
| | | | Fish for hammer | | | | |

| Recd. of Casing & Pipe | | | |
|------------------------|------|------|------|
| Size | Type | Size | Type |
| 6 | 200 | 6 | 200 |
| Feet | Inch | Feet | Inch |
| 246 | | | |

Remarks: - aphot - 1/2 G.P.M.
5 1/8" φ Hole in BEDROCK
11 6 3/8" Drive SHOU

| | | |
|---------------|----------------|------------|
| Static Level | Total Rig Time | 19:15 hrs. |
| Ground Level | Total Standby | hrs. |
| Top of Casing | Drilling Mud | sacks |

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....