



Field Report

204140164

(other half is on same sheet as Bill [unclear])

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started Sept. 8 1992

Completed Sept. 14 1992

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W / W	mi. 928 Alaska Hwy
	92-1A-28	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Fix DMH Trip in	Sept. 13	11:00	6:30	7.5
502	530	BR.	Develop.	"	6:30	7:00	0.5
			Fix Injection Pump	Sept. 14	8:00	10:00	2.
			Develop	"	10:00	12:00	2.
			Trip out move off	"	12:00	4:00	4.
			To shop				

Rcd. of Casing & Pipe			
Size	Type	Size	Type
6.			
Feet	Inch	Feet	Inch
44			

Remarks: 2 BPM.
1- olex shoe.

Static Level	Total Rig Time	hrs.
Ground Level 26'	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....