



Field Report

204140177

PH. 633-8070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Started... April 27... 1989

Completed..... 19.....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	Water Well	Yukon River (Beside Log Cabin Barrens)

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
0	21'	Sand	MOVE Load.	27	8:30	9:00	
21	63'	Silt	Travel to site		9:00	9:30	
63'	210	Clay	Unload. walk to Hole #1		9:30	10:00	
208'	215	Gravel	Drill test hole 0-50'		10:00	11:00	
215	220	Sand	Change to dex. Move		11:00	12:00	
			Drill 0-40'		12:00	1:30	
			Load. Shop	29	8:00	8:30	
			Travel		8:30	9:00	
			Drill 40-162'		9:00	7:00	
			Travel		7:00	7:30	
			Load.	30	8:00	8:30	
			Travel		8:30	9:00	
			Pull Rods check Hammer		9:00	10:00	
			Return to Shop For dex Bits		10:00	12:00	
			Drill 162' - 220'		12:00	16:00	
			Travel to Set Screens		16:00	20:00	
			Travel		20:00	20:30	

Rcrod. of Casing & Pipe			
Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks: Lost 1 new Reamer Bit, 1 Used Pilot
Used 222' casing
Lost 2 Screens - 2 k Packets
2 Bottoms & 1 Riser Pipe
1 dex casing shoe

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....