Field Report

2041140181

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Started..MAY 9.....19 81.

Completed.....19....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[redacted]	W/W	MAYO Rd

FORMATION LOG FROM	TO	FORMATION
0'	26'	Fine silty sand
26'	29'	Fine SAND
29'	60'	Fine silty SAND
60'	62'	Blue Clay
62'	73'	Till
73'	85	Bedrock

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE TRAVEL TO SITE	9	1:15	1:30	
MOVED SET UP	9	1:30	2:30	
		2:30	6:00	
FLUSH HOLE PULLOUT LOAD	9	6:00	6:15	
TRAVEL TO SHOP	11	6:15	7:00	

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....

Willow Printers