MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.

PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Field Report

204140183

Started..Apr..30.....19.85

Completed..May..10...19.85

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[redacted]	W / W	Maya Rd.

FORMATION LOG FROM	TO	FORMATION
0'	88'	sandy silt clay.
88'	102'	Till
102'	215'	BR.
215'	375'	BR.
375'	455'	BR.
455'	540'	BR.
540'	620'	BR.
620'	682'	BR Green
682'	685'	BR Grey
685'	745'	BR Grey

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE Loading	Apr. 30	8:00	12:30	4.5
move on set up.	"	1:00	1:30	0.5
	May 1	8:00	3:00	7
	May 2	8:00	4:00	8
	May 3	8:00	3:00	7
repair Hyd. Hose.	"	3:00	5:00	2
	May 4	8:00	7:00	11
	May 6	8:00	6:00	10
trip out prospected hole	May 7	8:00	5:00	9
load. trip in	May 8	8:00	1:30	6.5
	"	1:30	7:00	5.5
	May 9	7:30	8:30	11
Doveloxo	May 10	8:00	10:30	2.5
trip out move off	"	10:30	2:00	3.5

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch
11.5'			

Remarks:

1 - drive shoe.
1 - 5" hammer bit
1 GPM.

Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....

Willow Printers