Field Report

204140201

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Started...July 9.....19.86

Completed...July 11.....19.86

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[redacted]	TEST HOLE FOR W/W	Mile 10.5 HOT SPRINGS RD

FORMATION LOG FROM	TO	FORMATION
0	5'	silty clay
5'	143'	CLAY
143'	201	
201'	216'	Till
216	278'	
278	3.00	

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE LOAD	JULY 9	9:00	12:00	
LOAD	JULY 10	1:00	4:00	
Move to site - SET UP	JULY 11	8:00	10:30	
Mix MUD - RUN 32' casing	"	10:30	2:30	
grey (HARD)				
Silty CLAY - SOME SAND (grey)	"	2:30	8:30	
CLAY - SOME gravel "				
Silty clay (SOFTER) "				
Silty clay - (HARDER) "				
PACKUP - TRAVEL TO SHOP	"	8:30	9:30	

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....[redacted].....

TITLE.....[redacted].....

CLIENT.....

TITLE.....

Willow Printers