



Field Report

204140210

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started... Oct 1 1987
Completed... Oct 6 1987

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	Water well	Point of Check
46 Jarama Road 22 222 MACDONALD ROAD		

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
0	145'	Sand - Gravel	MOVE	Oct 1	13:30	14:00	
145	258'	Grey Limestone	Drill - 100'		14:00	17:00	
258	320'	Black Limestone	Drill 100 - 148'	Oct 2	8:00	10:30	
			Pull Rods		10:30	11:00	
			Get Sub For Hammer		11:00	13:00	
			Drill 148' - 190' 5 1/2"		13:00	17:00	
			Pull out		17:00	17:30	
			Move to Shop		17:30	18:00	
			Move Back on Hole	Oct 5	12:30	13:00	
			thru in.		13:00	13:30	
			Drill 140' - 230'		13:30	17:00	
			Drill 230' - 320'	Oct 6	8:00	15:30	
			Drill off		15:30	16:30	
			Pull Rods - Load up.		16:30	17:30	
			Move - Shop		17:30	18:00	

Rcd. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
6"				20 GPM. Flow 313'		
Feet	Inch	Feet	Inch			
148'						
				Static Level	Total Rig Time	hrs.
				Ground Level	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN. [REDACTED]
TITLE.....

CLIENT.....
TITLE.....