

DRILLER [REDACTED]

DATE AUG 3RD 2005

OVERBURDEN TYPE

LOT # 1223
PLAN 91-26 HOT SPRINGS ROAD.

FROM	TO	
<u>0</u>	<u>12</u>	<u>SAND CLAY ROCKS</u>
<u>12</u>	<u>33</u>	<u>BROKEN CRUSHED ROCK.</u>
<u>33</u>	<u>205</u>	<u>BED ROCK.</u>
_____	_____	_____
_____	_____	_____

BEDROCK

ELEVATION 2320 G.P.S. READING
N 60° 52.540 UNCORRECTED
135° 21.158

FROM 33 TO 205

10 INCH GROUT SEAL WITH BENTONITE CHIPS

TOTAL HOLE DEPTH ----- FEET 205
STEEL CASING DEPTH ----- FEET 45
P.V.C. CASING DEPTH ----- FEET _____
TOP OF SCREEN ----- FEET _____
DEPTH OF AQUIFER ----- FEET 191
STANDING WATER LEVEL ----- FEET 91
APPROXIMATE FLOW RATE ---- G.P.M. 6 TO 7

SIZE 6 INCH
SIZE _____ INCH

COMMENTS:

BED ROCK BADLY BROKEN - HAD TO RUN CASING TO 45 FT. - PRESSURE SYSTEM INSTALLED WATER SAMPLES TAKEN - WELL DISINFECTED.