#204140363

Field Report

105 D 14

[redacted]

Started Nov. 16 19 84

Completed Nov. 16 19 84

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[redacted]	W/W	Takhini River Bridge Mayo Rd.

FORMATION LOG FROM	TO	FORMATION
0'	10'	fine sand Gr.
10'	39'	silt Clay.
39'	55'	silt sand Gr.
55'	59'	Gr. Sand.

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE				
move on set up	Nov. 16	7:00	8:00	1
"	"	8:00	10:00	2.
set screen	"	10:00	10:30	0.5
Develop	"	10:30	12:30	2.
set pump	"	12:30	2:30	2.
move off to shop	"	2:30	3:30	1

Rcrd. of Casing & Pipe Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
55'			

Remarks:

1- drive shoe.
15 s/o+ screen Bottom 59'
2' riser load Packer
20 GPM.

Static Level		Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing	12'	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....

Willow Printers