



P.O. Box 4391

FIELD REPORT

204140364

105 014



204140364

Started. May. 20... 1979

Completed. May. 22... 1979



NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[Redacted] Box 4574 Whitehorse	W / W	mi. 4, Mayo Hwy.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Loading	May 20	8:00	9:00	1
			moving on setting up	"	9:00	10:00	1
0	18'	sand silty sand layers		"	10:00	6:30	8.5
18'	23'	sand					
23'	25'	silt					
25'	51 1/2'	clay					
51 1/2'	52'	Gravel					
52'	115'	bedrock					
115'	268'	bedrock		May 21	8:00	8:00	12.
			Loading (shops)	May 22	6:00	7:00	1
268'	300'			"	7:00	9:30	2.5
			Developing	"	9:30	10:30	1
			moving off	"	10:30	11:30	1

Rcd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	water at 235'
21				Developed at 5 gals / mi.
20				
12	2			

STATIC LEVEL	Total Rig Time	28	hrs.
Ground level	Total Standby		hrs.
Top of casing 108' rising	Drilling Mud		sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....